

Our Ref: SLT3986M

Your Ref: YQ5035G

S/NO	QTY	DESCRIPTIONS	ASSESSED CONDITION	EST. BY WORKSHOP
<u>PARTS REPLACEMENT - LIST ITEMS</u>				
1	1	REAR BUMPER <i>repair</i>		\$ 1,260.66 <i>XR</i>
2	1	REAR BUMPER SIDE RETAINER RH <i>Xnn</i>		\$ 196.26 <i>X</i>
3	1	REAR TAILLAMP RH <i>cm</i>		\$ 458.40
4	1	REAR FENDER RH <i>bt</i>		\$ 1,795.26
5	1	REAR FENDER GLASS RH <i>3 sec / photo</i>		\$ 366.72 <i>X</i>
6	1	REAR FENDER GLASS MOULDING RH		\$ W/GLASS
7	1	REAR TAILGATE SPOILER <i>Xnn</i>		\$ 908.88 <i>X</i>
8	1	REAR TAILGATE TRIM RH <i>Xnn</i>		\$ 83.22 <i>X</i>
9	1	FUEL FILLER FLAP <i>repair</i>		\$ 82.42 <i>XR</i>
10	1	REAR DOOR RH <i>Xnn</i>		\$ 1,391.70 <i>X</i>
11	1	REAR DOOR REAR WINDOW FRAME TRIM RH <i>Xnn</i>		\$ 167.58 <i>X</i>
			SUB TOTAL	\$ 6,711.10
			LESS 5%	\$ 335.56
			TOTAL AMOUNT	\$ 6,375.55

Our Ref: SLT3986M

Your Ref: YQ5035G

S/NO	QTY	SPECIAL NETT ITEMS	ASSESSED CONDITION	EST. BY WORKSHOP
1	1	REAR BUMPER CLIPS <i>Xnn</i>		\$ 50.00 <i>X</i>
1	1	REAR FENDER GLASS SEALANT <i>Xnn</i>		\$ 60.00 <i>X</i>
			SUB TOTAL	\$ 110.00
			TOTAL PARTS COST	\$ 6,485.55

Our Ref: SLT3986M

Your Ref: YQ5035G

S/NO	DESCRIPTION	EST. BY WORKSHOP
LABOUR & PAINTWORK		
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS	\$ 800.00 500
2	TO REMOVE & REFIT WIRING SYSTEM AT ACCIDENT AND CHECK FOR PROPER FUNCTIONS	\$ 100.00 30
4	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED	\$ <u>1010</u> 800.00 400
5	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	\$ 50.00 30
6	SUNDRIES (SAND PAPER, WELDING WIRE ETC.)	\$ 50.00 20
7	TO VACUUM, WAXING & CLEAN	\$ 60.00 Xnn
8	TO PERFORM WATER SEEPAGE TEST ON REPAIRED PORTIONS	\$ 50.00 30
TOTAL BEFORE GST		\$ 8,395.55
GST 7%		\$ 587.69
TOTAL (PARTS & LABOUR):		\$ 8,983.23

Adjustments / Recommendations

Our estimator have thoroughly inspected each and every item on the estimate against physical damage found on the vehicle and have listed the breakdown of our finding and recommendation.

Our Workshop has agreed to undertake the job at a sum of \$ 8,900.00 for lump sum with the third party insurance.

Yours Faithfully,

Jason Heng
Claims Director

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Same

Up 900 100 68

5 days

4/8

12/07/22 @ 1700

Reg after repair

2140.97

1010.00

3150.97

20%

2520.78

4/8 - \$2,500/5 days