

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 12/7/2022

To : LKK

Attn :

Tel :

*Not Withheld
11 Days @ 400h
Recovery After Paving
4 days*

By Fax:

VEHICLE NO : JPE 9263

Yamaha 135 LC

ACCIDENT DATE: 30/6/2022

Description	Qty	Quotation \$
1 Handle Bar <i>Sn</i>	1	95.00 X
2 Brake Lever <i>Pex</i>	1	75.00 X
3 Mirror <i>nd</i>	1 Set	120.00 ✓
4 Headlamp <i>Gr</i>	1	280.00 ✓
5 Headlamp Cover <i>nd/cm</i>	1	150.00 ✓
6 Head Cover Panel <i>?</i>	1 <i>Sn</i>	120.00 X
7 Inner Panel <i>cm</i>	1	115.00
8 Signal RH <i>?</i>	1 <i>Sn</i>	75.00 X
9 Fork Tube <i>?</i>	1 <i>Sn</i>	480.00 X
10 Fork Oil Seal <i>?</i>	1 <i>Sn</i>	125.00 X
11 Fork Under Bracket <i>?</i>	1 <i>Sn</i>	210.00 X
12 Front Mudguard <i>cm</i>	1	135.00 ✓
13 Front Rim <i>1 RX</i>	1	250.00 X
14 Front Side Fairing L/RH <i>Br/cm</i>	1	250.00 ✓
15 Radiator <i>nd/Pn</i>	1	280.00 ✓
16 Radiator Cap <i>1 Sn X</i>	1	120.00 X
17 Centre Leg Shield <i>MIT</i>	1	110.00 ✓
18 Engine Lower Cover <i>cm</i>	1	135.00 ✓
19 Rear RH Panel <i>Sn X</i>	1	125.00 X
20 Foot Rest <i>At</i>	1	90.00 ✓
21 Foot Rest Rubber <i>cm</i>	1 Set	55.00 ✓
22 Pillion Bar <i>R X</i>	1	90.00 X
23 Box Rack <i>nd/R X</i>	1	110.00 X
24 Radiator Fan Motor <i>Sn X</i>	1	260.00 X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Sub-Total	0.00	\$3,855.00
Less 10%	0.00	\$ 385.50
Sub-Total	0.00	\$3,469.50

Total

VEHICLE NO : ~~JSQ 2784~~
JPE 9263

Yamaha 135 LC

Nett items

1	Towing fees	40.00	301
2		250.00	1001
	Remove & replace parts, align & etc		
3	Remove & replace Fork Tube & Top Up Fork Oil	120.00	801
4	Supply Body Decal Sticker NEC	80.00	601
5	IU Unit <i>SW X</i>		
6	Rear Box <i>104/61</i>		
7	Number Plate (Sticker) <i>MC</i> <i>PM</i> 1 Set		

Sub-Total 490.00

Nett Total 490.00

Grand Total \$ 3,959.00

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion
Thank you

SG 98 MOTOR PTE LTD

LKK Auto Consultants hence notify
the Repaire of the following:
• To resurvey before after spray painting
• To display damaged parts (if any) resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modifications is allowed
• Supplementary items must be approved and
is subject to final approval from Insurance Company
Acknowledged by: _____
Signature: _____
Date: _____