



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. JPE 9263

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	HANDLE BAR	SERVICEABLE	95.00	-
1	BRAKE LEVER	SERVICEABLE	75.00	-
1	SET MIRROR	DENTED	120.00	120.00
1	HEADLAMP	CUT	280.00	280.00
1	HEADLAMP COVER	DENTED / CRACKED	150.00	150.00
1	HEAD COVER PANEL	SERVICEABLE	120.00	-
1	INNER PANEL	CRACKED	115.00	115.00
1	SIGNAL RH	SERVICEABLE	75.00	-
1	FORK TUBE	SERVICEABLE	480.00	-
1	FORK OIL SEAL	SERVICEABLE	125.00	-
1	FORK UNDER BRACKET	SERVICEABLE	210.00	-
1	FRONT MUDGUARD	CRACKED	135.00	135.00
1	FRONT RIM	TO REPAIR SEE LABOUR	250.00	-
1	FRONT SIDE FAIRING L/RH	BROKEN / CRACKED	250.00	250.00
1	RADIATOR	DENTED / PUNCTURE	280.00	280.00
1	RADIATOR CAP	SERVICEABLE	120.00	-
1	CENTRE LEG SHIELD	MISSING	110.00	110.00
1	ENGINE LOWER COVER	CRACKED	135.00	135.00
1	REAR RH PANEL	SERVICEABLE	125.00	-
1	FOOT REST	BENT	90.00	90.00
1	SET FOOT REST RUBBER	CRACKED	55.00	55.00
1	PILLION BAR	TO REPAIR SEE LABOUR	90.00	-
1	BOX RACK	TO REPAIR SEE LABOUR	110.00	-
1	RADIATOR FAN MOTOR	SERVICEABLE	260.00	-
	LESS 10% DISCOUNT		-385.50	-172.00
			3,469.50	1,548.00

Report Ref No. CS/SMO22006600/Kcy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
	BODY DECAL STICKER (SN)	NECESSARY	80.00	60.00
1	IU UNIT (SN) (NPA)	SERVICEABLE	-	-
1	REAR BOX (SN) (NPA)	DENTED / CUT	-	-
1	SET NUMBER PLATE (STICKER) (SN) (NPA)	FRT NECESSARY	-	-
			80.00	60.00
	<u>LABOUR</u>			
	TOWING FEES.		40.00	30.00
	REMOVE & REPLACE PARTS, ALIGN & ETC. INCLUSIVE OF THE REPAIR OF FRONT RIM, PILLION BAR AND BOX RACK.		250.00	100.00
	REMOVE & REPLACE FORK TUBE & TOP UP FORK OIL.		120.00	80.00
			410.00	210.00
	GRAND TOTAL		3,959.50	1,818.00

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			400.00
---	--	--	---------------

Report Ref No. CS/SMO22006600/Kcy3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.