



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22006600/Kcy3e2	
			Date: 26/09/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLB 7864A	Veh. Inspected	JPE 9263
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2202288/SYH	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	12/07/2022
2. Vehicle Particulars & Condition				
	Make & Model	YAMAHA 135LC	c.c	135
	Engine No.	HIDDEN	Year of Reg.	2013
	Chassis No.	PMYKG0540D0095524	Colour	ORANGE / BLACK
	Odometer	11339 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	70/90 R17	DIAMONDS	3 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	80/90 R17	METZELER	5 mm
	L/H Rear Tyre			mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S AND O/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	30/06/2022	Inspection Date	13/07/2022
	Survey held at	SG 98 MOTOR PTE LTD BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	