



南方摩哆

Southern Motor

Business Reg. No: 234147/00L

Block 1006, Bukit Merah Lane 2, #01-10, Singapore 159762

Tel: 6273-0369 (3 Lines) Fax: 6274-6614

06 July 2022

EQ Insurance Company Ltd
5 Maxwell Road #17-00 Tower Block
MND Complex
SINGAPORE (069110)

Dear Sirs,

RE: Cost of repair to Yamaha Sniper T150 - FBL8706H

1pc of Body Set / OR
1pc of Handle Bar / BT
1pc of Clutch Lever / BT
1pc of Handle Balancer / CV
1pc of Mirror / CV
1pc of Side Stand / BT
1pc of Rear Kappa Box / CV

SS

480.00 350 /

75.00 /

25.00 /

20.00 /

55.00 /

35.00 /

190.00 /

880.00 750

88.00 -10%

792.00 675

Less 10%

Nett

40.00 /

Transport

85.00 /

Alignment Fork

7.45 X

LTA Fees

150.00 /

Labuor

\$1,074.45 275

= 950

L/S - 760

= 750

Yours Faithfully,
Southern Motor



Store (LKK)
13/7/22, 10am

W R
L/S
by A y
3 45

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: