

2 Kaki Bukit Ave 2, #02 19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

JHHUCV 3F20K038546.

ESTIMATE OF REPAIR

Veh# : YQ3787H

Accident Date : 11/7/2022

Location : 78 TAGORE LANE

TP AIG
Xiao Tong

Model:

HINO XZU710R
1-Jun-22

3P:

GBD2866K (AIG)

S/Nos	Qty	Description	List \$	S/Nett \$	Nett \$
1	1pc	Front bumper Bent	2280.20	967	
2	1pcs	Front bumper o/s & bracket Bent	450.00	285	
3	1 pc	Front grille 3rd	1,098.20	+	
4	8 pcs	Front grille clips 3rd		80.00	+
5	1 pcs	Front o/s head lamp (with motor) Bent	1,780.20	✓ 1086	1086.00
6	1 pcs	Front o/s head lamp lower seal New	168.20	+	
7	1 pc	Front HINO emblem New	102.21	+	
8	1 pc	Front o/s fog lamp (LED) CRA		800.00	380
9	1 pc	Front o/s fog lamp bracket Cracked		100.00	✓
		2338 Sub Total:	5,879.01	980.00	0.00
		15%		0%	0%
		2104.20 After Less %:	4,997.16	980.00	0.00
		Labour			
1		To repair front portion		800.00	300
2		To spray painting front portion		600.00	250
3		To check for fault code and restting		280.00	+
4		To check wiring 580		100.00	30
5		To re seal anti rust		80.00	+
		Sub Total:		1,860.00	
		Total:		7,837.16	

Chan San Choon

Director

DipEng, AAE MIMI,MSAE(Aust)

Adrian L
P/P 13/07/22.
03 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification allowed
- Supplementary items to be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

bizSAFE
STARS

8778 1999
24 hr accident call

Mobil 1



Total: 3064.20
(P/P)