



2 Kaki Bukit Ave 2, #02 19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

Veh# GR777P

Accident Date : 5/7/2022

Location

3P: GBA5474D (CHINA)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Model: NISSAN NP300

Date:

16/1/2017


S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Rear bumper chrome		1500 750	1,570.00
2	1 pc	Rear bumper top garnish		200	351.00
3	1 pc	Rear bumper top garnish rubber		300	428.00
4	2 pcs	Rear bumper bracket			100.00
5	1 pc	Rear bumper step panel			410.20
6	1 pc	Rear tail gate			1,370.00
7	1 pc	Rear tail gate 70 kmph emblem		15.00	
8	1 pc	Rear tail gate NISSAN emblem		68.00	
9	1 pc	Rear reg. no. plate bracket		45.00	
10	1 pc	Rear reg. no. plate		25.00	
		Sub Total:	0.00	153.00	4,229.20
			30%	0%	10%
		After Less %:	0.00	153.00	3806.28
		Labour			
1		To dismantle, welding, knocking and replace rear damage parts		800.00	
2		To spray painting.		800.00	
3		To re seal anti rust		50.00	
4		To check wiring.		50.00	
		Sub Total:		1,700.00	
		Total:		5659.28	
		After Less 20%:		4527.42	

Chan San Choon
Director
DipEng, AAE, MIMI, MSAE(Aust)

Thuvan
82235769
12/7/22
1645 US 4 days w/p



F: 2650
RD: 4



AL 8778 1999
24 hr accident call

