

(08/11/13) wef
ASS. REC. BY: ASME

REF: CS/ASM 22006614/Rcy³

7660

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: ABG 813K
at Workshop m/s YIN YUN SHU
of 8, KKKI PARK MK4 #05-12
Insured: ASM
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: 48K
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 12 days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: ABG 813K Yr Regn: 2017 / MAY
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

Make: NISSAN NV350 2.5 SM c.c 2488
Colour: BLACK A/C: Insured / Std / NI / NA
Sp. Reading: 142328 T/Radio: Insured / Std / NI / NA

Eng/No: _____
C/No: IN1MC 2E 262000787

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt or

Brake: Order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 155R15C
R: 22

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front		Rear	
R/Bal. <u>6</u>	mm	R/Bal. <u>6</u>	mm
L/Bal. <u>6</u>	mm	L/Bal. <u>6</u>	mm
D.O.A. <u>01/07/22</u>		D.O.I. <u>13/07/22</u>	

Survey held at YIN YUN SHU
Des. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 33K

2/3/23 Finalised LS \$11,900f ; 12 days with Yi Xin. (Red \$18,034.20, 60%)

Date/Time, File Pass to?

☐ : Prel. Report
☒ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 12

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS SI

Photos

Others

Report Format: TP

Lump Sum / I.B.I: (\$ 11,900f)

ASM /
Celine.

Survey by Rasul on 13/7/2022



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

GBG813K Nissan Nv350

JN 1MC 2E 26 Z 0007877

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear bumper assy	\$ 850.00 DD 687.20
2	1	Rear bumper left bracket	\$ 98.00 X NS
3	1	Rear bumper right bracket	\$ 98.00 X NS
4	1	Rear bumper left retainer	\$ 85.00 CRA
5	1	Rear bumper right retainer	\$ 85.00 CRA
6	1	Rear reflector	\$ 95.00 X NS
7	1	Rear reflector	\$ 95.00 X NS
8	1	Rear bumper tow cover	\$ 78.00 X NS
9	1	Reinforcement	\$ 280.00 BT
10	1	Rear Tailgate	\$ 1,800.00 BUC
11	1	Rear tailgate rubber garnish	\$ 372.20 269
12	1	Tailgate internal trim cover	\$ 385.00 DIS
13	1	Tailgate logo nissan	\$ 95.00 NEC
14	1	Tailgate holder / pull pocket brake lamp	\$ 180 95.00 CRA
15	1	Rear tailgate emblem /model	\$ 105.00 BT 90
16	1	Rear tailgate lock mechanism	\$ 280.00 BT
17	1	Rear boot lock holder	\$ 95.00 X NS
18	1	Rear end top cover garnish	\$ 275.00 X NS
19	1	Antena, electrical key	\$ 88.00 X NS
20	2	Rear tailgate no plate lamp	\$ 160.00 CRA
21	1	Rear left taillamp	\$ 550.00 CRA 287
22	1	Rear right taillamp	\$ 550.00 CRA 287
23	1	Rear left corner light	\$ 250.00 X NS
24	1	Rear right corner light	\$ 150.00 X NS
25	1	Rear end lower tray	\$ 150.00 X R
26	1	Rear exhaust	\$ 650.00 X R
27	1	Rear end panel	\$ 900.00 BUC 500
28	1	Rear step	\$ 380.00 DIS 293
29	1	Rear windscreen	\$ 1,200.00 CRA 954
30	1	Rear windscreen seals	\$ 150.00 NEC 50
31	1	Rear top mirror	\$ 330.00 BR 295
32	1	Rear wiper arm and wiper	\$ 180.00 BT 103
33	1	Rear wiper motor	\$ 380.00 BT
34	2	Rear fender inner trim cover both side	\$ 800.00 X BT 400
35	1	Rear wheel arch housing trim-left	\$ 250.00 X NS
36	1	Rear fender window wooden board cover	\$ 400.00 X NS
37	1	Rear left fender outer layer	\$ 650.00
38	1	Rear left fender middle layer	\$ 500.00
39	1	Rear left fender inner layer	\$ 550.00
40	1	Rear roof	\$ 2,500.00 X R
41	1	Rear roof top inner cover trim	\$ 800.00 X SIC
42	2	Rear tailgate absorber	\$ 300.00 BT
Sub-total Parts			\$ 18,084.20

Tailgate outer chrome garnish CRA

\$355



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

GBG813K Nissan Nv350

No	Qty	Parts Description	Estimated Parts Price
<u>Special Nett Items</u>			
1	10	Rear bumper clips	\$ 80.00 30 NEC
2	6	Rear end lower panel top garnish clips	\$ 50.00 XNS
3	1	Rear end lower panel sealant	\$ 120.00 NEC 40
4	8	Rear tailgate inner trim board clips	\$ 50.00 NEC 20
5	6	Rear tailgate outer garnish clips	\$ 50.00 NEC 15
6	1	Rear floor panel sealant	\$ 120.00 XNN
7	1	Rear windscreen glass sealant	\$ 80.00 NEC 50
8	1	Rear end sealant	\$ 320.00 X Rpt.
9	1	Rear no plate with garnish	\$ 80.00 BT 35
10	1	Both fender and rear body advertising full stickers	\$ 1,500.00 NEC / DIS 1,200
11	1	Rear bumper reverse sensor rear set	\$ 400.00 short 200
12	1	Rear camera	\$ 450.00 XNF
13	1	Rear roof top trim clips	\$ 80.00 XNS
Sub-total special nett			<u>\$ 3,380.00</u>
Tailgate '70km/h' & '8pax' sticker NEC			\$30



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

GBG813K Nissan Nv350

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten rear affected area and replace rear damaged parts, main body frame rear end and rear left body frame damaged	\$ 3,000.00 2000
2	To putty and spray painting rear portion, boot inside out, bumper, rear left fender, main frame metal, rear end panel, gutter side panel for left and right, roof top -rear left	\$ 2,500.00 1,500
3	To check rear lighting and wiring.	\$ 60.00 30
4	To remove and install rear tailgate lock mechanism.	\$ 80.00 50
5	To remove & install rear windscreen glass for the repair.	\$ 150.00 120
6	To apply anti rust proofing to rear affected area including behind spare tyre area	\$ 250.00 120
7	To remove and install rear bumper reverse sensor.	\$ 80.00 50
8	To remove and install rear exhaust muffler assy.	\$ 250.00 X
9	To remove and rear tailgate and fender interal internal trims to facilitate the repair	\$ 80.00 50
10	To remove and install rear camera to facilitate the repair	\$ 80.00 X
11	Remove body stickers for both fender and trailgate	\$ 150.00 X Rpt.
12	Rear end replacement / water test is necessary for leaking	\$ 120.00 X
13	Remove rear seats to facilitate the rear end /floor panel body repair	\$ 150.00 X
14	Remove and replace ear roof top handle bar	\$ 200.00 X
15	Remove and put back roof top airbags, inner trim cover	\$ 500.00 X
16	Accident programming /remove fault code	\$ 350.00 X

Total labour : \$ 8,000.00

Total = 14,892.08
- 20% 2,978.42

11,913.66

10 Days

LS \$ 11,900

29,934.20