

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422/ 6745 4422 Fax : 6747- 6720 REG NO 200501102H

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 Anson Road #16-00
 Springleaf Tower
 Singapore 079909
 Tel : 6389 - 6111
 Fax : 6224 - 7478 / 7175

Online

Quotation
 DATE : 13.07.2022
 VEH NO : SLJ1942E
 MODEL : Kia Korte K3
 D O A : 12.07.2022
 YR REF : SFX9D

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SLJ1942E (KIA FORTE K3)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO LIST ITEMS - FRONT			
1	Front Number Plate Garnish <i>Deformed</i>	1	101.60 ✓
2	Front Bumper <i>Deformed</i>	1	658.40 ✓
3	Front Bumper Side Holder - LH & RH <i>new</i>	2	76.80 ✓
4	Front Bumper Lower Grille <i>new</i>	1	169.50 x.
5	Front Bumper Fog Lamp - LH & RH <i>new</i>	2	528.20 x.
6	Front Bumper Fog Lamp Cover - LH & RH <i>hit cut</i>	2	124.80 624.00
7	Front Bumper Tow Cover <i>new</i>	1	34.10x
8	Front Bumper Reinforcement <i>Deformed</i>	1	354.90 ✓
9	Front Bumper Sponge <i>Cracked</i>	1	141.80 ✓
10	Front Bumper Logo <i>new</i>	1	65.90 ✓
11	Front Bumper Lower Beam <i>new</i>	1	138.60 x.
12	Front Bumper Sensor <i>2 pieces damaged</i>	4	1,020.00 510.
13	Front Bumper Sensor Wire Harness <i>new</i>	1	348.40 x
14	Front Bumper Sensor Holder <i>new</i>	4	100.40 ✓
15	Head Lamp - LH & RH <i>Cracked</i>	2	4,215.40 ✓
16	Front Support Panel <i>Cracked</i>	1	798.50 ✓
17	Front Support Panel Top Garnish <i>Deformed</i>	1	165.90 ✓
18	Bonnet <i>Reps</i>	1	877.80 x.
19	Bonnet Lock <i>new</i>	1	68.90 x
20	Air Con Condenser <i>new</i>	1	820.40 x.
21	Air Con Condenser Side Guide <i>RH Deformed</i>	2	70.80 35.40
22	Front Grille <i>crack</i>	1	328.00 ✓
23	Front Grille Chrome Moulding <i>new</i>	1	136.00 ✓
NO LIST ITEMS - REAR			
24	Rear Number Plate Lamp - LH & RH <i>new</i>	2	110.20 x
25	Rear Bumper <i>Distorted</i>	1	688.90 ✓

7751.40

6976.26

RE : ESTIMATE FOR ACCIDENT REPAIR SLJ1942E (KIA FORTE K3)

26	Rear Bumper Side Holder - LH & RH	Dmgd.	2	768.00	✓
27	Rear Bumper Lower Garnish	Distorted	1	298.40	✓
28	Rear Bumper Lower Garnish Reflector - LH & RH	cracked	2	171.80	✓
29	Rear Bumper Reinforcement	Distorted	1	385.60	✓
30	Rear Bumper Reinforcement Stay - LH & RH	Dented.	2	190.20	✓
31	Rear Bumper Reinforcement Bracket	Damaged	5	92.50	✓
32	Rear Bumper Reinforcement Antenna Sensor	Dmgd	1	185.40	✓
33	Rear Bumper Undercover - LH	Deformed	1	112.20	✓
34	Reverse Sensor	Damaged	4	1,001.60	✓
35	Reverse Sensor Wire Harness	are new	1	349.40	+
36	Reverse Sensor Holder	new	4	105.60	✓
37	Rear End Panel	Distorted.	1	480.50	✓
38	Rear End Panel Top Garnish	deformed	1	153.90	✓
39	Bootlid	Distorted	1	894.50	✓
40	Bootlid Lock	Dmgd	1	165.90	✓
41	Bootlid Weatherstripe	cut	1	178.50	✓
42	Bootlid Hinge	Best	2	156.20	✓
43	Bootlid Top Spoiler	cracked	1	585.10	✓
44	Bootlid Inner Trimboard	torn	1	189.40	✓
45	Bootlid Lamp - LH & RH	cracked	2	1,392.20	✓
46	Kia Logo	3 new	1	52.40	✓
47	Cerato Wording		1	49.50	✓
48	Tail Lamp - LH & RH	cracked	2	1,584.20	✓
49	Tail Lamp Panel - LH & RH	Dented	2	454.80	✓
50	Rear Fender Inner Trimboard - LH & RH	deformed	2	516.40	✓
51	Spare Tyre Panel	Distorted	1	866.90	✓
52	Spare Tyre Panel Top Cover	torn	1	190.50	✓
53	Spare Tyre Nut Screw	Damaged	1	45.80	✓
54	Rear Exhaust Pipe	rust	1	757.80	+
55	Rear Exhaust Pipe Mounting	3 new	1	36.90	f
56	Rear Exhaust Pipe Gasket		1	34.10	f.
57	Rear Exhaust Pipe Heat Shield	crumpled	1	89.40	✓

12804.10
11523.69

Less 10%

\$	24,679.80
	(2,467.98)
\$	22,211.82

S/NETT ITEMS - FRONT

1	Front Number Plate	Best	1	30.00	✓
2	Front Number Plate Holder	deformed	1	30.00	✓
3	Front Bumper Clips	new	1 set	30.00	✓
4	Front Support Panel Top Garnish Clips	new	1 set	20.00	✓
5	Air Con Condenser Side Guide Clips	new	1 set	20.00	✓
6	Coolant	new	1	50.00	✓
7	Front Grille Clips	new	1 set	20.00	✓

200

S/NETT ITEMS - REAR

RE : ESTIMATE FOR ACCIDENT REPAIR SLJ1942E (KIA FORTE K3)

8	Rear Number Plate	<i>Deleted</i>	1	30.00	✓
9	Rear Number Plate Holder	<i>del</i>	1	30.00	✓
10	Rear Bumper Clips	<i>nu</i>	1 set	30.00	✓
11	Rear Bumper Undecover Clips	<i>nu</i>	1 set	20.00	✓
12	Rear End Panel Top Garnish Clips	<i>nu</i>	1 set	20.00	✓
13	Rear End Panel Sealant	<i>nu</i>	1	60.00	✓
14	Bootlid Top Spoiler Sealant	<i>nu</i>	1	50.00	✓
15	Bootlid Inner Trimboard Clips	<i>nu</i>	1 set	30.00	✓
16	Rear Camera	<i>del nu</i>	1	500.00	✗
17	Rear Fender Inner Trimboard Clips	<i>nu</i>	1 set	60.00	✓
18	Spare Tyre Panel Insulation Pads	<i>nu</i>	1	280.00	✓ <i>200</i>
19	Spare Tyre Panel Sealant	<i>nu</i>	1	60.00	✓
20	Rear Exhaust Chrome Pipe	<i>Deleted</i>	1	150.00	✓ <i>80</i>
				<hr/>	
				\$ 1,520.00	
Total parts				<hr/>	
				\$ 23,731.82	

670

LABOUR CHARGE

1	To knocking out front portion & renew above parts	\$	1,200.00 <i>700</i>
2	To putty & spray up paint works (front)	\$	800.00 <i>600</i>
3	To check wiring (front)	\$	50.00 <i>30</i>
4	To remove front bumper sensor	\$	100.00 <i>50</i>
5	To remove condenser & top-up aircon gas	\$	120.00 <i>60</i>
6	To remove radiator & top-up coolant	\$	120.00 <i>60</i>
7	To knocking out rear portion & renew above parts	\$	1,500.00 <i>1300</i>
9	To putty & spray up paint works (rear)	\$	1,300.00 <i>1200</i>
9	To check wiring (rear)	\$	50.00 <i>30</i>
10	To spray tuff coat	\$	150.00 <i>100</i>
11	To remove reverse sensor	\$	100.00 <i>50</i>
12	To remove rear camera	\$	100.00 <i>50</i>
13	To remove upholstery	\$	150.00 <i>80</i>
14	To transfer bootlid fittings	\$	150.00 <i>60</i>

RE : ESTIMATE FOR ACCIDENT REPAIR SLJ1942E (KIA FORTE K3)

15	To remove rear exhaust pipe	4510	\$	150.00 80
16	Towing Charges		\$	60.00 ✓
	Total Labour		\$	6,100.00
	Grand Total		\$	29,831.82

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total: 23879.95

L/S: 19.1K.

16 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: