

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Richard Ang Wei Guang

Date: 03 Apr 2023

**Preliminary Advice**

Insured Vehicle No	: SLG5797Y	Accident Date	: 10/07/2022
TP Vehicle No	: SNC8149X	Assignment Date	: 13/07/2022
Make	: TESLA MODEL 3 STANDARD RANGE	Est. Duration of Repair	: 21
Date of Inspection	: 14/7/2022		
Inspection At	: OPTIMA WERKZ PTE LTD		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	36,383.39
Revised Amount	:S\$	26,784.39
Check Items (Estimated)	:S\$	0.00
Total	:S\$	26,784.39

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	206,000.00
COE / PARF Rebate	:S\$	89,800.00
Salvage Value	:S\$	
Margin for Repair	:S\$	116,200.00

**Remarks**

- ( X ) The vehicle is economical for repair  
 ( ) The vehicle is not economical for repair  
 ( X ) Part-by-Part repair  
 ( ) Lump Sum repair

- ( X ) The above survey was conducted on a 'without prejudice' basis.

Please note that the preliminary advise amount (Revised) stated are subject to consistency check, part prices and labour cost .