

ASS. REC. BY:

REF:

MSG/ 2200 6627 HKV

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop m/s

Optimo

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

1.30pm

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

\$206k

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

21 days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SNC 8149X

Yr Regn:

11, 21

Type: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

Tesla Model 3

c.c.

Colour:

Matte Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

19349

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

LRW 3F7FABMC 384728

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

235/40R19

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front

Rear

R/Bal.

8 mm

R/Bal.

8 mm

L/Bal.

8 mm

L/Bal.

8 mm

D.O.A.

10/7/22

D.O.I.

14/7/2022

Survey held at

10.40am

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear n/s & Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

/ Almost all parts have to order from oversea.

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) S + RS. SI

☐

: Interview (\$

) F. & S.

☐

: Tech Invs (\$

) Others

☐

: Weekend (\$

)

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

Date: 12/07/2022

Vehicle No: SNC8149X

Model: TESLA MODEL 3 STANDARD RANGE

Chassis: LRW3F7FA8MC384728-2021

Reg.Year: 2021

Third Party Insurer: MSIG

Third Party Veh No: SLG5797Y

Date of Accident: 10/07/2022

Estimator: TING AN

Surveyor: LKK-Auto Kenneth Kong

*Not within
Recovery B4 paint*

21 days

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$	
1	REAR BOOTLID	1		R \$728.97	X
2	REAR BOOTLID "TESLA" EMBLEM	1		nn \$37.38	X
3	REAR BOOTLID INNER TRIM BOARD	1		nn \$46.73	X
4	REAR BOOTLID LAMP LH	1		nn \$177.57	X
5	REAR BUMPER	1		R \$663.55	—
6	REAR BUMPER SIDE BRACKET LH	1		cm \$7.48	—
7	REAR BUMPER REINFORCEMENT	1		\$271.03	?
8	REAR BUMPER CENTER BRACKET	1		\$52.34	?
9	REAR BUMPER LOWER LIP	1		nn \$140.19	X
10	REAR BUMPER UNDER COVER	1		\$205.61	?
11	REAR BUMPER REFLECTOR LH	1		cm \$20.56	—
12	REAR BUMPER PARKING SENSOR	2	\$158.88	\$317.76	?
13	REAR BUMPER PARKING SENSOR BRACKET	2	\$4.67	\$9.34	?
14	REAR TAIL LAMP LH	1		cm \$280.37	—
15	REAR TAIL LAMP BRACKET LH	1		\$2.80	?
16	REAR CHARGING PORT DOOR LH	1		\$252.34	?
17	REAR END PANEL	1		R \$448.60	X
18	REAR FENDER LH	1		R \$1,345.79	—
19	REAR FENDER QUARTER GLASS LH	1		nn \$280.37	—
20	REAR FENDER AIR VENT LH	1		Di \$14.95	—
21	REAR FENDER INNER SHIELD LH	1		Re form \$116.82	—
22	REAR FENDER INNER PANEL LH	1		\$112.15	?
23	ROCKER PANEL COVER LH	1		Re form \$370.00	—
24	REAR RIM LH	1		Re \$939.00	—
25	REAR ABSORBER LH	1		\$177.57	?
26	REAR ABSORBER SPRING LH	1		\$149.53	?
27	REAR UPPER ARM LH	1		\$224.30	?
28	REAR LOWER ARM LH	1		\$224.30	?
29	REAR CONTROL ARM LH	1		\$224.30	?
30	REAR KNUCKLE ARM LH	1		\$420.56	?
31	REAR WHEEL BEARING HUB LH	1		\$149.53	?
32	FRONT BONNET	1		R \$663.55	—
33	FRONT BONNET HINGE LH	1		\$74.77	?
34	FRONT BONNET HINGE RH	1		\$74.77	?
35	FRONT BONNET STRUT LH	1		nn \$52.34	X
36	FRONT BONNET STRUT RH	1		nn \$52.34	X
37	FRONT BONNET "TESLA" EMBLEM	1		nn \$48.60	—

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 12/07/2022
Vehicle No: SNC8149X
Model: TESLA MODEL 3 STANDARD RANGE
Chassis: LRW3F7FA8MC384728-2021
Reg.Year: 2021

Third Party Insurer: MSIG
Third Party Veh No: SLG5797Y
Date of Accident: 10/07/2022
Estimator: TING AN
Surveyor:

38	FRONT BONNET LOCK	1		B ₁	\$177.57	✓
39	FRONT BONNET LOCK ACTUATOR ASSY	1		T _m	\$107.48	✓
40	FRONT BONNET STRIKER	1		D ₁	\$2.80	✓
41	FRONT WIPER AIR GRILLE	1		P _m	\$44.86	X
42	FRONT LUGGAGE COMPARTMENT	1		B ₁	\$64.49	✓
43	FRONT LUGGAGE COMPARTMENT MAT	1		De foun	\$74.77	✓
44	FRONT WINDSCREEN GLASS	1		CM	\$785.05	✓
45	FRONT DASHBOARD	1		T _m	\$1,186.90	✓
46	FRONT PASSENGER AIRBAG	1		R ₁	\$644.80	✓
47	FRONT STEERING WHEEL AIRBAG	1		"	\$448.60	✓
48	FRONT AIRBAG CONTROL UNIT	1		De	\$560.75	✓
49	FRONT AIRBAG SENSOR	2	\$58.88	De	\$117.76	✓
50	HIGH VOLTAGE BATTERY PYROFUSE	1		De	\$42.18	✓
51	FRONT DASHBOARD WIRING HARNESS	1			\$178.88	✓
52	FRONT SAFETY BELT LH	1		T _m	\$158.88	✓
53	FRONT SAFETY BELT RH	1		T _m	\$158.88	✓
54	FRONT SEAT BELT PRETENSIONER LH	1			\$65.42	7
55	FRONT SEAT BELT PRETENSIONER RH	1			\$65.42	7
56	FRONT HEADLAMP LH	1			\$1,308.41	7
57	FRONT HEADLAMP RH	1		CM	\$1,308.41	✓
58	FRONT HEADLAMP LOWER BRACKET LH	1			\$7.48	7
59	FRONT HEADLAMP LOWER BRACKET RH	1			\$7.48	7
60	FRONT BUMPER	1		B ₁	\$663.55	✓
61	FRONT BUMPER TOWING COVER	1		P _m	\$14.95	X
62	FRONT BUMPER SIDE BRACKET LH	1		CM	\$9.35	✓
63	FRONT BUMPER SIDE BRACKET RH	1			\$9.35	7
64	FRONT BUMPER CENTER UPPER BRACKET LH	1		CM	\$12.15	✓
65	FRONT BUMPER CENTER UPPER BRACKET RH	1		CM	\$12.15	✓
66	FRONT BUMPER UPPER BRACKET LH	1		D ₁	\$1.87	✓
67	FRONT BUMPER UPPER BRACKET RH	1		D ₁	\$1.87	✓
68	FRONT BUMPER LOWER GRILLE	1		CM	\$102.80	✓
69	FRONT BUMPER GARNISH COVER LH	1		D ₁	\$6.54	✓
70	FRONT BUMPER GARNISH COVER RH	1		CM	\$6.54	✓
71	FRONT BUMPER REINFORCEMENT	1		B ₁	\$271.03	✓
72	FRONT BUMPER ABSORBER FOAM	1		CM	\$46.73	✓
73	FRONT BUMPER REINFORCEMENT CRUSH CAN LH	1			\$52.34	7
74	FRONT BUMPER REINFORCEMENT CRUSH CAN RH	1			\$52.34	7
75	FRONT BUMPER LOWER REINFORCEMENT	1			\$102.80	7
76	FRONT BUMPER LOWER REINFORCEMENT CRUSH CAN LH	1			\$59.81	7

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 12/07/2022
 Vehicle No: SNC8149X
 Model: TESLA MODEL 3 STANDARD RANGE
 Chassis: LRW3F7FA8MC384728-2021
 Reg.Year: 2021

Third Party Insurer: MSIG
 Third Party Veh No: SLG5797Y
 Date of Accident: 10/07/2022
 Estimator: TING AN
 Surveyor:

77	FRONT BUMPER LOWER REINFORCEMENT CRUSH CAN RH	1		\$59.81	7
78	FRONT SUPPORT BEAM	1		\$738.32	7
79	FRONT SUPPORT BEAM BRACKET LH	1		\$7.48	7
80	FRONT SUPPORT BEAM BRACKET RH	1		\$7.48	7
81	FRONT BUMPER UNDER COVER	1		\$186.92	7
82	FRONT BUMPER PARKING SENSOR	6	\$158.88	\$953.28	7
83	FRONT BUMPER PARKING SENSOR BRACKET	6	\$4.67	\$28.02	7
84	FRONT BUMPER WIRING HARNESS	1		\$93.46	7
85	FRONT HEADLAMP WIRING HARNESS	1		\$88.79	7
86	FRONT AMBIENT AIR SENSOR	1		\$1.83	7
87	FRONT HORN SENSOR ASSY	1		\$44.86	7
88	FRONT AIR VENT ASSY	1		\$186.92	7
89	FRONT RADAR SENSOR	1		\$345.79	7
90	FRONT RADAR SENSOR BRACKET	1		\$4.67	7
91	FRONT RADAR SENSOR SUPPORT BRACKET	1		\$7.48	7
92	FRONT RADIATOR	1		\$420.56	7
93	FRONT RADIATOR COOLING FAN & SHROULD	1		\$373.83	7
94	FRONT RADIATOR TOP HOSE	1		\$252.34	7
95	FRONT RADIATOR BOTTOM	1		\$224.30	7
96	FRONT FENDER LH	1		\$448.60	X
97	FRONT FENDER RH	1		\$448.60	7
98	FRONT FENDER SUPPORT BRACKET LH	1		\$23.36	X
99	FRONT FENDER SUPPORT BRACKET RH	1		\$23.36	7
100	FRONT FENDER INNER SHIELD LH	1		\$116.82	7
101	FRONT FENDER INNER SHIELD RH	1		\$116.82	X
102	FRONT DOOR LH	1		REPAIR	
103	FRONT DOOR RH	1		REPAIR	
SUB TOTAL				\$23,525.30	
LESS 10%				-\$2,352.53	
PARTS TOTAL				\$21,172.77	

Date: 12/07/2022
 Vehicle No: SNC8149X
 Model: TESLA MODEL 3 STANDARD RANGE
 Chassis: LRW3F7FA8MC384728-2021
 Reg.Year: 2021

Third Party Insurer: MSIG
 Third Party Veh No: SLG5797Y
 Date of Accident: 10/07/2022
 Estimator: TING AN
 Surveyor:

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BOOTLID INNER TRIM CLIPS	1		1n \$50.00
2	REAR BUMPER CLIPS	1		1n \$60.00
3	REAR END PANEL JOINT SEALANT	1		\$80.00
4	REAR FENDER QUARTER GLASS SEALANT LH	1		1n \$60.00
5	REAR FENDER INNER SHIELD CLIPS LH	1		1n \$40.00
6	REAR TYRE LH	1		1n \$450.00
7	FRONT WINDSCREEN GLASS SEALANT	1		1n \$80.00
8	FRONT IU STICKER	1		1n \$20.00
9	FRONT BUMPER CLIPS	1		1n \$60.00
10	FRONT NUMBER PLATE & HOLDER	1		1n \$50.00
11	FRONT FENDER INNER SHIELD CLIPS LH	1		1n \$40.00
12	FRONT FENDER INNER SHIELD CLIPS RH	1		1n \$40.00
13	FRONT BATTERY	1		\$300.00
14	WRAP FOR AFFECTED AREAS	1	(Bill)	\$1,850.00
15	FRONT WINDSCREEN COATING	1	(Bill)	\$1,000.00
S/N TOTAL				\$4,180.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST FRONT & REAR ACCIDENT AREAS & ETC.

\$3,000.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BOOTLID, REAR BUMPER, REAR FENDER LH, REAR END PANEL, FRONT BONNET, FRONT BUMPER, FRONT FENDER LH, FRONT FENDER RH, FRONT DOOR LH, FRONT DOOR RH & ETC.

\$3,000.00

LABOUR CHARGES TO REMOVE & REPLACE FRONT & REAR PARKING SENSOR.

\$200.00

LABOUR CHARGES TO REMOVE & REPLACE FRONT BUMPER WIRING HARNESS & ETC. TO EFFECT REPLACE OF FRONT BUMPER.

\$150.00

LABOUR CHARGES TO REMOVE & REFIX REAR FENDER INNER TRIM & UNHOLDSTERY CUSHION SET & ETC. TO EFFECT REPLACE OF REAR FENDER LH.

\$300.00

LABOUR CHARGES TO REMOVE & REFIX REAR QUARTER GLASS LH & ETC.

\$150.00

Head office

8 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 12/07/2022
 Vehicle No: SNC8149X
 Model: TESLA MODEL 3 STANDARD RANGE
 Chassis: LRW3F7FA8MC384728-2021
 Reg.Year: 2021

Third Party Insurer: MSIG
 Third Party Veh No: SLG5797Y
 Date of Accident: 10/07/2022
 Estimator: TING AN
 Surveyor:

LABOUR CHARGES TO REMOVE & REPLACE REAR ABSORBER LH, REAR KNUCKLE ARM LH, REAR UPPER & LOWER ARM LH, REAR WHEEL BEARING LH & ETC.	\$350.00	7
LABOUR CHARGES TO REMOVE & REPLACE FRONT SAFETY BELT LH & RH, FRONT PASSENGER AIRBAG, FRONT STEERING WHEEL AIRBAG & ETC.	\$500.00	2501
LABOUR CHARGES TO REMOVE, REPLACE, REFIX FRONT DASHBOARD & ETC.	\$400.00	2501
TO DIAGNOSIS & RESET AIRBAG CONTROL UNIT.	\$300.00	2001
TO DAIGNOSIS FAULT CODE & RESET MEMORY.	\$200.00	1501
TO WHEEL ALIGNMENT & BALANCING.	\$100.00	801
TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.	\$120.00	401
LABOUR TOTAL		\$8,770.00
TING AN	TOTAL	\$34,122.77

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 13/07/2022 11:43 (SGT)
Reported by Both
Date of Accident 10/07/2022 11:15 (SGT)
Exact Location of Accident SLE, Singapore
Additional Location Information -
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SNC8149X

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner NG PENG XUN LUKAS
NRIC No SXXXX706D
Email Address NLUKAS94@GMAIL.COM
Mobile Phone No (Phone) +65-91159313
Alternative Phone No -

VEHICLE PARTICULARS

Manufacturer Tesla
Model MODEL 3 STD RANGE
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 1991

INSURANCE COMPANY


Name of Insurance Company EQ Insurance Company Ltd
Policy Number / Cover Note Number DMPPHQ21-008559

DRIVER

Name of Driver NG PENG XUN LUKAS
NRIC No SXXXX706D
Date Of Birth 09/07/1994
Occupation Indoor

Date of accident: 10/07/2022 Time: 11:15 HRS Location: Seletar Expressway
My Vehicle A: SNC8149X Vehicle B: SLG5777Y Vehicle C: SGE7521H

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report No: T/20220710/2036

☐ Claim OD/TP at Ah Lim Motor ☒ Claim OD/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop: Optima Werkz

Email address: Mohamed.nashik@ow.sg
& myself

Email address: NLUKAS94@gmail.com

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

AH LIM MOTOR COMPANY
No. 10, Kio Industrial Park 2A
#01-09 AHK/Autoright Singapore 60004
Tel: 6353 1244 Fax: 6493 5170
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

AH LIM MOTOR COMPANY