

ASS. REC. BY: Tauyith

REF:

C/CTI 22006630/TV43

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: **GBH 8161A**Policy No. **DMCVSNA00110382101**Claims No. **SNM22D204824/C01/CSC**

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
	X

Bal. or Market Value: \$175K.

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SBL 328T Yr Regn: 2021, May

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Mercedes Benz GLA 200 c.c. 1332Colour: White A/C: Insured / Std / NI / NASp. Reading: 9079 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WIN 2477872J16 *163

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 235/55R18R: n n

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or ConfidentialFront RearR/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 8/7/2022 D.O.I. 18/7/22Survey held at Xin YunDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
5/4/23	Lump Sum \$6000 confirmed by email (Red 7156.26, 54%)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 11/4/23-typistReport Format: MerimenLump Sum / LB: \$6000Days Of Repair: 4Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS, \$ _____

Photos

Others

TOTAL



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

Number Plate: SBL328T

Modle: MERCEDES CLA200 NEW MODEL

			Estimated Parts Price	
No	Qty	Parts Description		
1	1	Bumper assy	\$ 2,250.00	di ✓ 1,353.32
2	2	Bumper side bracket	\$ 280.00	x un
3	2	Bumper side retainer	\$ 260.00	x un
4	1	Bumper internal mounting -center	\$ 150.00	de ✓
5	2	Bumper lower refector	\$ 200.00	x un.
6	1	Reinforcement	\$ 850.00	bt ✓ 795
7	1	Reinforcement top cover garnish	\$ 380.00	cu ✓ 304
8	1	Rear end top cover	\$ 290.00	x un
9	1	Emblem	\$ 145.38	re ✓ 75
10	1	A200 Logo	\$ 158.36	al ✓ 108
11	1	Tailgate assy	\$ 2,500.00	bt ✓ 2370
12	1	Tailgate internal trim	\$ 285.00	x }
13	1	Tailgate lock	\$ 225.00	x }
14	2	Tailgate hinges	\$ 197.20	x }
15	2	Tailgate mounting /stopper	\$ 160.00	x }
16	1	Tailgate number plate light	\$ 100.00	x }
17	1	Tailgate rubber garnish	\$ 325.00	x }
18	1	Taillight left	\$ 775.75	x }
19	1	Taillight right	\$ 775.75	x }
20	1	Lower lip silving chrome	\$ 375.00	cu ✓ 250
21	1	Lower lip base	\$ 616.00	de ✓ 506
22	2	Lower lip both side joint cover /exhaust base	\$ 200.00	x un
23	2	Exhaust cover silver cover	\$ 380.00	LH bt ✓ RHX un 190
24	1	Tow cover	\$ 80.00	x }
25	2	Rear light side cover	\$ 180.00	x }
26	2	Rear light bracket	\$ 280.00	x }
27	2	Rear light support bracket	\$ 250.00	x }
28	1	Auto door open sensor with cable	\$ 650.00	x }
29	1	Tailgate middle trim	\$ 380.00	x }
30	1	Bumper diffuser	\$ 200.00	x }
		Parts sub-total	\$ 13,898.44	



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

Number Plate: SBL328T

Modle: MERCEDES CLA200 NEW MODEL

			Estimated	
No	Qty	Parts Description / Special Nett Item	Parts Price	
1	10	Rear bumper clips	\$ 100.00	5000 ✓
2	8	Rear end lower panel top garnish clips	\$ 80.00	× nn
3	1	Rear end lower panel sealant	\$ 120.00	× nn
4	8	Rear tailgate inner trim board clips	\$ 80.00	× nn
5	8	Rear tailgate outer garnish clips	\$ 80.00	× nn
6	12	Rear lower lip clips	\$ 100.00	3000 ✓
7	1	Tailgate middle trim clips	\$ 120.00	× nn
8	1	Rear windscreen glass sealant	\$ 120.00	× nn
9	8	Rear windscreen garnish clips	\$ 80.00	× nn
10	1	Rear windscreen rubber seal	\$ 150.00	× nn
11	2	Rear bumper reverse sensor	\$ 600.00	hw ✓ 400
12	1	Rear no plate with garnish	\$ 80.00	↓ nn
Special Nett Items			<u>\$ 1,710.00</u>	



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

Number Plate: SBL328T

Modle: MERCEDES CLA200 NEW MODEL

No	Description	Labour Charges
1	Replacing accident damages parts, bumper, lower lip, tailgate, rear end panel, reinforcement etc, knock jack and straighten accident damages area	\$ 2,000.00 600
2	To putty and spray painting for accident affected damaged area	\$ 1,500.00 700
3	Checking rear wiring and lighting system for proper function	\$ 120.00 50
4	Carry up body cavity preservation for affected area	\$ 200.00 x
5	Replacing rear undercarriage parts, including bleeding brake system	\$ 120.00 x
6	To carry out rear wheel balancing	\$ 100.00 x
7	To conduct wheel alignment.	\$ 120.00 x
8	Removing and installing rear bootlid compartment garnish, timing etc, to facilitate the necessary repair work	\$ 150.00 60
9	Transferring tailgate / bootlid lock mechansam, trimming etc.	\$ 120.00 x
10	To conduct chassis alignment.	\$ 150.00 x
11	Checking central lock system for proper function	\$ 120.00 x
12	Removing and installing rear exhaust muffler assy to facilitate the necessary repair work.	\$ 150.00 x
13	Removing and install rear camera	\$ 100.00 x
14	Paint protection for accident affected area	\$ 500.00 x
15	Water test after accident repair body work	\$ 150.00 x
16	Carrau out diagnostic check including cleaning faults code, if necessary	\$ 120.00 ✓
17	Labour to remove and install rear camera module whole set	\$ 150.00 x
Total labour :		\$ 5,870.00

Total parts 13,156.26

Tanpin 97445749
WP' 18/7/22
L/S Resurvey after repair
Tanpin @ lkkauto.com
04 days

LKK Auto Consultant hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a Without Prejudice basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: