



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2303805

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 15/06/2023
Reference CC6/CTI22006633/Rya3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SLV 8131U
Insured Veh. YQ 5194E
Claim No. SNM22D204879/C02
Policy No. DMCVSNW00149082100
Accident Date 10/07/2022
Inspection Date 19/07/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI22006633/Rya3q2 Date: 15/06/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YQ 5194E	Veh. Inspected	SLV 8131U	
Policy No.	DMCVSNW00149082100	Coverage (\$)	0.00	
Claim No.	SNM22D204879/C02	Excess (\$)	0.00	
Assign From		Assign Date	19/07/2022	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN NOTE 1.2 CVT	c.c	1198	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	JN1TAAE12Z0980117	Colour	PINK	
Odometer	70666 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/65 R15	YOKOHAMA	6 mm	
L/H Front Tyre	185/65 R15	YOKOHAMA	6 mm	
R/H Rear Tyre	185/65 R15	YOKOHAMA	6 mm	
L/H Rear Tyre	185/65 R15	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	10/07/2022	Inspection Date	19/07/2022	
Survey held at	AUTOMOTIVE REPAIR CENTRE PTE LTD 38 WOODLANDS INDUSTRIAL PARK E1 # 05-18 SINGAPORE 757700			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 8131U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	680.00	680.00
10	REAR BUMPER CLIPS @\$5.00	NECESSARY	50.00	50.00
1	REAR BUMPER RETAINER LH	NOT NECESSARY	60.00	-
1	REAR BUMPER RETAINER RH	NOT NECESSARY	60.00	-
1	REAR BUMPER SPONGE	NOT NECESSARY	180.00	-
1	REAR BUMPER STAY LH	NOT NECESSARY	90.00	-
1	REAR TAIL LAMP RH	NOT NECESSARY	480.00	-
1	REAR TAIL LAMP LH	NOT NECESSARY	480.00	-
1	REAR TAIL LAMP SPECIAL CLIP LH	NOT NECESSARY	30.00	-
1	REAR TAIL LAMP SPECIAL CLIP RH	NOT NECESSARY	30.00	-
1	REAR TAILGATE DOOR	BENT	1,100.00	1,100.00
1	REAR TAILGATE OUTER GARNISH	CRACKED	400.00	400.00
1	REAR TAILGATE DOOR RUBBER SEAL	NECESSARY	150.00	150.00
1	REAR TAILGATE DOOR INNER TRIM	NOT NECESSARY	180.00	-
1	REAR /END PANEL GARNISH	SCRATCHED	150.00	150.00
1	END PANEL	NOT NECESSARY	650.00	-
1	REAR NISSAN EMBLEM	NECESSARY	60.00	60.00
1	REAR NOTE EMBLEM	NECESSARY	80.00	80.00
1	REAR WIPER MOTOR ASSY	NOT WORKING	580.00	580.00
1	REAR WIPER ARM	NOT NECESSARY	200.00	-
1	REAR REFLECTOR RH	NOT NECESSARY	60.00	-
1	REAR REFLECTOR LH	NOT NECESSARY	60.00	-
1	ANTENNA SENSOR	NOT NECESSARY	150.00	-
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	120.00	-
	LESS 30% DISCOUNT		-	-975.00
			6,080.00	2,275.00
	<u>SPECIAL NETT ITEMS</u>			
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	40.00	40.00
1	REAR LICENCE PLATE (SN)	NOT NECESSARY	40.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REVERSE SENSOR (SN)	NOT NECESSARY	200.00	-
			280.00	40.00
	LABOUR			
	SPRAY PAINTING WHOLE REAR INCLUDING BLENDING .		800.00	600.00
	REMOVE AND REFIT ACCIDENT AFFECTED AREA .		800.00	500.00
	REMOVE AND REFIT REAR WINDSCREEN.		150.00	120.00
	APPLY RUST PROOFING ON REPLACED /REPAIRED PANEL.		100.00	40.00
	TRANSFER DOOR FITTING AND WINDOW MECHANISM TO NEW DOOR .		80.00	60.00
	REMOVE AND REFIT REAR BUMPER REVERSE SENSOR .		80.00	40.00
	CHECK AND RECTIFY /ELECTRICAL WIRING.		30.00	30.00
			2,040.00	1,390.00
GRAND TOTAL			8,400.00	3,705.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,950.00

Report Ref No. CC6/CTI22006633/Rya3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLV 8131U

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLV 8131U

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLV 8131U

RE-INSPECTION

