



Automotive Repair Centre Pte Ltd
CO. Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2207-371
DATE : 13-Jul-2022
POLICY NO. : BD P10117218R03
VEHICLE REG. NO. : SLV8131U
VEHICLE MAKE : NISSAN NOTE 1.2 CVT

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

--

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
<u>SPARE PARTS</u>				
1	Rear Bumper	1	\$ 680.00	\$ 680.00
2	Rear Bumper Clips	10	\$ 5.00	\$ 50.00
3	Rear Bumper Retainer LH	1	\$ 60.00	\$ 60.00
4	Rear Bumper Retainer RH	1	\$ 60.00	\$ 60.00
5	Rear Bumper Sponge	1	\$ 180.00	\$ 180.00
6	Rear Tail Lamp RH	1	\$ 480.00	\$ 480.00
7	Rear Tail Lamp LH	1	\$ 480.00	\$ 480.00
8	Rear Tail Lamp Special Clip LH	1	\$ 30.00	\$ 30.00
9	Rear Tail Lamp Special Clip RH	1	\$ 30.00	\$ 30.00
10	Rear Tailgate Door	1	\$ 1,100.00	\$ 1,100.00
11	Rear Tailgate Outer Garnish	1	\$ 400.00	\$ 400.00
12	Rear Tailgate Door Rubber Seal	1	\$ 150.00	\$ 150.00
13	Rear Tailgate Door Inner Trim	1	\$ 180.00	\$ 180.00
14	Rear / End Panel Garnish	1	\$ 150.00	\$ 150.00
15	End Panel	1	\$ 650.00	\$ 650.00
16	Rear Nissam Emblem	1	\$ 60.00	\$ 60.00
17	Rear Reflector RH	1	\$ 60.00	\$ 60.00
18	Rear Reflector LH	1	\$ 60.00	\$ 60.00
19	Rear Windscreen Moulding	1	\$ 120.00	\$ 120.00
Total Spare Parts				\$ 4,980.00
<u>SPECIAL NETT</u>				
20	Rear Windscreen Sealant	1	\$ 40.00	\$ 40.00
21	Rear Licence Plate	1	\$ 35.00	\$ 35.00
22	Reverse Sensor	1	\$ 200.00	\$ 200.00
Total Special Nett				\$ 275.00
<u>LABOUR</u>				
21	Spray Painting Whole Rear Including Blending	1	\$ 800.00	\$ 800.00
22	Remove and Refit Accident Affected Area	1	\$ 800.00	\$ 800.00
23	Remove and Refit Rear Windscreen	1	\$ 150.00	\$ 150.00
24	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00
25	Transfer Door Fitting and Window Mechanism to New Door	1	\$ 80.00	\$ 80.00
26	Remove and Refit Rear Bumper Reverse Sensor	1	\$ 80.00	\$ 80.00
27	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00
Total Labour				\$ 2,040.00
Amount Before Excess				\$ 7,295.00

Estimate prepared by: Oscar Pong

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started.



Automotive Repair Centre Pte Ltd
CO. Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2207-371
DATE : 13-Jul-2022
POLICY NO. : BD P10117218R03
VEHICLE REG. NO. : SLV8131U
VEHICLE MAKE : NISSAN NOTE 1.2 CVT

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.				
Add GST @ 7%				510.65
Total Amount Payable				\$ 7,805.65