

Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No.200810440N)
Blk 3 Pioneer Road North, #01-18
Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg; darren@sngahtee.com; janice@sngahtee.com

TP INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)
N/A

Singapore

Claimant Insurer: HL Assurance Pte Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	26/06/2022
Vehicle Reg. No.:	SKX7507C	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	MARK LIM SOON SHIN		
Make/Model:	NISSAN QASHQAI, 1.2 DIG-T CVT ABS 2WD 5DR (A)	Vehicle Reg. Date:	28/12/2015
Vehicle Colour:	BROWN	Chassis No:	SJNFEAJ11U1533614
Engine No:	HRA2208947A		
Odometer:	5 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	8		
Description of Accident/Loss	REFER TO POLICE		
Present Location:	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)		

COST OF CLAIMS	Amount
Parts	5,269.00
Miscellaneous Items	0.00
Labour	1,880.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	7,149.00
+ GST 7.00% (S\$)	500.43
Nett Amount (S\$)	7,649.43

This claim is handled by: SAMANTHA TAN YONG SING

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Jul 2022)

Parts: M1-SUV NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKX7507C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR NUMBER PLATE X <i>nn</i>	0	0.00	*35.00 FS X
2	1		*REAR BUMPER — <i>OD</i>	0.00	0.00	*420.00 F
3	2		*REAR BUMPER RETAINER — <i>BR</i>	0.00	0.00	*50.00 F
4	1		*REAR BUMPER TOWING COVER — <i>cut</i>	0.00	0.00	*25.00 F
5	1		*REAR BUMPER SPONGE ? — <i>BR</i>	0.00	0.00	*95.00 F
6	1		*REAR BUMPER REINFORCEMENT ? — <i>BT</i>	0.00	0.00	*320.00 F
7	2		*REAR BUMPER REINFORCEMENT ARM ? — <i>BT</i>	0.00	0.00	*180.00 F
8	1		*REAR END PANEL ? — <i>X R</i>	0.00	0.00	*330.00 F X
9	10		*REAR BUMPER CLIP — <i>MC</i>	0.00	0.00	*15.00 F
10	1		*REAR TAILGATE — <i>nn</i>	0.00	0.00	*1,750.00 F
11	1		*REAR TAILGATE CENTER GARNISH X <i>nn</i>	0.00	0.00	*210.00 F X
12	1		*REAR TAILGATE WEATHERSTRIPE X <i>nn</i>	0.00	0.00	*110.00 F X
13	1		*REAR TAILGATE EMBLEM X <i>nn</i>	0.00	0.00	*45.00 F X
14	1		*REAR TAILGATE QASHQAI LOGO — <i>MC</i>	0.00	0.00	*60.00 F
15	1		*REAR TAILGATE LAMP RH X <i>nn</i>	0.00	0.00	*170.00 F X
16	1		*REAR TAILLAMP RH X <i>nn</i>	0.00	0.00	*210.00 F X
17	1		*REAR WINDSCREEN MOULDING WITH GLASS X <i>nn</i>	0.00	0.00	*550.00 F X
18	1		*REAR WINDSCREEN SEALANT — <i>MC</i>	0	0.00 <i>nett</i>	*40.00 FS
19	1		*REAR PARKING SENSOR — <i>OR</i>	0	0.00 <i>nett</i>	*200.00 FS
Sub Total (\$\$)						4,815.00
+ Margin on L,N Items 10.00% (\$\$)						454.00
Total Parts (\$\$)						5,269.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO KNOCK,WELD,REMOVE & FIX ON ABOVE PARTS	New 400 660 /	850.00
2	TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS	New 400 600 /	800.00
3	TO CHECK WIRING	New	30.00 ✓
4	TO APPLY ANTI RUST COATING	New 30 /	80.00
5	TO REMOVE & FIX REAR WINDSCREEN	New	120.00 ✓
Gross Labour Cost (S\$)			1,880.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Steve (LKK)

18/7/22, 12.19p

W/L R/L

P/P

L/R

5 L/R

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 10 Sep 2022)**Parts:** M1-SUV NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Sng Ah Tee Motor & Panel Service Pte Ltd/SKX7507C/10/09/2022 11:08**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.*Supplementary***Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR WINDSCREEN MOULDING	0.00	0.00	NEC *120.00 F ✓
			Sub Total (S\$)			120.00
			+ Margin on L,N Items 10.00% (S\$)			12.00
			Total Parts (S\$)			132.00

Sng Ah Tee Motor & Panel Service Pte Ltd/SKX7507C/10/09/2022 11:08. Not valid without Reference section.

Generated using Merimen e-Claims IEAS