

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III22006639/RPA3Q2**Date:** 14/12/2022**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0003693_02
Claimant Vehicle No : FBP7987Z **Insured Vehicle No :** CB6596L
 Date of Loss: 05/07/2022 Nature of Claim: TP Claim No: MFL2022D0003558

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBP7987Z**
 Make & Model: YAMAHA SNIPER T150, 150cc Engine No: G3E6E0484916
 Reg. Date: 11/06/2019 (Man. Year: 2019) Chassis No: MH3UG0740K0152763
 Colour: Multi-colour Odometer: 72260 km
 Engine Capacity: 150 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 70/90-17 Rear Tyre Size: 90/80-17
 Front Left Side: Maxxis 3 mm Rear Left Side: Maxxis 3 mm
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,067.20	1,426.70	1,640.50	53.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,740.00	450.00	1,290.00	74.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,807.20	1,876.70	2,930.50	60.96
Approved Total (Overridden) (S\$)		1,500.00		
Nett Amount (S\$)	4,807.20	1,500.00	3,307.20	68.80
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 13/07/2022
 Date Inspected: 14/07/2022 Inspected At: Project 8 Motorworks (HQ)
 61 Woodlands Industrial Park E9,, #01-03 E9
 Premium
 Singapore 757047
 Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 26 Oct 2022)	
Parts:	N/A	YAMAHA SNIPER T150 150cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBP7987Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FOOTREST BRACKET	Bent	140.00 FL	*140.00 FL
2	1		*REAR BRAKE PEDAL	Bent	100.00 FL	*75.00 FL
3	1		*RHS FRONT FOOTREST	Scratched	100.00 FL	*50.00 FL
4	1		*RHS FRONT FOOTREST RUBBER	Scratched	80.00 FL	*45.00 FL
5	1		*HANDLEBAR	Not Necessary	140.00 FL	*- FL
6	1		*FRONT MASTER PUMP	Cracked	280.00 FL	*280.00 FL
7	1		*RHS BRAKE LEVER	Scratched	70.00 FL	*45.00 FL
8	1		*EXHAUST COVER	Scratched	120.00 FL	*75.00 FL
9	1		*EXHAUST TIP COVER	Scratched	110.00 FL	*55.00 FL
10	2		*SET BALANCER	Missing	80.00 FL	*50.00 FL
11	1		*RHS SIDE MIRROR	Scratched	85.00 FL	*55.00 FL
12	1		*RHS REAR SIGNAL LIGHT	Not Necessary	90.00 FL	*- FL
13	1		*RHS FRONT SIGNAL LIGHT	Scratched	120.00 FL	*75.00 FL
14	1		*CLUTCH HOUSING	Not Necessary	420.00 FL	*- FL
15	1		*CLUTCH GASKET	Not Necessary	80.00 FL	*- FL
16	1		*ENGINE OIL	Necessary	45.00 FS	*20.00 FS
17	1		*BRAKE FLUID	Necessary	36.00 FS	*30.00 FS
18	1		*RHS Z PANEL	Scratched	140.00 FL	*100.00 FL
19	1		*RHS REAR SEAT COVER	Scratched	130.00 FL	*105.00 FL
20	1		*FRONT MUDGUARD	Scratched	135.00 FL	*85.00 FL
21	1		*RHS HEADLAMP COVER (BLACK)	Scratched	128.00 FL	*128.00 FL
22	1		*TOP BOX	Scratched	198.00 FS	*150.00 FS
23	1		*BOX RACK	Not Necessary	210.00 FL	*- FL
24	1		*KICK STARTER LEVER	Not Necessary	120.00 FL	*- FL
25	1		*REAR RHS FOOTREST BRACKET	Not Necessary	120.00 FL	*- FL
26	1		*REAR RHS FOOTREST	Not Necessary	100.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,377.00	1,563.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	309.80	136.30
Total Parts (\$\$)	3,067.20	1,426.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	FORK ALIGNMENT	New	220.00	100.00
2	FRONT RIM ALIGNMENT	New	220.00	0.00
3	CHASSIS ALIGNMENT	New	500.00	0.00
4	LABOUR FEE	New	800.00	350.00
Gross Labour Cost (\$\$)			1,740.00	450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >