



HKL LIM TEAM MOTORSPORT PTE LTD

UEN: 202218929Z

Blk 1008 #01-24 Bukit Merah Lane 3, Singapore 159722.
Tel: 6275 6656 Email: hklteam@gmail.com

FBP2464Z

1	LAMP STAY	? X nn	\$250
2	FRONT FENDER	X nn	\$90
3	FRONT SIGNALS LH/RH	? (LH) - OR	80- \$160
4	HANDLE BAR	X nn	\$150
5	WINDSHIELD MALOSSI	- CUT	\$160
6	FRONT NO PLATE	- n/c	\$15
7	BRAKE LEVER RH	- CUT	\$45
8	SIDE MIRROR	- CUT	\$150
9	HEADLIGHT	- CUT	\$580
10	HEAD COWLING CENTER	- CUT	\$130
11	HEAD COWLING LH/RH	- CUT	180- \$300
12	SEATBAR RH	X nn	\$180
13	HEAD PANEL	- CUT	\$120
14	TAIL BOARD CENTER	- CUT	\$95
15	TAIL PANEL	- CRU	\$60
16	TAIL PANEL LH/RH	- CRU	\$160
17	REAR FENDER	X nn	\$90
18	FRONT FOOT REST RH PANEL	(1/2) - CRU	\$120
19	EXHAUST	X nn	\$780
20	EXHAUST MUFFLER COVER	- CRU	\$95
21	TAIL LIGHT LH/RH	- OR (RH) (LH) ? X nn	\$400 200-
22	TAILBOARD LH/RH	- CRU	120- \$240
23	TAILBOARD LOGO LH/RH	- CRU	40- \$80
24	SIDE PANEL BLACK RH	- CRU	\$120
25	LABOUR		\$680 350

TOTAL AMOUNT:

2320
-10%
2088 + 350
= 2438 \$5,250

Steve (LKK)
14/7/22, 11:39L

m n
P/P
m gcl y
3 Lys