

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBP 2464Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	LAMP STAY	NOT NECESSARY	250.00	-
1	FRONT FENDER	NOT NECESSARY	90.00	-
2	FRONT SIGNALS LH / RH	N/S BROKEN	160.00	80.00
1	HANDLE BAR	NOT NECESSARY	150.00	-
1	WINDSHIELD MALOSSI	CUT	160.00	160.00
1	FRONT NO PLATE	NECESSARY	15.00	15.00
1	BRAKE LEVER RH	CUT	45.00	45.00
1	SIDE MIRROR	CUT	150.00	150.00
1	HEADLIGHT	CUT	580.00	580.00
1	HEAD COWLING CENTER	CUT	130.00	130.00
2	HEAD COWLING LH / RH	N/S CUT	300.00	150.00
1	SEATBAR RH	NOT NECESSARY	180.00	-
1	HEAD PANEL	CUT	120.00	120.00
1	TAIL BOARD CENTER	CUT	95.00	95.00
1	TAIL PANEL	CRUSHED	60.00	60.00
2	TAIL PANEL LH / RH	CRUSHED	160.00	160.00
1	REAR FENDER	NOT NECESSARY	90.00	-
1	FRONT FOOT REST RH PANEL	CUT	120.00	120.00
1	EXHAUST	NOT NECESSARY	780.00	-
1	EXHAUST MUFFLER COVER	CUT	95.00	95.00
2	TAIL LIGHT LH / RH	O/S BROKEN / N/S NOT NECESSARY	400.00	200.00
2	TAILBOARD LH / RH	O/S CUT	240.00	120.00
2	TAILBOARD LOGO LH / RH	O/S NECESSARY	80.00	40.00
1	SIDE PANEL BLACK RH	TO REPAIR SEE LABOUR	120.00	-
	LESS 10% DISCOUNT		-	-232.00
			4,570.00	2,088.00

Report Ref No. CS/AWA22006642/Ecy3e2



RECOMMENDED COST OF REPAIRS

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

2,438.00

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>LABOUR</u>			
1	LABOUR. INCLUSIVE OF THE REPAIR OF SIDE PANEL BLACK RH.		680.00	350.00
			680.00	350.00
	GRAND TOTAL		5,250.00	2,438.00

Report Ref No. CS/AWA22006642/Ecy3e2



Automotive Assessor

X.S.

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.