



HKL LIM TEAM MOTORSPORT PTE LTD

UEN: 202218929Z

Blk 1008 #01-24 Bukit Merah Lane 3, Singapore 159722.

Tel: 6275 6656 Email: hklteam@gmail.com

FBP2464Z

1	LAMP STAY	? X nn	\$250
2	FRONT FENDER	X nn	\$90
3	FRONT SIGNALS LH/RH	? (LH) - OR	80- \$160
4	HANDLE BAR	X nn	\$150
5	WINDSHIELD MALOSI	- cut	\$160
6	FRONT NO PLATE	- RX	\$15
7	BRAKE LEVER RH	- cut	\$45
8	SIDE MIRROR	- cut	\$150
9	HEADLIGHT	- cut	\$580
10	HEAD COWLING CENTER	- cut	\$130
11	HEAD COWLING LH/RH	- cut	180- \$300
12	SEATBAR RH	X nn	\$180
13	HEAD PANEL	- cut	\$120
14	TAIL BOARD CENTER	- cut	\$95
15	TAIL PANEL	? - CRU	\$60
16	TAIL PANEL LH/RH	? - CRU	\$160
17	REAR FENDER	X nn	\$90
18	FRONT FOOT REST RH PANEL	(1/2~) - cut	\$120
19	EXHAUST	X nn	\$780
20	EXHAUST MUFFLER COVER	- cut	\$95
21	TAIL LIGHT LH/RH	- OR (RH) (LH) ? X nn	\$400 200
22	TAILBOARD LH/RH	- cut	120- \$240
23	TAILBOARD LOGO LH/RH	- cut	40- \$80
24	SIDE PANEL BLACK RH	- cut	\$120 * R
25	LABOUR		\$680 350

2320
-10%
2088 + 351

TOTAL AMOUNT:

= 2438 \$5,250

Stew (LKK)

14/7/22, 11:39L

m n

P/P

My GUY

3 Lyr

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



CamScanner