

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

| | |
|--|---|
| To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 | From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933 |
|--|---|

Attn: Fievel Foo Wen Yao

Date: 04 Aug 2022

Preliminary Advice

| | | | |
|--------------------|------------------------|-------------------------|--------------|
| Insured | : YN3662A | | |
| Vehicle No | | | |
| TP Vehicle No | : SMG1466S | Accident Date | : 09/07/2022 |
| Make | : HONDA FREED HYBRID | Assignment Date | : 14/07/2022 |
| Date of Inspection | : 14/07/2022 | Est. Duration of Repair | : 4 |
| Inspection At | : Optima Werkz Pte Ltd | | |

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|----------|
| Repairer's Estimate (Gross) | :S\$ | 6,603.44 |
| Revised Amount | :S\$ | 2,821.86 |
| Check Items (Estimated) | :S\$ | 0.00 |
| Total | :S\$ | 2,821.86 |
| Lump Sum Repair | :S\$ | |

Total Loss Consideration

| | |
|--------------------|------|
| New for Old Value | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate | :S\$ |
| Salvage Value | :S\$ |
| Margin for Repair | :S\$ |

Remarks

- () The vehicle is economical for repair
 - () The vehicle is not economical for repair
 - () Part-by-Part repair
 - (X) Lump Sum repair
-
- (X) The above survey was conducted on a 'without prejudice' basis.
Please note that the preliminary advice amount (Revised & Check Items)
stated are subject to consistency check, part prices and labour cost.