

ASS. REC. BY:

REF:

CS/CT12200664/Tg. y3

ASSIGNMENT

06 2024 June

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 921K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No:

SLC6775A

Yr Regn:

2009, June

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Vios

C.C

1497

Colour

Black

A/C: Insured / Std / NI / NA

Sp. Reading

191777

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MRO53HY 9305 * 114583

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/50R14

R:

7 1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

14/7/22

Survey held at

Bijest

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Rep. Format:

Lump Sum / L.B. /

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Bifrost Auto Pte Ltd

8 Kaki Bukit Ave 4 #01-49, Premier @ Kaki Bukit Singapore 415875
Tel: 93290237 Email: claims_rar@bifrotauto.com

SJE : _____
Date of Survey : _____
Date of ReSurvey: _____
Contacts : _____

Vehicle Nos : SLC 6775A
Made : Toyota
Model : Vios
Chassis No : _____

* AGREED Cost Of Repair and Repair Day/s with SJE *

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Front Bumper	1	\$ 474.80	\$ <i>M</i> 474.80
2	Front Bumper Side Retainer RH	1	\$ 61.40	\$ <i>X</i> 61.40
3	Front Bumper Side Retainer LH	1	\$ 61.40	\$ <i>X</i> 61.40
4	Front Bumper Fog Lamp Garnish RH	1	\$ 68.60	\$ <i>X</i> 68.60
5	Front Bumper Fog Lamp Garnish LH	1	\$ 68.60	\$ <i>X</i> 68.60
6	Front Bumper Fog Lamp RH	1	\$ 298.10	\$ <i>X</i> 298.10
7	Front Bumper Fog Lamp LH	1	\$ 298.10	\$ <i>X</i> 298.10
8	Front Bumper Lower Grille	1	\$ 87.50	\$ <i>X</i> 87.50
9	Front Bumper Reinforcement	1	\$ 382.50	\$ <i>X</i> 382.50
10	Front Bumper Arm RH	1	\$ 250.90	\$ <i>X</i> 250.90
11	Front Bumper Arm LH	1	\$ 250.90	\$ <i>X</i> 250.90
12	Front Bumper Reinforcement Bracket RH	1	\$ 56.30	\$ <i>X</i> 56.30
13	Front Bumper Reinforcement Bracket LH	1	\$ 56.30	\$ <i>X</i> 56.30
14	Front Bumper Sponge	1	\$ 95.40	\$ <i>X</i> 95.40
15	Front Bumper Tow Hook Cover	1	\$ 14.70	\$ <i>X</i> 14.70
16	Front Bumper Lower Cover RH	1	\$ 138.60	\$ <i>X</i> 138.60
17	Front Bumper Lower Cover LH	1	\$ 138.60	\$ <i>X</i> 138.60
18	Front Radiator Grille	1	\$ 265.20	\$ <i>X</i> 265.20
19	Front Radiator Grille Moulding	1	\$ 99.60	\$ <i>X</i> 99.60
20	Front Radiator Grille Emblem	1	\$ 55.00	\$ <i>X</i> 55.00
21	Front Bonnet	1	\$ 575.20	\$ <i>X</i> 575.20
22	Front Bonnet Hinge RH	1	\$ 52.20	\$ <i>X</i> 52.20
23	Front Bonnet Hinge LH	1	\$ 52.20	\$ <i>X</i> 52.20
24	Front Bonnet Seal	1	\$ 16.60	\$ <i>X</i> 16.60
25	Front Bonnet Lock	1	\$ 90.60	\$ <i>X</i> 90.60
26	Front Radiator Support	1	\$ 1,022.30	\$ <i>X</i> 1,022.30
27	Front Radiator Brace RH	1	\$ 91.20	\$ <i>X</i> 91.20
28	Front Radiator Brace LH	1	\$ 91.20	\$ <i>X</i> 91.20
29	Front Headlamp Assembly RH	1	\$ 602.50	\$ <i>X</i> 602.50
30	Front Headlamp Assembly LH	1	\$ 602.50	\$ <i>aut</i> 602.50
31	Aircon Liquid Pipe	1	\$ 667.40	\$ <i>X</i> 667.40
32	Aircon Suction Pipe	1	\$ 481.40	\$ <i>X</i> 481.40
33	Aircon Discharge Hose	1	\$ 387.90	\$ <i>X</i> 387.90

34	Radiator Assembly	1	\$	1,835.10	\$ X	1,835.10
35	Radiator Fan Blade	1	\$	201.50	\$ X	201.50
36	Radiator Fan Shroud	1	\$	246.80	\$ X	246.80
37	Radiator Fan Motor	1	\$	461.20	\$ X	461.20
38	Radiator Top Hose	1	\$	40.50	\$ X	40.50
39	Radiator Bottom Hose	1	\$	40.50	\$ X	40.50
40	Aircon Condenser	1	\$	1,133.30	\$ X	1,133.30
41	Front Fender LH	1	\$	575.20	\$ bt	575.20
42	Front Fender Emblem	1	\$	38.20	\$ ner	38.20
43	Front Fender Inner Shield LH	1	\$	175.20	\$ X	175.20
44	Front Fender Inner Panel LH	1	\$	478.60	\$ X	478.60
45	Front Shock Absorber LH	1	\$	460.00	\$ X	460.00
46	Front Shock Absorber Top Mounting LH	1	\$	185.50	\$ X	185.50
47	Front Lower Arm LH	1	\$	980.00	\$ X	980.00
48	Front Knuckle Arm LH	1	\$	455.10	\$ X	455.10
49	Front Knuckle Arm Bearing LH	1	\$	165.80	\$ X	165.80
50	Front Drive Shaft LH	1	\$	1,395.00	\$ X	1,395.00
51	Front Stabilizer Bar Link LH	1	\$	179.20	\$ X	179.20
52	Front Steering Rack & Pinion	1	\$	1,028.10	\$ X	1,028.10
53	Front Steering Tie Rod LH	1	\$	110.20	\$ X	110.20
54	Front Door LH	1	\$	781.09	\$ X	781.09
55	Front Door Protector LH	1	\$	99.80	\$ X	99.80
56	Front Door Protector Chrome Moulding LH	1	\$	25.10	\$ X	25.10
57	Front Door Upper Hinge LH	1	\$	69.20	\$ X	69.20
58	Front Door Lower Hinge LH	1	\$	69.20	\$ X	69.20
59	Front Door Checker LH	1	\$	88.70	\$ X	88.70
60	Front Door Inner Trim Board LH	1	\$	721.30	\$ X	721.30
61	Front Door Weatherstrip LH	1	\$	173.30	\$ X	173.30
62	Front Door Window Glass LH	1	\$	473.80	\$ X	473.80
63	Front Door Window Glass Run Channel LH	1	\$	68.60	\$ X	68.60
64	Front Door Window Glass Outer Moulding LH	1	\$	75.40	\$ X	75.40
65	Front Door Window Glass Inner Weatherstrip	1	\$	98.60	\$ X	98.60
66	Front Door Window Regulator LH	1	\$	123.20	\$ X	123.20
67	Front Door Window Regulator Motor LH	1	\$	763.20	\$ X	763.20
68	Front Door Lock Assembly LH	1	\$	289.80	\$ X	289.80
69	Front Door Side Mirror Assembly LH	1	\$	1,120.30	\$ cm	1,120.30
70	Front Door Side Mirror Cover LH	1	\$	85.70	\$ cm	85.70
Parts Sub Total :					\$	23,266.99
25% Discount					\$	5,816.75
PARTS TOTAL :					\$	17,450.24

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Front Number Plate	1	\$ 50.00	\$ X 50.00
2	Front Bumper Clips - Set	1	\$ 50.00	\$ 30mm 50.00
3	Front Headlamp Clips - Set	1	\$ 50.00	\$ X 50.00

4	Front Grille Assembly Clips - Set	1	\$	30.00	\$ X	30.00
5	Front Fender Inner Shield Clips - Set	1	\$	50.00	\$ X	50.00
6	Front Bonnet Insulator Clips - Set	1	\$	50.00	\$ X	50.00
7	Front Door Inner Trimboard Clips - Set	1	\$	50.00	\$ X	50.00
8	Radiator Coolant	1	\$	60.00	\$ X	60.00
9	Front Bonnet Sealant	1	\$	150.00	\$ X	150.00
10	Front Fender LH Sealant	1	\$	150.00	\$ X	150.00
11	Front Fender Inner Panel LH Sealant	1	\$	120.00	\$ X	120.00
12	Front Support Panel Sealant	1	\$	120.00	\$ X	120.00
13	Front Door LH Sealant	1	\$	150.00	\$ X	150.00
14	Front Wheel Rim LH	1	\$	1,000.00	\$ X	1,000.00
15	Front Tyre LH	1	\$	350.00	\$ X	350.00
SPECIAL NETT TOTAL :						\$ 2,430.00

Nos.	LABOUR		S\$
1	To Panel Beat, Remove & Refix Parts	\$ 600	1,800.00
2	To Spray Paint Affected Areas	\$ 600	1,600.00
3	Wiring & Bulb Check	\$ 30	100.00
4	To Transfer Front Door LH Mechanism	\$ X	150.00
5	To Remove & Refix Aircon Condenser and Top Up Gas	\$ X	150.00
6	To Remove & Refix Radiator and Pressure Test	\$ X	150.00
7	To Remove & Refix Front Undercarriage	\$ X	350.00
8	To Conduct Four Wheel Alignment	\$ X	120.00
9	To apply anti rust on affected parts	\$ 30	180.00
10	To Conduct Water Leak Test	\$ X	100.00
11	To Send for Diagnostic and Reset Control Unit. Programming & Calibration	\$ X	480.00
LABOUR TOTAL :		\$	5,180.00

Taufik 93495449
 WP 17/7/22 @ 3pm
 L/S Resurvey after repair
 for the claimants
 To check consistency of accident
 To check part price
 04 days

PARTS TOTAL : \$ 17,450.24
 SPECIAL NETT TOTAL : \$ 2,430.00
 LABOUR TOTAL : \$ 5,180.00
 GRAND TOTAL : \$ 25,060.24

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	154E
Vehicle Details	
Vehicle No.:	SLC6775A
Vehicle to be Exported:	Yes
Intended Deregistration Date:	12 Jul 2022
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS G AUTO
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	1NZX914092
Chassis No.:	MR053HY9305114583
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$13,876.00
Original Registration Date:	10 Jun 2009
First Registration Date:	10 Jun 2009
Transfer Count:	6
Actual ARF Paid:	\$11,511.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	09 Jun 2024
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$14,920.00
COE Rebate Amount:	\$5,697.00
Total Rebate Amount:	\$5,697.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 12 Jul 2022

OK

VEHICLE NO: 8LC 677SA

MAKE & MODEL: Toyota Vios

AUTO / MANUAL

DATE OF ACCIDENT	10 / 07 / 2022	*C.C.	1500
TIME OF ACCIDENT	06:50 AM / PM		
LOCATION OF ACCIDENT	Changi Village CarPark		
EXACT PURPOSE USED AT TIME OF ACCIDENT	EMPLOYMENT / PRIVATE USE / PRIVATE HIRE		
NAME OF OWNER	Jason Chia Chin Leng		
EMAIL: jasonchia2205@gmail.com	Office:	MOBILE:	
NRIC	892181546		
CLAIM TYPE	OD / THIRD PARTY / REPORTING ONLY		
FLEET POLICY:	YES / NO?		
INSURANCE CO.	MTUC		
TYPE OF COVERAGE	Comprehensive / Third Party / Third Party Fire & Theft		
POLICY NO.	5127572850		
NAME OF DRIVER	AS ABOVE / IF NO.		
NRIC			
DATE OF BIRTH	22 / 05 / 1992		
ANY PASSENGER	YES / NO: 0		
NAME OF PASSENGER			
GENDER OF PASSENGER	MALE / FEMALE		
OCCUPATION	Outdoor / Indoor		
DATE OF DRIVING PASS	15 / 09 / 2021		
GENDER	Male / Female		
CONTACT NO.	Mobile: 9276 3346	Office:	
EMAIL:			
ADDRESS	Block 446 Tampines Street #2 #10-32 S(520446)		
DOES DRIVER OWN OTHER VEHICLES?	NO / If yes: Reg No.	INSURER:	
RELATIONSHIP	Employee / If No: hsp		
WEATHER CONDITION	Clear / Raining / Other:		
ROAD SURFACE	Dry / Wet / Other:		
ANY INJURIES	No / If yes: Who?		
CONVEYED BY AMBULANCE	No / If yes: Who?		
POLICE REPORT	No / If yes: Where? TPMQ		
NOTICE OF INTENDED PROSECUTION GIVEN?	NO / IF YES: WHO?		
VEHICLE B NO.	4029117	Any Passenger:	
NAME			
CONTACT NO.			
VEHICLE C NO.		Any Passenger:	
VEHICLE D NO.		Any Passenger:	
VEHICLE E NO.		Any Passenger:	
VEHICLE F NO.		Any Passenger:	
ANY WITNESS			
WITNESS CONTACT NO.			
WAS THERE ANY VIDEO CAPTURE?	YES / NO		
WAS THERE ANY AUDIO RECORDED?	YES / NO		
SCENE ACCIDENT PHOTOS TAKEN?	YES / NO		
Who is Reporting	Driver / Owner / Both		
Original Language Used	English / Mandarin / Others:		
Have you been approach by unknown person soliciting (s) /			
offering accident claims assistance?	YES / NO		

IMPORTANT NOTICE

- #### 8. Consent under the Personal Data Protection Act (PDPA)

(collectively the "Purposes")

- A: SLC 6775M
B: 1429117
- Change Voltage
Circuit.
-
- Reverse


Describe Circumstance of the Accident

Refer to TP Report

T/20220710/7033

Declaration

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date

Witnessed by Reporting Centre Personnel



Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20220710/7033

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 10/07/2022 22:31		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: JASON CHIA CHIN SENG			Address: 446 TAMPINES STREET 42 #10-32 SINGAPORE 520446		
ID Type / ID No.: NRIC NO / S9218154E			Contact No.: Home/Office: Mobile: 92763346		
Nationality: SINGAPORE CITIZEN			Email: JASONCHIA2205@GMAIL.COM		
Sex: Male	Age: 30	Date of Birth: 22/05/1992	Type of Informant: Driver		
Race: Chinese		Language: English		Institution / School Name:	
Occupation:		Driving Licence Information: Class: 3A Date of Expiry:			

General Information of the Accident				
Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 10/07/2022 18:50	Type of Location: Car Park
Location: changji village carpark				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control:		Traffic Volume:
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Conditio	No of
SLC6775A	Car	TOYOTA	Vios	Black	Slightly Damaged	0
YQ2911Y	Lorry			White		0



SINGAPORE
POLICE FORCE



T/20220710/7033

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3

Report No. T/20220710/7033

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPIB /
IRMAN BIN MOHAMAD SAID
Contact No.: 65476145

This report is lodged at Pasir Ris NPC Kiosk 1
NP168

Signature Of Informant:
The identity of the person making this report has
been authenticated by Singpass. No signature is
required.

Date/Time:
10/07/2022 22:31

Classification Of Case: