



Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)
Email: motor@wahhong.sg
(199806235M)

Vehicle No. SMH6445P TOYOTA SIENTA HYBRID 1.5X

Page No. 1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$S)	SURVEYOR'S ADJUSTMENT
PARTS (LIST ITEMS)				
1	Bonnet / <i>OD</i>		979.00	845 ✓
2	Bonnet hinge LH/RH @2*\$ 171 ⁷⁰ / <i>OT</i>		342.00	140 ✓
1	Bonnet lock ✓ <i>BT</i>		231.00	122 ✓
1	Front fender LH/RH @2*\$379 / <i>OD</i>		758.00	379 ✓
②	Front fender shield LH/RH @2*\$ 361 ¹⁸⁵ / <i>OR</i>		722.00	370 ✓
2	Front both fender emblem "hybrid" LH/RH @2*\$62 / <i>ALL</i>		124.00	✓
1	Horn Low pitch / <i>OR</i>		231.00	127 ✓
1	Front bumper / <i>MIS</i>		490.00	✓
2	Front bumper side retainer LH/RH @2*\$ 231 ⁶⁷ / <i>OR</i>		462.00	124 ✓
1	Front bumper top center rubber seal / <i>MIS</i>		172.00	✓
1	Front bumper top garnish / <i>MIS</i>		371.00	143 ✓
1	Front bumper under cover / <i>OR</i>		290.00	232 ✓
2	Fog lamp cover LH/RH @2*\$ 231 ¹¹² / <i>MIS</i>		462.00	224 ✓
2	Fog lamp LH/RH @2*\$371 / <i>MIS</i> X Not fitted		742.00	X
1	Center grille / <i>MIS</i>		979.00	596 ✓
1	Center grille towing cover / <i>MIS</i>		62.00	32 ✓
1	Center grille logo badge / <i>MIS</i>		84.00	✓
1	Front bumper sponge / <i>MIS</i>		180.00	95 ✓
1	Front reinforcement / <i>OD</i>		379.00	✓
1	Support panel (Top center panel) / <i>OD</i>		1218.00	891 ✓
②	Headlamp top panel LH/RH @2*\$ 181 ¹³⁰ / <i>OT</i>		362.00	130 ✓
1	Brace panel / <i>OT</i>		231.00	184 ✓
②	Radiator side air guide top LH/RH @2*\$ 179 ¹²⁷ / <i>OR</i>		358.00	254 ✓
2	Radiator side air guide lower LH/RH @2*\$ 179 ¹²⁷ / <i>OR</i>		358.00	254 ✓
1	Radiator top air duct / <i>MIS</i>		371.00	187 ✓
1	Condense ? X <i>NN</i>		1219.00	X
1	Radiator small / <i>BT</i>		1018.00	870 ✓
1	Radiator big ? ✓ <i>BR</i>		1719.00	950 ✓
1	Front door RH (Repair refer to labour) X <i>R</i>		0.00	X
			14914.00	
			-25% -3728.50	
			11185.50	
SPECIAL NETT ITEMS				
1	Front bumper clips / <i>ALL</i>		30 ✓ 35.00	
1	Center grille clips / <i>ALL</i>		30 ✓ 30.00	
1	Front carplate with holder / <i>MIS</i>		35.00	
1	Coolant <i>AA</i> ? ✓ <i>NEC</i>		20 ✓ 50.00	
2	Front fender clips LH/RH / <i>ALL</i>		30 ✓ 50.00	
Total Parts			11385.50	

8398
-25%
6298.50

135



Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)
Email: motor@wahhong.sg
(199806235M)

Vehicle No. SMH6445P TOYOTA SIENTA HYBRID 1.5X

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	SURVEYOR'S ADJUSTMENT
LABOUR			
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	1200.00	1000
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	1200.00	1000
3	To remove and refix wiring system at accident damaged area and check for all electrical proper	60.00	30
4	To perform anti-rust treatment on affected areas	60.00	30
5	To remove/refix and replace air-con condenser, pipes, vacuum and recharging gas.	100.00 ✓	7
Labour Total:		2620.00	
TOTAL (PARTS & LABOUR):		14005.50	

2160

8593.50

supp - 3200

11,793.50

Steve CLKK)
14/7/22, 10.00c

Mr PL
P/P
H ALY
6 dgr

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To identify damaged parts & components
- Parts prices
- Third party survey is on a "no win, no fee" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SMH6445P TOYOTA SIENTA HYBRID 1.5X

Page No. 3

QTY	DESCRIPTION (SUPPLEMENTARY)	CONDITION	REPAIRER'S ESTIMATE(\$)	SURVEYOR'S ADJUSTMENT
PARTS (LIST ITEMS)				
1	Air cleaner box / OR		1219.00	650/
2	Engine lower cover LH/RH @2*\$279 / OR		558.00	250/
2	Headlamp LH/RH @2*\$1010 / BR		2020.00	/
1	Front bumper lower rubber seal / MIS		280.00	/
		-25%	4077.00	
			-1019.25	
			3057.75	
SPECIAL NETT ITEMS				
1	Engine lower cover clips LH/RH / N/C		50.00	24 30
16	Front bumper special clips @16*\$10 / N/C		160.00	140
16	Front bumper screws @16*\$5 / N/C		80.00	40
1	Headlamp light bulb RH / MIS		50.00	25
1	Headlamp beam light bulb RH / MIS		50.00	25
1	Signal light bulb RH / MIS		30.00	20
1	Signal light bulb socket RH / MIS		30.00	20
1	Parking light bulb RH / MIS		30.00	20
1	Parking light bulb socket RH / MIS		30.00	20
1	Headlamp screws & clips RH / N/C		50.00	30
LABOUR				
1	To carried out repair on both chassis LH/RH		300.00	200
2	To carried out repair on both chassis lower LH/RH		300.00	X
3	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired		400.00	200
4	To Carried our focus headlamp		60.00	30
	Store (LKK)	Total Parts	4057.75	

3200
-25%
2400

370

430

= 3200

18/7/22