



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ECICS LTD

10 EUNOS ROAD 8
SINGAPORE POST CENTRE #09-04A
SINGAPORE 408600

Ref: CS/ICS22006653/Ucy3

Date: 13/07/2022

Code: ICS

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLA 819H	Veh. Inspected	SLF 9934Y
Policy No.		Coverage (\$)	0.00
Claim No.	DMPC2200290H	Excess (\$)	0.00
Assign From	LIU CHUN CHEONG	Assign Date	13/07/2022

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	09/07/2022	Inspection Date	14/07/2022
Survey held at	15 Kaki Bukit Road 4 #01-05/53 Bartley Biz Centre		
Repairer	ASIA MOTORSPORTS SOLUTION PTE LTD		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.