

Vehicle Damage Assessment Report for [SMX9995P]

Estimate Created: 13/07/2022 11:11 by LKK_admin-a
(LKK_Auto_Consultants_Pte_Ltd)

Owned: 28/07/2022 00:18 by LKK_cs-a (LKK_Auto_Consultants_Pte_Ltd)

General Information

Insurance Company	III	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Toyota	Model	Prius
Engine Type			
License Plate Number	SMX9995P	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- Pre Review done base on survey information provided
Take note that this review is done before finalization, a final review on repair cost to be concluded after repair.

Note: Please send in the final assessment once resurvey and all information is confirm.

Insurlogic 1 (28/07/2022 00:12)

Pre Review By : Insurlogic
Amount : \$2794.60 (As of current)
Check: \$3972.80
Repair Duration: 4 -5 days (As of current)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
COVER REAR BUMPER		1	485.60	-25.00 %	364.20
REINFORCEMENT SUB ASSY, REAR BUMPER	CHECK /	1	0.00	-25.00 %	0.00
GUARD REAR BUMPER CENTER		1	374.50	-25.00 %	280.88
COVER REAR BUMPER LOWER		1	22.00	-25.00 %	16.50
PANEL SUB ASSY BODY LOWER BACK	CHECK /	1	0.00	-25.00 %	0.00
COVER REAR FLOOR CTR	CHECK /	1	0.00	-25.00 %	0.00
PLATE LUGGAGE COMPARTMENT DOOR NAME NO.2		1	54.60	-25.00 %	40.95
PLATE DOOR NAME NO.1		1	54.60	-25.00 %	40.95
ORNAMANT SUB ASSY, BACK DOOR		1	47.90	-25.00 %	35.93
GARNISH SUB ASSY, BACK DOOR OUTSIDE		1	913.60	-25.00 %	685.20
WEATHERSTRIP BACK DOOR TRIM	CHECK /	1	0.00	-25.00 %	0.00
PARKING AID	CHECK /	1	0.00	0.00 %	0.00

Parts Subtotal 1,464.61

Materials

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
BUMPER CLIPS		1.0	30.00	0.00 %	30.00
WINDSCREEN SEALANT		1.0	80.00	0.00 %	80.00
WINDSCREEN MOULDING		1.0	200.00	0.00 %	200.00
WINDSCREEN INNER SPONGE		1.0	30.00	0.00 %	30.00

Materials Subtotal 340.00

Labor**Replace/RnR**

Description	Type	Cost	Markup/Disc %	Price
ANTI RUST	RnR	30.00	0.00 %	30.00

REMOVE AND REFIX INTERIOR TRIMING AND GARNISH	RnR	60.00	0.00 %	60.00
Panel beat and replacement labour	RnR	300.00	0.00 %	300.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
Painting	Full spray	600.00	0.00 %	600.00
Labor Rate	S\$ 50 / Hour	General Labor Subtotal		390.00
		Paint Labor Subtotal		600.00
		Labor Subtotal		990.00

Summary

Repair Cost	2,794.61
Discount(0 %)	(0.00)
	2,794.61
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	2,794.61