

ASS. REC. BY:

REF:

TU / 220066541kp

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4-5 days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

1 / GIA not ready

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

Not Authored
Pulvin B4 paint

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMX9995P

LAD2207-

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

14 JUL 2022

SMX9995P

JTDKB3FU903091508

201603575K

TOYOTA

PRIUS **GEN 4**

13/07/2022

68L6641 Z / III

09/02/2021

- PART**
- 1 COVER, REAR BUMPER
 - 1 REINFORCEMENT SUB-ASSY, REAR BUMPER
 - 1 GUARD, REAR BUMPER, CENTER
 - 1 SEAL, REAR BUMPER SIDE, LH
 - 1 SEAL, REAR BUMPER SIDE, RH
 - 1 RETAINER, REAR BUMPER SIDE, RH
 - 1 COVER, REAR BUMPER, LOWER
 - 1 COVER, DECK TRIM, REAR
 - 1 PANEL SUB-ASSY, BODY LOWER BACK
 - 1 COVER, FLOOR UNDER, NO.2 (RH)
 - 1 COVER, FLOOR UNDER, NO.1 (LH)
 - 1 COVER, REAR FLOOR (CTR)
 - 1 PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2
 - 1 PLATE, BACK DOOR NAME, NO.1
 - 1 ORNAMENT SUB-ASSY, BACK DOOR
 - 1 GARNISH SUB-ASSY, BACK DOOR, OUTSIDE
 - 1 BOARD ASSY, BACK DOOR TRIM
 - 1 WEATHERSTRIP, BACK DOOR
 - 1 STAY ASSY, BACK DOOR, LH
 - 1 STAY ASSY, BACK DOOR, RH
 - 1 HINGE ASSY, BACK DOOR, LH
 - 1 HINGE ASSY, BACK DOOR, RH

		LIST	
\$	485.60	✓	
\$	332.70	✓	
\$	374.50	✓	
\$	118.30	X	
\$	118.30	X	
\$	132.60	X	
\$	22.00	✓	
\$	126.70	X	
\$	651.00	✓	
\$	241.90	X	
\$	175.10	X	
\$	229.90	✓	
\$	54.60	✓	
\$	54.60	✓	
\$	47.90	✓	
\$	913.60	✓	
\$	259.20	✓	
\$	372.30	X	
\$	242.50	X	
\$	242.50	X	
\$	61.00	X	
\$	61.00	X	
TOTAL	\$ 5,317.80		
25%	\$ 1,329.45		
	\$ 3,988.35		

Special Nett

- 1 REAR BUMPER SIDE CLIP

\$ 60.00 ✓

Trans-cab Auto Services Pte Ltd**LAD2207-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMX9995P

2	WINDSCREEN SEALANT	\$	<i>nn</i>	150.00	<i>3000</i>
1	WINDSCREEN MOULDING	\$	<i>nn</i>	200.00	<i>✓</i>
1	WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i>	130.00	<i>3000</i>
1SET	PARKING AID	\$		700.00	<i>7</i>
1	REAR NUMBER PLATE	\$	<i>nn</i>	180.00	<i>X</i>
1SET	REAR BUMPER CLIP	\$	<i>nn</i>	85.00	<i>X</i>
1	REAR BUMPER RETAINER CLIP	\$	<i>nn</i>	75.00	<i>X</i>
TOTAL		\$		1,780.00	
TOTAL PARTS		\$		5,768.35	

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$		240.00	<i>300</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$		380.00	<i>600</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		1,800.00	<i>?</i>
To transfer of rear end panel fittings, attachment to facilitate bodywork repair.	\$	<i>nn</i>	380.00	<i>X</i>
Putty And Spray Painting Of The Affected Portion.	\$		1,600.00	<i>8000</i>
To reinstall rear bumper parking sensor.	\$		170.00	<i>500</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i>	170.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$		170.00	<i>200</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i>	220.00	<i>X</i>
To remove and refit of rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i>	170.00	<i>X</i>
TOTAL		\$		5,300.00

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMX9995P

LAD2207-

Over All Total \$ 11,068.35

(PART-BY-PART) Repair Days

~~20~~ Days

4-5 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Trans-cab Auto Services Pte Ltd**LAD2207-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMX9995P

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SUPPLEMENTARY**SMX9995P**

JTDKB3FU903091508

201603575K

TOYOTA

PRIUS **GEN 4**

13/07/2022

09/02/2021

- PART**
- 1 PANEL SUB-ASSY, BACK DOOR

		LIST	
		<i>PM</i>	1147.8 ✓
TOTAL	\$		1,147.80
25%	\$		286.95
	\$		860.85