

China (Lisun)

COMFORTDELGRO ENGINEERING PTE LTD

Date: 22.06.2022

REPAIR ESTIMATE

Time: 14:09:14

Page: 1

[Handwritten signature]

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305520684
REGN NO : SHA2667M
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 10.03.2016
DATE/TIME IN : 22.06.2022 11:20
ACCIDENT DATE : 22.06.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT


PART REQUISITION

0001	04-01-0103-0579-G	COVER ASSY-RR BUMPER#	1	553.00	20.00	442.40	<i>inv</i>
0002	04-01-0103-0738-G	COVER-RR BUMPER LWR#	1	228.00	20.00	182.40	<i>Rp</i>
0003	04-01-0103-0739-G	ABSORBER-RR BUMPER ENERGY	1	119.50	20.00	95.60	<i>av</i>
0004	04-01-0103-0740-G	BEAM-RR BUMPER#	1	428.40	20.00	342.72	<i>?</i>
0005	04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60	<i>all</i>
0006	04-01-0103-0742-G	STAY-RR BUMPER LH	1	160.60	20.00	128.48	<i>?</i>
0007	04-01-0103-0743-G	STAY-RR BUMPER RH	1	160.60	20.00	128.48	<i>?</i>
0008	09-01-9999-0068-A	REVERSE SENSOR ASSY*	1 N	135.70	2.00-	135.70	<i>X</i>

SUB-TOTAL : 1,473.38

JOB NATURE

0000	PB	PANEL BEATING		300.00		<i>280</i>
0001	SP	SPRAYPAINT CHARGE		300.00		<i>250</i>
0002	L	REMOVE/REFIX REVERSE SENSOR		50.00		<i>X</i>



COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305520684
REGN NO : SHA2667M
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 10.03.2016
DATE/TIME IN : 22.06.2022 11:2
ACCIDENT DATE : 22.06.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

SUB-TOTAL : 650.00

TOTAL : 2,123.38

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Tanfhi 97495747
WR' 22/6/22 @ 4:30
= 2 days
4/5 days after repair
Tanfhi @ lkkauto.com

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SMS

Team: ARC Repair TP(CLS0)1

JOB CARD Sales Order: 4298901

JC NO305520684


STOMER /MS COMFORT TRANSPORTATION PTE LTD STOMER NO. 7010045 DRESS 383 SIN MING DRIVE Singapore SINGAPORE 575717 (R) 65508755 (O) (P) COUNT CARD NO.	REGN NO.: SHA2667M	MILEAGE
	MAKE: HYUNDAI	FUEL E.....1/2.....F
	MODEL I-40	DATE/TIME IN 22.06.2022 11:20
	YR OF MANU. 10.03.2016	TARGET DATE
	CHASSIS CODE KMHLB41UMGU085531	COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 22.06.2022
NATURE: 3P 22.06.22

SJJ 76906

S/NO	LABOR CODE	DESCRIPTION
------	------------	-------------



Usum

CHECKED & PASSED OUT BY:

SERVICE ADVISOR	CUSTOMER'S SIGNATURE
-----------------	----------------------

wedgement Slip

Exit Pass

No.: **SHA2667M** **JU CHINA**

Vehicle No.: **SHA2667M**

of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard