

China (Lisun)

COMFORTDELGRO ENGINEERING PTE LTD

Date: 22.06.2022

Time: 14:09:14

Page: 1

*Handwritten signature*

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305520684  
REGN NO : SHA2667M  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : I-40  
DATE OF REGN : 10.03.2016  
DATE/TIME IN : 22.06.2022 11:20  
ACCIDENT DATE : 22.06.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-0579-G	COVER ASSY-RR BUMPER#	1	553.00	20.00	442.40	<i>inc</i>
0002	04-01-0103-0738-G	COVER-RR BUMPER LWR#	1	228.00	20.00	182.40	<i>part</i>
0003	04-01-0103-0739-G	ABSORBER-RR BUMPER ENERGY	1	119.50	20.00	95.60	<i>air</i>
0004	04-01-0103-0740-G	BEAM-RR BUMPER#	1	428.40	20.00	342.72	<i>Xun</i>
0005	04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60	<i>nee</i>
0006	04-01-0103-0742-G	STAY-RR BUMPER LH	1	160.60	20.00	128.48	<i>Xun</i>
0007	04-01-0103-0743-G	STAY-RR BUMPER RH	1	160.60	20.00	128.48	<i>Xun</i>
0008	09-01-9999-0068-A	REVERSE SENSOR ASSY*	1 N	135.70	2.00-	135.70	<i>Xun</i>

*20% 922 737-60*

SUB-TOTAL : 1,473.38

JOB NATURE

0000	PB	PANEL BEATING	300.00	<i>280</i>
0001	SP	SPRAYPAINT CHARGE	300.00	<i>250</i>
0002	L	REMOVE/REFIX REVERSE SENSOR	50.00	<i>30</i>

*Vertical stamp with mirrored text: LKX Auto Components Pte Ltd, The Republic of Singapore, To resolve any disputes...*

*1297-60  
1/5 91050  
02 days  
#*