

BIFROST AUTO PTE LTD

REPAIR ESTIMATE (Supplementary)

DATE: 19-Jul-22

INSURANCE: MS FCI

MODEL: HYUNDAI IONIC

VEHICLE NO.: SHA 7978 H

Description	Qty	List Price	Amount
Radiator Spare Tank <i>crack mounty</i>	1	\$ 196.50	\$ 196.50
Frt Door(RH) <i>MM</i>	1	\$ 1,797.20	\$ 1,797.20
SUB TOTAL			\$ 1,993.70
LESS 20%			\$ 398.74
DISCOUNTED TOTAL			\$ 1,594.96
Front Door Advertisement Logo (RH) <i>MM</i> SN	1	\$ 100.00	\$ 100.00
SUB TOTAL			\$ 100.00
ESTIMATE TOTAL			\$ 1,694.96

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company. Please send your book value request to: claims_ltr@bifrostauto.com

Ryan

L&K Auto

R

196.50

20% (157.20)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: