



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 9055C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT PANEL ASSY (SN)	DENTED	5,200.00	3,500.00
1	FRONT PANEL LOGO (SN)	NECESSARY	150.00	150.00
1	FRONT WINDSCREEN GLASS RUBBER (SN)	NECESSARY	530.00	300.00
1	FRONT CORNER BUMPER RH (SN)	DEFORMED	2,350.00	950.00
1	FRONT BUMPER BRACKET RH (SN)	NOT NECESSARY	185.00	-
1	FRONT BUMPER FOG LAMP RH (SN)	CRACKED	425.00	350.00
1	FRONT BUMPER FOG LAMP COVER (SN)	NOT NECESSARY	165.00	-
1	FRONT BUMPER DAYLIGHT RH (SN)	CRACKED	455.00	320.00
1	FRONT GRILLE LED LAMP (CENTRE) (SN)	CRACKED	980.00	800.00
1	FRONT GRILLE LED LAMP CLIPS (SN)	NECESSARY	30.00	30.00
1	FRONT CENTRE BUMPER (SN)	NOT NECESSARY	3,800.00	-
1	FRONT NUMBER PLATE (SN)	NOT NECESSARY	50.00	-
1	HEADLAMP RH (SN)	CRACKED	1,250.00	1,250.00
1	FRONT DOOR PILLAR RH (SN)	NOT NECESSARY	936.00	-
1	FRONT SIDE MIRROR RH (SN)	TO REPAIR SEE LABOUR	950.00	-
1	FRONT WIPER GARNISH (BLACK) (SN)	NOT NECESSARY	1,800.00	-
1	FRONT WIPER ARM RH (SN)	CUT	380.00	120.00
1	SET FRONT BODY PANEL SEALANT (SN)	NECESSARY	350.00	120.00
1	SET WINDSCREEN SEALANT (SN)	NECESSARY	300.00	120.00
			20,286.00	8,010.00
	<b><u>LABOUR</u></b>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT SIDE MIRROR RH.		2,000.00	800.00
	SPRAY PAINTING -2 TONES.		2,000.00	600.00
	ANTI RUST.		250.00	100.00
	CHECK WIRING ON HEADLAMP .		150.00	50.00
	REMOVE AND INSTALL FRONT WINDSCREEN FOR PANEL REPAIR.		350.00	250.00
			4,750.00	1,800.00
	<b>GRAND TOTAL</b>		<b>25,036.00</b>	<b>9,810.00</b>

Report Ref No. CS/FCI22006662/Any3q2



<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>7,800.00</b>
---	--	--	-----------------

Report Ref No. CS/FCI22006662/Any3q2

**ADRIAN LING WAI PING**

**B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.