



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581			Ref: CS/FCI22006662/Any3q2	
			Date: 24/11/2022	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	PC 2503Y	Veh. Inspected	PC 9055C	
Policy No.	D-22099240MFCV/1486	Coverage (\$)	0.00	
Claim No.	D22002008MFCV	Excess (\$)	0.00	
Assign From	HARMINDER KAUR	Assign Date	14/07/2022	
2. Vehicle Particulars & Condition				
Make & Model	YUTONG ZK6958HQ	c.c	6690	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	LZYTCTE64H1039655	Colour	GREY	
Odometer	154906 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	275/70 R22.5	AEOLUS	8 mm	
L/H Front Tyre	275/70 R22.5	AEOLUS	8 mm	
R/H Rear Tyre	275/70 R22.5	AEOLUS	8 mm	
L/H Rear Tyre	275/70 R22.5	AEOLUS	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/06/2022	Inspection Date	14/07/2022	
Survey held at	KT MOTORWERK 3012 BEDOK INDUSTRIAL PARK E, #01-2020, BEDOK INDUSTRIAL PARK E, SINGAPORE 489978			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	