

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

國際汽車維修 KT MOTORWERK

Blk 3012 Bedok Ind. Park E #01-2020 Singapore 489978.
(Bedok North Ave. 4) Tel: 98287487 Fax: 6448 5177
Email: ktmotorwerk@hotmail.com
Reg. No.: 53373462B

Vehicle Number : PC 9055C

Vehicle Model : ZK6958HQAUTO YUTONG

Accident Date : 28.06.2022

Original Reg Date : 01.07.2020

Date : 15.07.2022

Chassis : LZYTCTE64H1039655

TP : FIRST CAPITAL

Xiao Chun.

ESTIMATE

Special Nett

1	1 pc	Front Panel Assy	Dented.	5,200.00	3500
2	1 pc	Front Panel LOGO	new	150.00	✓
3	1 pc	Front Windscreen Glass Rubber	new	530.00	300.
4	1 pc	Front corner Bumper RH	Deformed	2,350.00	950
5	1 pc	Front Bumper Bracket RH	new	185.00	+
6	1 pc	Front Bumper Fog Lamp RH	Cracked.	425.00	350.
7	1 pc	Front Bumper Fog Lamp Cover	new	165.00	X
8	1 pc	Front Bumper DAYLIGHT RH	Cracked	455.00	320.
9	1 pc	Front Girllle LED LAMP (CENTRE)	Cracked.	980.00	800.
10	1 pc	Front Girllle LED LAMP CLIPS	new	30.00	✓
11	1 pc	Front CENTRE BUMPER	new	3,800.00	X
12	1 pc	Front NUMBER PLATE	new	50.00	+
13	1 pc	Headlamp RH	Cracked	1,250.00	✓
14	1 pc	Front Door Pillar RH	new	936.00	+
15	1 pc	FRONT SIDE MIRROR RH	Repair	950.00	+
16	1 pc	FRONT WIPER GARNISH(BLACK)	new	1,800.00	+
17	1 pc	FRONT WIPER ARM RH	new	380.00	120.
18	1 SET	FRONT BODY PANEL SEALANT	new	350.00	120.
19	1 SET	WINDSCREEN SEALANT	new	300.00	120
SUBTOTAL				20,286.00	8010

Labour charge

Panel Beating	2,000.00	800
Spray painting - 2 Tones	2,000.00	600
Anti rust	250.00	100
Check Wiring on headlamp	150.00	50.
Remove and install front windscreen for panel repair	350.00	250
TOTAL	\$ 25,036.00	

1800

7.8K

Total: 9810

4/5: 7.8K

06 Days