

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

HL Assurance Pte Ltd  
11 Keppel Road, #11-01 ABI Plaza  
Singapore 089057

**Our File No:** CS/HLA22006664/UVY3M4**Date:** 02/08/2022**REFERENCE**

Insured/Claimant:	ANG YI CHEN IAN	Policy No:	MP309854		
Date of Loss:	08/07/2022	Nature of Claim:	OD	Claim No:	MPC03550/ANA

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SLZ2479K</b>	Engine No:	HR12285054B
Make & Model:	NISSAN NOTE, 1.2 (A)	Chassis No:	JN1TAAE12Z0980432
Reg. Date:	26/04/2018 (Man. Year: 2018)	Odometer:	42113 km
Colour:	Grey		
Engine Capacity:	1198 cc		
Market Value/New Car Price:	S\$56,000.00		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,563.00	1,738.00	825.00	32.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	300.00	230.00	70.00	23.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>2,863.00</b>	<b>1,968.00</b>	<b>895.00</b>	<b>31.26</b>
<b>- Excess (\$\$)</b>	0.00	500.00	-500.00	
<b>(\$\$)</b>	2,863.00	1,468.00	1,395.00	48.73
<b>+ GST 7.00/7.00% (\$\$)</b>	200.41	102.76	97.65	48.73
<b>Nett Amount (\$\$)</b>	<b>3,063.41</b>	<b>1,570.76</b>	<b>1,492.65</b>	<b>48.73</b>

**INSPECTION**

Date of Assignment:	13/07/2022	Present Location:	SME Motor Pte Ltd (Kaki Bukit)
Date Inspected:	14/07/2022	Inspected At:	SME Motor Pte Ltd (Kaki Bukit) 1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	2.0 days		

**Adjuster:** MARCUS CHUA**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Aug 2022)
Parts:	144	NISSAN NOTE 1.2 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLZ2479K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT RH SHOCK ABSORBER (WCP)	Bent	235.00 F	*235.00 F
2	1		*FRT RH LOWER ARM (WCP)	Bent	180.00 F	*180.00 F
3	1		*FRT RH KNUCKLE ARM (WCP)	Bent	395.00 F	*395.00 F
4	1		*FRT RH KNUCKLE BEARING (WCP)	Necessary	95.00 F	*95.00 F
5	1		*FRT RH RACK END (WCP)	Bent	105.00 F	*105.00 F
6	1		*FRT RH TIE ROD END (WCP)	Bent	120.00 F	*120.00 F
7	1		*FRT RH SPORTS RIM (WCP)	Cut	1,200.00 F	*450.00 F
						F=Franchise part.
					Sub Total (\$\$)	2,330.00 1,580.00
					+ Margin on L,N Items 10.00/10.00% (\$\$)	233.00 158.00
					Total Parts (\$\$)	2,563.00 1,738.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	<b>REMOVE &amp; REFIX FRT UNDERCARRIAGE</b> (REPLACED INSTEAD OF REFIX)	New	220.00	150.00
2	<b>WHEEL ALIGNMENT</b>	Repair	80.00	80.00
<b>Gross Labour Cost (\$\$)</b>			<b>300.00</b>	<b>230.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >