## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: HL Assurance Pte Ltd From: LKK Auto Consultants Pte Ltd

11 Keppel Road51 Ubi Ave 1 #01-25#11-01 ABI PlazaPaya Ubi Industrial ParkSingapore 089057Singapore 408933

Attn: ALANO Ana Maria Velarde Date: 14 Jul 2022

# **Preliminary Advice**

Vehicle No : SLZ2479K Accident Date : 08/07/2022 Make : NISSAN NOTE Policy No. : MP309854 Assignment Date Excess : 13/07/2022 : S\$0.00 Date of Inspection : 14/7/2022 Est. Duration of Repair : 2

Inspection At :SME MOTOR PTE LTD

#### Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,863.00
Revised Amount	:S\$	2,089.00
Check Items (Estimated)	:S\$	704.00
Total	:S\$	2,793.00

Lump Sum Repair :S\$

#### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	56,000.00
COE / PARF Rebate	:S\$	25,716.00
Salvage Value	:S\$	

Margin for Repair :S\$ 30,284.00

### Remarks

( X )	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let
	us have your authorisation.

( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: Part by part repair as there is no 2nd hand parts available

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .