

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No: 19960/198R GST Reg. No. 19-960/198-R						
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	Re	ef:	CS/AGI22006671/Kvy3m4	
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Da	ate:	08/08/2022	
			Co	ode:	AGI	
1.	. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SMZ 3239T	Veh. Inspected		SMP 7128G	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10016329/JM	Excess (\$)		0.00	
	Assign From	SHAFAWATI MD RABU	Assign Date		14/07/2022	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA SHUTTLE (A)	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	GP72004590	Colour		METALLIC DARK BLUE	
	Odometer	156297 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	185/60 R15	INTERTRAC		9 mm	
	L/H Front Tyre	185/60 R15	INTERTRAC		9 mm	
	R/H Rear Tyre	185/60 R15	INTERTRAC		9 mm	
	L/H Rear Tyre	185/60 R15	INTERTRAC		9 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	12/07/2022	Inspection Date		14/07/2022	
	Survey held at	OPTIMA WERKZ PTE LTD				
		10 ANG MO KIO INDUSTRIAL PARK 2A #01-05 AMK AUTOPOINT SINGAPORE 568047				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	1= /	Estimate Days of Repair				

3 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: