

OPTIMA WERKZ SINGAPORE

OPTIMA WERKZ PTE LTD
Co. Reg. No. 201212455W
www.ow.sg

OptimaWerkz

Date: 13/07/2022

Vehicle No: SMP7128G

Model: HONDA SHUTTLE HYBRID 1.5

Chassis: GP72004590-2018

Reg. Year: 2019

Third Party Insurer: AGI

Third Party Veh No: SMZ3239T

Date of Accident: 12/07/2022

Estimator: TING AN

Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT HEADLAMP RH	1		2,315.50
2	FRONT HEADLAMP LOWER BRACKET RH	1		53.50
3	FRONT BUMPER	1		988.60
4	FRONT BUMPER SIDE BRACKET RH	1		25.90
5	FRONT BUMPER FOG LAMP GARNISH COVER RH	1		35.50
6	FRONT FENDER RH	1		455.50
7	FRONT FENDER "HYBRID" EMBLEM	1		65.50
8	FRONT FENDER INNER SHIELD RH	1		125.90
SUB TOTAL				\$4,065.90
LESS 20%				-\$813.18
PARTS TOTAL				\$3,252.72

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER CLIPS	1		50.00
2	FRONT FENDER INNER SHIELD CLIPS RH	1		40.00
S/N TOTAL				\$90.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX & READJUST FRONT ACCIDENT AREAS & ETC.

\$500.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER, FRONT FENDER RH & ETC.

\$500.00

TO DIAGNOSIS FAULT CODE & RESET MEMORY.

\$120.00

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.

\$80.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be returned and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Branch (Motor Insurance Claims)

Head office

8 Kung Chong Road Singapore 159143

Tel: (+65) 6472 1313 | Fax: (+65) 6472 2132

Branch

9A Serangoon North Ave 5 Singapore 554600

Tel: (+65) 6484 9919 | Fax: (+65) 6484 9923

Bk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 56804

Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

