

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/GRB21005675/TQY3E2-1

Date: 10/08/2022

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447
Claimant Vehicle No : FBP3551Z **Insured Vehicle No :** SLP9774P
Date of Loss: 02/05/2021 Nature of Claim: TP Claim No: MFL2021D0001911

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBP3551Z**
Make & Model: HONDA WAVE 125, 125cc Engine No: NF125MPE0030942
Reg. Date: 22/03/2005 (Man. Year: 2004) Chassis No: NF125MP0030942
Colour: Red Odometer: 38553 km
Engine Capacity: 125 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 80/90 R17 Rear Tyre Size: 90/80 R17
Front Left Side: Pirelli 5 mm Rear Left Side: Pirelli 5 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|-------------------|-------------------|---------------|
| Parts | 3,695.00 | 2,374.40 | 1,320.60 | 35.74 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,300.00 | 640.00 | 660.00 | 50.77 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 4,995.00 | 3,014.40 | 1,980.60 | 39.65 |
| Approved Total (Overridden) (S\$) | | 2,400.00 | | |
| Nett Amount (S\$) | 4,995.00 | 2,400.00 | 2,595.00 | 51.95 |

INSPECTION

Date of Assignment: 13/07/2022
Date Inspected: 10/05/2021 Inspected At: Equator Brotherhood (HQ)
Singapore 417800
Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | | |
|----------------------|--|--|
| Part Source: | (Last Synchronised: 10 Aug 2022) | |
| Parts: | N/A | HONDA WAVE 125 125cc (Model not available in database) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for FBP3551Z) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|------------------------------------|----------------------|------------|------------|
| 1 | 1 | | *HONDA FAIRING SET (SILVER) | Cracked / Grazed | 380.00 F | *300.00 FL |
| 2 | 1 | | *HONDA FAIRING SET (MATTE BLACK) | Grazed / Cracked | 180.00 F | *150.00 FL |
| 3 | 1 | | *HONDA FRONT RIM | Warped / Wobble | 200.00 F | *165.00 FL |
| 4 | 1 | | *HONDA FRONT SUSPENSION (LEFT) | Distorted / Affected | 380.00 F | *280.00 FL |
| 5 | 1 | | *HONDA FRONT SUSPENSION (RIGHT) | Distorted / Affected | 380.00 F | *280.00 FL |
| 6 | 1 | | *HONDA TRIPLE CLAMP (BOTTOM) | Distorted / Affected | 285.00 F | *160.00 FL |
| 7 | 1 | | *HONDA STEERING CONE BEARING | Necessary | 120.00 F | *120.00 FL |
| 8 | 1 | | *HONDA HANDLEBAR | Distorted / Affected | 95.00 F | *95.00 FL |
| 9 | 1 | | *HONDA HANDLEBAR BRACKET | Repair | 65.00 F | *- FL |
| 10 | 2 | | *HONDA FRONT WHEEL BEARING | Rattle | 70.00 F | *70.00 FL |
| 11 | 2 | | *HONDA FRONT WHEEL SEAL | Necessary | 30.00 F | *30.00 FL |
| 12 | 1 | | *HONDA FRONT WHEEL SHAFT | Repair | 60.00 F | *- FL |
| 13 | 1 | | *HONDA BRAKE LEVER | Scratched | 25.00 F | *25.00 FL |
| 14 | 1 | | *HONDA BRAKE LEVER PIN | Necessary | 15.00 F | *15.00 FL |
| 15 | 1 | | *HONDA BRAKE LEVER HOLDER | Not Necessary | 30.00 F | *- FL |
| 16 | 1 | | *HONDA FRONT BRAKE MASTER CYLINDER | Not Necessary | 120.00 F | *- FL |
| 17 | 1 | | *HONDA FRONT BRAKE HOSE | Not Necessary | 85.00 F | *- FL |
| 18 | 2 | | *HONDA MIRROR MOUNTING SCREW | Necessary | 20.00 F | *20.00 FL |
| 19 | 2 | | *HONDA MIRROR | Grazed | 70.00 F | *70.00 FL |
| 20 | 1 | | *HONDA FRONT HEADLIGHT | Scratched | 240.00 F | *180.00 FL |
| 21 | 2 | | *HONDA FRONT SIGNAL LIGHTS | Scratched | 130.00 F | *116.00 FL |
| 22 | 1 | | *HONDA PLASTIC BASKET | Cracked | 60.00 F | *60.00 FL |
| 23 | 2 | | *HONDA PLASTIC BASKET BRACKET | Bent | 30.00 F | *30.00 FL |
| 24 | 1 | | *KAPPA BOX | Grazed | 180.00 FS | *180.00 FS |
| 25 | 1 | | *KAPPA BOX BASE PLATE | Necessary | 85.00 FS | *85.00 FS |
| 26 | 1 | | *KAPPA BOX RACK | Not Necessary | 140.00 FS | *- FS |
| 27 | 1 | | *CNC BAR END BALANCER | Grazed | 120.00 FS | *60.00 FS |
| 28 | 1 | | *IU UNIT | Grazed | 50.00 FS | *50.00 FS |
| 29 | 1 | | *FRONT WINDSHIELD | Broken | 50.00 FS | *50.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|---|-----------------|-----------------|
| Sub Total (\$\$) | 3,695.00 | 2,591.00 |
| - List Item Discount on L Items 0.00/10.00% (\$\$) | 0.00 | 216.60 |
| Total Parts (\$\$) | 3,695.00 | 2,374.40 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------|---|----------|-------------------------------|-----------------|
| Labour Items | | | | |
| 1 | TO REMOVE & REPLACE FRONT RIM, FRONT WHEEL BEARING, AXLE SHAFT, TRIPPLE CLAMPS, FRONT FORK, STEERING CONE, FRONT BRAKE DISC | New | 250.00 | 120.00 |
| 2 | TO REMOVE & REPLACE ABOVE BODY DAMAGED PARTS, CHECK WIRING & LIGHTING SYSTEM | New | 450.00 | 200.00 |
| 3 | TO CONDUCT CHASSIS ALIGNMENT | New | 480.00 | 200.00 |
| 4 | TOWING - WORKSHOP TO ACCIDENT REPORTING CENTER | New | 60.00 | 60.00 |
| 5 | TOWING - ACCIDENT REPORTING CENTER TO WORKSHOP | New | 60.00 | 60.00 |
| | | | Gross Labour Cost (\$) | 1,300.00 |
| | | | | 640.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >