

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 13.07.2022

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
VEHICLE NO : SMS1599D *Veron.*
MODEL : KIA CARENS
DATE OF ACCIDENT : 12.07.2022
TIME OF ACCIDENT : 17:00HRS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER (UPPER)	1	\$ 598.00	\$ 598.00
2	REAR BUMPER (LOWER) <i>Distorted</i>	1	\$ 387.00	\$ 387.00
3	REAR BUMPER DIFFUSER	1	\$ 288.00	\$ 288.00
4	REAR BUMPER LAMP <i>cracked</i>	2	\$ 116.00	\$ 232.00
5	REAR BUMPER SIDE INNER GARNISH <i>ton</i>	2	\$ 153.00	\$ 306.00
6	REAR BUMPER TOWING COVER <i>Missing</i>	1	\$ 20.00	\$ 20.00
7	REAR BUMPER SENSOR <i>3 pieces damaged</i>	4	\$ 187.00	\$ 748.00
8	REAR BUMPER SENSOR HOLDER <i>New</i>	4	\$ 36.00	\$ 144.00
9	REAR BUMPER SENSOR WIRE HARNESS <i>new</i>	1	\$ 348.00	\$ 348.00
10	REAR BUMPER BRACKET <i>2nd</i>	5	\$ 21.00	\$ 105.00
11	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 39.00	\$ 78.00
12	REAR BUMPER MUDFLAP <i>new</i>	2	\$ 165.00	\$ 330.00
13	REAR BUMPER REINFORCEMENT <i>Distorted</i>	1	\$ 428.00	\$ 428.00
14	REAR BUMPER REINFORCEMENT BRACKET <i>Distorted</i>	2	\$ 152.00	\$ 304.00
15	TAILGATE <i>Distorted</i>	1	\$ 1,088.00	\$ 1,088.00
16	TAILGATE LAMP <i>new</i>	2	\$ 243.00	\$ 486.00
17	TAILGATE LOGO <i>3 new</i>	1	\$ 76.00	\$ 76.00
18	TAILGATE EMBLEM 'CARENS'	1	\$ 64.00	\$ 64.00
19	TAILGATE EMBLEM 'LIMITED EDITION' <i>new</i>	1	\$ 86.00	\$ 86.00
20	TAILGATE EMBLEM 'CROI' <i>3 new</i>	1	\$ 59.00	\$ 59.00
21	TAILGATE EMBLEM 'TURBO' <i>new</i>	1	\$ 66.00	\$ 66.00
22	TAILGATE DETECTOR <i>cracked</i>	1	\$ 346.00	\$ 346.00
23	TAILGATE DETECTOR WIRE HARNESS <i>new</i>	1	\$ 259.00	\$ 259.00
24	TAILGATE STOPPER <i>new</i>	2	\$ 14.00	\$ 28.00
25	TAILGATE LOCK CATCH <i>new</i>	1	\$ 19.00	\$ 19.00
26	TAILGATE WEATHER STRIP <i>cut</i>	1	\$ 168.00	\$ 168.00
27	TAILLAMP <i>cut</i>	2	\$ 397.00	\$ 794.00

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : SMS1599D
 MODEL : KIA CARENS
 DATE OF ACCIDENT : 12.07.2022
 TIME OF ACCIDENT : 17:00HRS

28	REAR FENDER INNER COWLING <i>new</i>	2	\$ 224.00	\$ 448.00	+
29	REAR FENDER INNER TRIM <i>RH cml'd</i>	2	\$ 474.00	\$ 948.00	474 365
30	REAR END PANEL <i>Dented</i>	1	\$ 594.00	\$ 594.00	✓
31	REAR END PANEL TOP GARNISH <i>Dented</i>	1	\$ 127.00	\$ 127.00	✓
32	REAR STORAGE BOX <i>cml'd</i>	1	\$ 386.00	\$ 386.00	✓
33	REAR CHASSIS MEMBER RH <i>Repair</i>	1	\$ 846.00	\$ 846.00	+
34	REAR EXHAUST BOX	1	\$ 740.00	\$ 740.00	+
35	REAR EXHAUST INSULATOR	1	\$ 142.00	\$ 142.00	+
36	REAR EXHAUST GASKET (SET)	1	\$ 60.00	\$ 60.00	+
37	REAR EXHAUST MOUNTING <i>not ne</i>	6	\$ 29.00	\$ 174.00	+
38	REAR SPARE TYRE	1	\$ 564.00	\$ 564.00	+
39	REAR SPARE TYRE CABLE BOX	1	\$ 288.00	\$ 288.00	+

7519
6767-10

TOTAL PRICE \$ 13,172.00
 LESS 10% \$ 1,317.20
 SUB TOTAL PRICE \$ 11,854.80

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>Best</i>	1	\$ 50.00	\$ 50.00	✓
2	REAR BUMPER (UPPER) CLIP (SET) <i>3/4</i>	1	\$ 80.00	\$ 80.00	20
3	REAR BUMPER (LOWER) CLIP (SET)	1	\$ 80.00	\$ 80.00	20
4	TAILGATE SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00	+
5	TAILGATE EMBLEM 'CYCLE & CARRIAGE' <i>new</i>	1	\$ 150.00	\$ 150.00	45
6	TAILGATE DAMPER (ELECTRICAL)(SPECIAL TYPE) <i>new</i>	1	\$ 1,400.00	\$ 1,400.00	+600.
7	TAILGATE INNER TRIM REFLECTOR <i>new</i>	2	\$ 20.00	\$ 40.00	+
8	TAILGATE INNER TRIM CLIP <i>new</i>	1	\$ 50.00	\$ 50.00	30
9	TAILGATE INNER LOCK C/W MOTOR (SPECIAL TYPE) <i>new</i>	1	\$ 1,200.00	\$ 1,200.00	400
10	TAILGATE OPENING FOOT SENSOR (SPECIAL TYPE) <i>new</i>	1	\$ 850.00	\$ 850.00	X
11	TAILGATE WINDSCREEN SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	40
12	TAILGATE WINDSCREEN INNER SHIELD <i>new</i>	1	\$ 60.00	\$ 60.00	40
13	TAILGATE SIDE LINING <i>new</i>	1	\$ 80.00	\$ 80.00	30
14	TAILGATE STICKER 'CARENS' <i>new</i>	1	\$ 60.00	\$ 60.00	20
15	TAILGATE TURBO PAD <i>new</i>	1	\$ 50.00	\$ 50.00	40
16	TAILLAMP CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	20
17	REAR FENDER INNER COWLING CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
18	REAR FENDER INNER TRIM CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	30
19	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00	60
20	REAR END PANEL TOP GARNISH CLIP (SET) <i>new</i>	1	\$ 40.00	\$ 40.00	10
21	REVERSE CAMERA <i>new</i>	1	\$ 450.00	\$ 450.00	X

TOTAL \$5,230.00

1425

TO : CHINA TAIPIING MOTOR CLAIMS DEPTS
 VEHICLE NO : SMS1599D
 MODEL : KIA CARENS
 DATE OF ACCIDENT : 12.07.2022
 TIME OF ACCIDENT : 17:00HRS

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 2,000.00	800
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	800
3	TUFF COAT	\$ 350.00	80
4	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY & ROOF LINING TO FACILITATE REPAIR	\$ 350.00	80
5	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
6	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	50
7	TRANSFER TAILGATE MECHANISM	\$ 80.00	/
8	CONDUCT WATER LEAKAGE TEST	\$ 250.00	x
9	RESET TAILGATE AUTO SYSTEM	\$ 350.00	120
10	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	x
11	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	✓
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 350.00	x.

TOTAL \$5,790.00

ESTIMATE REPORT

TOTAL PARTS COST : \$17,084.80
 TOTAL LABOUR COST : \$5,790.00
 TOTAL REPAIR COST : \$22,874.80

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP :8297 9787

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

total: 10382.10
 r/s: 8.3k.
 06 Days.

8.3k

2180