

BODYFIX

NO 10 ANG MO KIO INDUSTRIAL PARK 2A #04-06

AMK AUTOPOINT SINGAPORE 568047

Tel No. : 62571289 Fax No. : 64837432

E-Mail : bodyfix@singnet.com.sg

Tax Reg. No. : 53010635C Buss. Reg. No. : 53010635C

AXA INSURANCE PTE LTD
8 SHENTON WAY #27-01
AXA TOWER SINGAPORE 068811

Attention : Motor Claim Department

Contact : 3387288 Fax No. : 8804838

Estimate : ES220714

Date : 13/07/2022

Vehicle Num. : SMN 4948 L

Make/Model : HONDA FREED-2018

Chassis/Eng# : GB71085793/LEB5623460

Accident Date : 07/07/2022

Claim No. :

Reference :

Policy No. :

*Not Withheld
Primary Repair
4 days**Henrich**96910663**@ 5096.08**19/7/22*

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

- | | | | | |
|-----|--------|------------------------------|------------|--|
| 1. | REPAIR | LIST ITEMS : | | |
| 2. | 1PC | REAR FENDER (RH) | | |
| 3. | 1PC | REAR BUMPER | <i>828</i> | |
| 4. | 1PC | REAR BUMPER SIDE RETAINER RH | | |
| 5. | 1PC | REAR BUMPER REFLECTOR RH | | |
| 6. | 1PC | REAR END PANEL | | |
| 7. | 1PC | REAR END PANEL TOP GARNISH | | |
| 8. | 1PC | TAILGATE | | |
| 9. | 1PC | TAILGATE WEATHERSTRIP | | |
| 10. | 1PC | TAILGATE INNER TRIM BOARD | | |
| 11. | 1PC | EMBLEM 'FREED' | | |
| 12. | 1PC | EMBLEM 'HYBRID' | | |
| 13. | 1PC | LOGO 'H' | | |
| 14. | 1PC | REAR WINDSCREEN MOULDING | | |
| 15. | 1PC | TAILGATE REFLECTOR RH | | |
| 16. | 1PC | TAIL LAMP RH | | |
| | | REAR BUMPER TOWING COVER | | |

List Total S\$:

- | | | | | |
|----|------|-------------------------|--|--|
| 1. | 1PC | SPECIAL NETT ITEMS : | | |
| 2. | 1SET | REAR WINDSCREEN SEALANT | | |
| | | REVERSE SENSOR | | |

Special Nett Total S\$:

LABOUR :

RUST-PROOFING ON THE REAR ACCIDENT AFFECTED PORTIONS

<i>my car / Bu</i>	919.40	<i>2</i>
<i>oil</i>	35.60	<i>1</i>
<i>cm</i>	42.80	<i>1</i>
<i>R</i>	523.70	<i>X</i>
<i>su</i>	155.40	<i>X</i>
<i>B</i>	1,200.20	<i>1</i>
<i>m</i>	168.20	<i>X</i>
<i>m</i>	388.40	<i>X</i>
<i>na</i>	55.40	<i>1</i>
<i>na</i>	75.40	<i>1</i>
<i>na</i>	32.50	<i>1</i>
<i>na</i>	95.40	<i>1</i>
<i>h</i>	360.20	<i>X</i>
<i>my car</i>	629.40	<i>2</i>
<i>oil</i>	39.50	<i>1</i>
	4,721.50	

<i>m</i>	80.00	<i>40.00</i>
<i>su</i>	400.00	<i>X</i>
	480.00	

100.00 *30%*

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

BODYFIX

NO 10 ANG MO KIO INDUSTRIAL PARK 2A #04-06
AMK AUTOPOINT SINGAPORE 568047
Tel No. : 62571289 Fax No. : 64837432
E-Mail : bodyfix@singnet.com.sg
Tax Reg. No. : 53010635C Buss. Reg. No. : 53010635C

XA INSURANCE PTE LTD
SHENTON WAY #27-01
KA TOWER SINGAPORE 068811

ention : Motor Claim Department
ntact : 3387288 Fax No. : 8804838

Estimate : ES220714

Date : 13/07/2022
Vehicle Num. : SMN 4948 L
Make/Model : HONDA FREED-2018
Chassis/Eng# : GB71085793/LEB5623460
Accident Date : 07/07/2022
Claim No. :
Reference :
Policy No. :

Quantity	Particular	Unit Price	Amount S\$
	TO CHECK&TEST LIGHTING FUNCTIONS & REVERSE SENSOR WIRING		80.00 <i>501</i>
	TO REMOVE AND REFIT REAR WINDSCREEN TO ASSIST REPAIR		120.00 ✓
	LABOUR TO REPLACE ABOVE PARTS, PANEL BEAT, REPAIR & RE-ALIGN DAMAGE PARTS		1,200.00 <i>700</i>
	TO PUTTY & SPRAY PAINT REAR END PANEL, REAR BUMPER, TAILGATE, REAR FENDER RIGHT & OTHER AFFECTED AREAS		1,500.00 <i>800</i>
	Labour Total S\$:		3,000.00

Eight Thousand Two Hundred One & Cents Fifty Only

E. & O.E.

Total S\$: 8,201.50
=====

FIX

BODYFIX

NO 10 ANG MO KIO INDUSTRIAL PARK 2A #04-06

AMK AUTOPOINT SINGAPORE 568047

Tel No. : 62571289 Fax No. : 64837432

E-Mail : bodyfix@singnet.com.sg

Tax Reg. No. : 53010635C Buss. Reg. No. : 53010635C

AXA INSURANCE PTE LTD
8 SHENTON WAY #27-01
AXA TOWER SINGAPORE 068811

Attention : Motor Claim Department
Contact : 3387288 Fax No. : 8804838

Supplementary Estimate : ES220715

Date : 13/07/2022

Vehicle Num. : SMN 4948 L

Make/Model : HONDA FREED-2018

Chassis/Eng# : GB71085793/LEB5623460

Accident Date : 07/07/2022

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

- | | | | | |
|----|-----|----------------------------|--|--|
| 1. | 1PC | LIST ITEMS : | | |
| 2. | 1PC | REAR FENDER (RH) | | |
| 3. | 1PC | REAR FENDER RIGHT AIR VENT | | |
| | | REAR SPLASH GUARD RIGHT | | |

List TotalS\$:

1,110.90 ✓
26.40 ✗
50.00 ✓

1,187.30

lars : One Thousand One Hundred Eighty-Seven & Cents Thirty Only

E. & O.E.

Total S\$: 1,187.30

ODYFIX