

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: PC 3699J

at Workshop m/s

of

Insured:

Policy No.

Claims No. S2M046MP

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

C 370M

Vehicle: IN / OUT

Date:

Person Contacted:

LTA 814234

Veh No:

PC 3699J

Yr Regn:

18/05/15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

G.C

Make:

Toyota hiace commuter c.c 2982

Colour:

white

A/C: Insured / Std / NI / NA

Sp. Reading

341687

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KDH 2230022947

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195 R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

10/07/22

D.O.I.

14/07/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Dep 13k.

27/7/22 4/5 @ 5200 informed shown (red 11,030.43, 67%)

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2) 28/7/22-typist

Days Of Repair: 5

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

) S + RS, SI

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

Report Format: TP

Lump Sum / H.B.t: (\$ 5200)

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	370M
Vehicle Details	
Vehicle No.:	PC3699J
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Jul 2022
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE COMMUTER GL
Primary Colour:	White
Manufacturing Year:	2014
Engine No.:	1KD2488219
Chassis No.:	KDH2230022947
Maximum Power Output:	-
Open Market Value:	\$38,776.00
Original Registration Date:	18 May 2015
First Registration Date:	18 May 2015
Transfer Count:	1
Actual ARF Paid:	\$1,939.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	17 May 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$50,098.00
COE Rebate Amount:	\$14,234.00
Total Rebate Amount:	\$14,234.00

The information contained herein is correct as at 14 Jul 2022

OK

5 Trends Transform the End-to-End Car Experience

Post an Advertisement

Sell it yourself! Advertise it at just

\$68 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

Brand new unregistered unit. Not used import. 1.88%



Comes with 10 years servicing and warranty. Priced to sell. Understated race car Car Empire StarAd

KA-HUP

VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND







HOTLINE: 6741 9997 [view our cars](#)

Sort by results/page

6 vehicles



[Advanced Search](#)


	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	toyota hiace commuter		Any	Any	2015	Any	Any	Any	Available
	Toyota Hiace Commuter 3.0A High Roof		\$47,800	\$15,130 /yr	10-Sep-2015	2,982 cc	-	Bus	Available
	Fuel Type: Diesel 9/2015 Toyota Hiace 3.0 GL Commuter High Roof. Power door, 14 seaters. High loan and trade in welcome. Call now. Think One Automobile & Trading Posted: 14-Jul-2022								
	PREMIUM AD								
	Toyota Hiace Commuter 3.0A High Roof		\$49,800	N.A	02-Oct-2015	2,982 cc	-	Bus	Available
	Fuel Type: Diesel Reduced Price for Quick Sale! Full and flexible loan available, trade in welcome, in house financing available, speak to our friendly repres... AL Autocar Pte Ltd Posted: 08-Jul-2022								
	PREMIUM AD								
	Toyota Hiace Commuter 3.0A GL High Roof		\$48,800	\$16,540 /yr	26-Jun-2015	2,982 cc	196,000 km	Bus	Available
	Fuel Type: Diesel Looking for a commuter van? Come down and view it today. Wear and tear replaced. We offer best rates for trade in. In addition, we off... Swee Seng Motors Posted: 08-Jul-2022								
	PREMIUM AD								
	Toyota Hiace Commuter 3.0A GL		\$41,888	\$15,180 /yr	17-Apr-2015	2,982 cc	-	Bus	Available
	Fuel Type: Diesel PVC seats for easy maintenance. Well maintained vehicle. Posted: 06-Jul-2022								
	Toyota Hiace Commuter 3.0A GL		\$40,800	\$14,830 /yr	14-Apr-2015	2,982 cc	-	Bus	Available
	Fuel Type: Diesel Please Call To Arrange For Viewing, Thank You. Posted: 06-Jul-2022								
	Toyota Hiace Commuter 3.0A GL		\$55,000	\$17,640 /yr	26-Aug-2015	2,982 cc	-	Bus	Available
	Fuel Type: Diesel Hiace commuter 3.0A Euro 5 with digital aircon system. Pearl white. Wear and tear changed. New tyres. New battery. New alternator. Ne... Posted: 15-Jun-2022								
	DIRECT OWNER								

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

[view Expired ads](#)

[Compare](#)

results/page

IMPERIUM AUTOMOTIVE

25 Kaki Bukit Road 4 #01-47 Synergy@KB, Singapore 417800

HP : 9748 9940 Shawn Tan

Email: shawn7530@hotmail.com

13 Jul 2022

Vehicle No.: PC 3699 J

Model: TOYOTA HIACE BUS

not fullment
her
14/07/22
1/5 \$5200
5 days

QTY	DESCRIPTION	AMT \$
	List Items	
1	Rear windscreen moulding NS	\$ 120.80 X
1	Rear tailgate Body m	\$ 2,162.00 /
2	Rear tailgate dampers n	\$ 694.20 x
1	Rear tailgate inner trim board De/brn	\$ 289.60 /
1	Rear tailgate lock m/shall	\$ 450.00 /
1	Rear tailgate lock catch n	\$ 55.00 X
1	Rear tailgate lock remote n	\$ 850.00 X
1	Rear tailgate logo her	\$ 80.50 /
1	Rear tailgate rubber n	\$ 379.80 x
2	Rear tailgate lower side stoppers n	\$ 96.50 x
1	Rear tailgate "HIACE" emblem n	\$ 59.60 /
1	Rear tailgate "GL" emblem n	\$ 72.40 /
2	Rear taillamps o/s one 388.60	\$ 850.00 1pc
2	Rear taillamp lower garnishes R	\$ 568.40 x
1	Rear end panel Body m	\$ 569.10 /
1	Rear end panel inner member R	\$ 624.50 x
1	Rear end panel top moulding n	\$ 259.30 x
1	Rear bumper D.J	\$ 738.00 /
2	Rear bumper top brackets NS	\$ 130.00 X
3	Rear bumper lower brackets Surf 25x3= 75	\$ 156.00 /
1	Rear bumper reinforcement NS	\$ 458.00 X
2	Rear bumper side retainers o/s one 56	\$ 112.40 1pc
1	Rear floor panel R	\$ 1,880.80 X
1	Rear spare tyre carriage Surf 388.90	\$ 486.95 /
1	Rear spare tyre lock catch Sur	\$ 88.20 x
1	Rear exhaust silencer R	\$ 716.95 x
2	Rear exhaust mountings n	\$ 97.20 x
1	Rear side panel -RH R	\$ 1,879.70 x
1	Rear side panel air vent To.n	\$ 68.00 /
		\$ 14,993.90
	Less 25%	\$ 3,748.48
		\$ 11,245.43

Special Nett Items

1	Rear windscreen sealant	nee	\$	80.00	40
1	Rear tailgate "70KM/H" sticker	nee	\$	25.00	10
1	Rear bumper clip (1 set)	nee	\$	50.00	✓
1	Rear number plate	nee	\$	50.00	X
1	Rear reverse sensor (1 set)	shorted	\$	350.00	200
			\$	555.00	

S/N. Labour Charges

1	To remove, replaced damaged lamps and check up rear wiring.	\$	80.00	20
2	To remove and refit inner garnishes. <i>Seat cushion</i>	\$	150.00	80
3	To remove and refit rear reverse sensor.	\$	150.00	50
4	To transfer rear tailgate mechanism and wiring assembly.	\$	120.00	60
5	To remove and refit rear windscreen glass.	\$	180.00	120
6	To remove, refit and replace exhaust silencer and mountings.	\$	150.00	X
7	To apply undercoating.	\$	200.00	80
8	Panel beating.	\$	1,800.00	900
9	To re-spray painting on the affected areas.	\$	1,600.00	900
		\$	4,430.00	

Grand Total : \$ 16,230.43

P-5320.5
252
3990.37
300
2210

6500.37
252
5200

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: