



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLP 1185S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BOOTLID (CONSISTENT)	BENT	970.00	970.00
1	REAR BOOTLID EMBLEM (CONSISTENT)	NECESSARY	60.00	60.00
1	REAR WINDSCREEN MOULDING (CONSISTENT)	NECESSARY	50.00	50.00
1	REAR BUMPER RETAINER (CONSISTENT)	SERVICEABLE	38.00	-
1	REAR BUMPER (CONSISTENT)	BUCKLED / DENTED	780.00	780.00
	LESS 20% DISCOUNT		-379.60	-372.00
			1,518.40	1,488.00
	<u>LABOUR</u>			
	TO REMOVE REAR WINDSCREEN.		150.00	120.00
	TO RESPRAY AFFECTED PORTION.		450.00	400.00
	LABOUR CHARGES TO RENEW ABOVE PARTS.		500.00	400.00
			1,100.00	920.00
	GRAND TOTAL		2,618.40	2,408.00
RECOMMENDED COST OF REPAIRS				2,408.00

Report Ref No. CS/ASM22006680/Kqy3m4

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.