



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: OH VALE			Ref: CS/ASM22006680/Kqy3m4 Date: 30/08/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHD 5700P	Veh. Inspected	SLP 1185S
	Policy No.	VFX/P2413997	Coverage (\$)	0.00
	Claim No.	S2M046M5	Excess (\$)	0.00
	Assign From	OH VALE	Assign Date	14/07/2022
2. Vehicle Particulars & Condition				
	Make & Model	HONDA SHUTTLE (A)	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	GK81007286	Colour	METALLIC SILVER
	Odometer	65936 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/50 R16	MICHELIN	4 mm
	L/H Front Tyre	205/50 R16	MICHELIN	4 mm
	R/H Rear Tyre	205/50 R16	MICHELIN	4 mm
	L/H Rear Tyre	205/50 R16	MICHELIN	4 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	13/07/2022	Inspection Date	18/07/2022
	Survey held at	RC AUTO 160 SIN MING DRIVE #06-20 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	