

not Authorized

30 September 2022

Sum
14/7/22
1/5 \$6000/
5 days.

REG NO.: SKV 4294 X
MAKE/MODEL: PEUGEOT 3008

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
<u>LIST ITEMS</u>		
1	Front headlamp -LH 11	\$ 3,675.00 X
1	Front bumper Deep cut	\$ 1450 1,785.00
1	Front bumper side bracket (set) 11	\$ 126.00 X
1	Front bumper fog lamp 11	\$ 315.00 X
1	Front bumper lower side garnish (set) cut	\$ 450.00
1	Front bumper PDC sensor 11	\$ 315.00 X
1	Front bumper side grille 115 cut	\$ 210.00
1	Front bumper side retainer 11	\$ 85.00 X
1	Front fender -LH Bent/warped	\$ 540.00
1	Front fender bracket 11	\$ 99.00 X
1	Front fender inner shield 11	\$ 189.50
1	Front fender wheel arch garnish ground	\$ 297.00 X
1	Front fender top quarter garnish 11	\$ 43.00 X
1	Front wheel hub 11	\$ 234.00 X
1	Front wheel bearing 11	\$ 333.00 X
1	Front shock absorber 11	\$ 399.00 X
1	Front knuckle arm 11	\$ 810.00 X
1	Front lower arm 11	\$ 831.60 X
1	Front door 115 warped	\$ 1810 2,250.00
1	Front door protector 115 ground	\$ 545 2,315.00
1	Front seat belt gun 11	\$ 665.00 X
1	Front seat belt buckle 11	\$ 635.00 X
		\$ 16,602.10
Less 10%		\$ 1,660.21
		\$ 14,941.89

SPECIAL NETT ITEMS

1	Front bumper clip (1 set)	net	\$	80.00	50
1	Front fender inner shield clip (1 set)	net	\$	45.00	✓
1	Front tyre	2 in 1	\$	500.00	140
1	Front wheel rim -LH	warp	\$	1,050.00	900
				\$	1,675.00

S/N

LABOUR CHARGES

1	To check wiring and reset headlamps focusing.		\$	80.00	20
2	To remove and refit front sensor.	11	\$	150.00	X
3	To remove and refit front undercarriage.	11	\$	500.00	X
4	To conduct wheel alignment.		\$	180.00	60
5	To apply undercoating.		\$	200.00	60
6	Panel beating.		\$	1,500.00	580
7	To re-spray painting on the affected areas.		\$	1,400.00	800
8	To diagnose erase fault memory after repair.		\$	500.00	50
				\$	4,510.00

GRAND TOTAL :**\$ 21,126.89**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1-5342
102
4807.80
1135
1570