



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					CS3/SMO22003033/Uqy3-1
SOMPO INSURANCE SINGAPORE PL			Ref: 000/GM		
50 RAFFLES PLACE #03-03			Date: 01/01/2022 14/07/2022		
SINGAPORE LAND TOWERSINGAPORE 048623			Code: SMO		
1. Policy Particulars :- (THIRD PARTY CLAIM)					
Insured Veh.	GBB 4932A	Veh. Inspected	SKT 7985B		
Policy No.		Coverage (\$)	0.00		
Claim No.	CMTD2201084/MYE	Excess (\$)	0.00		
Assign From	000/GM MELVIN YE	Assign Date	01/01/2022 14/07/2022		
2. Vehicle Particulars & Condition					
Make & Model		c.c	0		
Engine No.	HIDDEN	Year of Reg.			
Chassis No.		Colour			
Odometer	-	Steering			
Brakes		Modification			
General					
3. Conditions of Tyres					
	Size	Make	Balance		
R/H Front Tyre			mm		
L/H Front Tyre			mm		
R/H Rear Tyre			mm		
L/H Rear Tyre			mm		
4. Description of Damages					
5. General Information					
Accident Date	30/03/2022	Inspection Date	01/04/2022		
Survey held at	EVERGUM AUTO SERVICES BLK 3022A UBI ROAD 1 #01-51 SINGAPORE 408716				
5a. Remarks					
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					