

S&H Motor Pte Ltd
160 Sin Ming Drive #07-02
Sin Ming Autocity
Singapore 575722

Insurer Reference:
Repairer Reference: 048856
Date calculated: 09/07/2022 11:02 AM

Full Report
Registration: SLV1888R
Printed: 09/07/2022 11:10 AM

Summary Information

Claim		Work Provider:	China Taiping Insurance
Location:	Singapore (SG)		(Singapore) Pte Ltd
Printed by:	SH Motor	Currency:	SGD
Claim Reference:		Date of Incident:	02/07/22
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle
Manufacturer: TOYOTA
Model: ALPHARD/VELLFIRE
Sub Model: BASE MODEL
Model Sheet Number: 70 VF 01
Registration: SLV1888R
VIN number: JTNGF3DH608022645
Odometer:

Model Specs

FROM 05.2019
 DOOR LIGHT
 TRIM WOOD
 VERSION VELLFIRE
 TYRES 215/65 R16..H
 SUNROOF

EL VERSION
 RADIO WITH DISP 9.0
 CAPTAIN SEAT
 CHROME DOOR HANDLES
 WHEELS 7.5J X 18 ALU
 JAPAN VERSION

ADD REAR OUT MIRROR
 LED FOG LAMPS
 8-SEATER
 2.5 LTR 134 KW
 SPARE WHEEL
 TWO COAT METALLIC

HEATED DOOR MIRROR
 TAILGATE HSG BLACK
 PASS SEAT SLIDE
 CVT AUTO GEARBOX
 FRONT DRIVE
 PREPARE OFF VEHICLE

Not Notified
Repairing
Ex @ 1250/-
1/1/2022

Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
M050 ZAX	R + R FRONT ASSEMBLIES INCLUDES: R + R WHEELS, ENGINE WITH GEARBOX AND ENGINE SUPPORT, DETACH + REFIT CONTROL ARMS, TIE RODS, UPPER SUSPENSION STRUTS, DRIVE SHAFTS, STABILIZER AND FRONT EXHAUST, BLEED BRAKE SYSTEM		46.0	193.20
043233	ALIGN VEHICLE CPL		12.0	50.40
M250 ZAX	R + R REAR AXLE CPL INCLUDES: DETACH + REFIT SHOCK ABSORBERS BLEED REAR BRAKE SYSTEM		27.0	113.40
B040	RENEW BOTH HEADLAMPS (BUMPER REMOVED)		5.0	21.00
B030	INCLUDES: ADJUST HEADLAMPS RENEW RADIATOR GRILLE		6.0	25.20

Code	Description	WU	Price SGD
520011	RENEW FRONT BUMPER (RADIATOR GRILLE REMOVED) INCLUDES: FRONT BUMPER AND REQUIRED ATTACHED PARTS R + R	9.0	37.80
B140 NO NUMBER B010)	RENEW FRONT PANEL CPL RENEW R/FRT SIDE MEMBER R + R FRONT BUMPER REINFORCEMENT (BUMPER REMOVED) INCLUDES: ABSORBER REMOVE AND REFIT	13.0 17.0 2.0	54.60 71.40 8.40
531011)	RENEW L/FRT WING INCLUDES: WHEELHOUSE LINER AND REQUIRED ATTACHED PARTS R + R NOT INCLUDED: HEADLAMP AND R + R BUMPER	7.0	29.40
531011)	RENEW R/FRT WING INCLUDES: WHEELHOUSE LINER AND REQUIRED ATTACHED PARTS R + R NOT INCLUDED: HEADLAMP AND R + R BUMPER	7.0	29.40
30051	RENEW BONNET INCLUDES: R + R BONNET, ATTACH PARTS ASSEMBLE AND IF NEC RENEW	7.0	29.40
B080 530121 851091)	R + R BONNET HINGE/S R + R BONNET OPENER CABLE R + R WASHER RESERVOIR	1.0 10.0 3.0	4.20 42.00 12.60
B085) 554011	R + R WIRE LINKAGE R + R WINDSCREEN (AIR GUIDE TRIM REMOVED) INCLUDES A-PILLAR TRIM, REAR VIEW MIRROR AND ALL REQUIRED ATTACHED PARTS R + R.	1.0 41.0	4.20 172.20
B085	R + R COWL PANEL TRIM INCLUDES: WIPER ARMS REMOVE AND REFIT	2.0	8.40
B085) 670301) 670301)	R + R WATER BOX CLOSING PANEL R + R L/F DOOR TRIM R + R R/F DOOR TRIM	2.0 2.0 2.0	8.40 8.40 8.40
B216	RENEW L/R DOOR INCLUDES: R + R LEFT REAR DOOR AND ADJUST, ATTACH PARTS ASS IF NECESS RENEW	33.0	138.60
B270 NO NUMBER B420 NO NUMBER 743401 G030 B430 893401) ZAX M230 893111) M010 NO NUMBER B440 NO NUMBER 711731)	RENEW L/R LOWER SIDE PANEL R + R TAILGATE INNER SIDE TRIM/S R + R L/R BUMPER TRIM R + R REAR BUMPER R + R RIGHT REAR LOWER SIDE TRIM R + R LEFT REAR SIDE WINDOW GLASS R + R HEADLINING R + R HEAD AIRBAG (COMPOSITE WORK) R + R UPPER INSTRUMENT PANEL R + R PASSENGER AIRBAG DRAIN AIR CONDITIONING R + R COMPRESSOR PIPE R + R LEFT FRONT SEAT DIS/ASS LEFT FRONT SEAT R + R L/F SEAT BACKREST COVER	73.0 2.0 1.0 4.0 5.0 22.0 10.0 1.0 16.0 13.0 4.0 1.0 3.0 4.0 5.0	306.60 8.40 4.20 16.80 21.00 92.40 42.00 4.20 67.20 54.60 16.80 4.20 12.60 16.80 21.00

Code	Description	WU	Price SGD
B440	R + R RIGHT FRONT SEAT		
NO NUMBER	DIS/ASS RIGHT FRONT SEAT	3.0	12.60
711731)	R + R R/F SEAT BACKREST COVER	4.0	16.80
893401) ZAX	R + R L/HEAD AIRBAG	5.0	21.00
893401) ZAX	R + R R/HEAD AIRBAG	1.0	4.20
B450	R + R L/R 3RD ROW SEAT	1.0	4.20
B450	R + R R/R 3RD ROW SEAT	3.0	12.60
711501	R + R LEFT FRONT SEAT BELT	3.0	12.60
711501	R + R RIGHT FRONT SEAT BELT	4.0	16.80
893011	R + R AIRBAG CONTROL UNIT	4.0	16.80
893061)	R + R L/SIDE AIRBAG SENSOR	5.0	21.00
893061)	R + R R/SIDE AIRBAG SENSOR	2.0	8.40
881151 ZAX	RENEW CONDENSER	2.0	8.40
	(BUMPER REMOVED)	13.0	54.60
160011	INCLUDES: REFILL AIR CONDITIONING		
	RENEW RADIATOR	13.0	54.60
	INCLUDES: BLEED COOLING SYSTEM		
NO NUMBER	R + R HEAT SHIELD PANEL	2.0	8.40
160251)	R + R DRIVE BELT	1.0	4.20
271011)	R + R ALTERNATOR	1.0	4.20
893361)	R + R L/F SIDE AIRBAG	2.0	8.40
893361)	R + R R/F SIDE AIRBAG	2.0	8.40
M240)	R + R CENTRE EXHAUST PIPE	2.0	8.40
170151	R + R REAR EXHAUST SECTION	5.0	21.00
420018)	R + R TYRE/S AND/OR WHEEL/S	3.0	12.60
420091)	R + R R/F WHEEL/TYRE	2.0	8.40
NO NUMBER	R + R FRONT AXLE CARRIER	10.0	42.00 7x
431011)	R + R R/F CONTROL ARM REAR	1.0	4.20
434211)	R + R R/F STEERING KNUCKLE	1.0	4.20
420091)	R + R L/R TYRE AND WHEEL	2.0	8.40 7x
420091)	R + R R/R TYRE AND WHEEL	2.0	8.40 7x
473201)	DETACH + REFIT REAR BRAKE CALIPER	4.0	16.80
042214)	BALANCE WHEEL/S	1.0	4.20
422041)	R + R L/R WHEEL HUB	1.0	4.20 7x
	INCLUDES: R + R BRAKE DISC	1.0	4.20 7x
422041)	R + R R/R WHEEL HUB	1.0	4.20 7x
	INCLUDES: R + R BRAKE DISC	1.0	4.20 7x
422041)	R + R REAR WHEEL HUB	7.0	29.40 7x
NO NUMBER	R + R L/REAR DRIVE SHAFT END	7.0	29.40 7x
NO NUMBER	R + R R/REAR DRIVE SHAFT END	9.0	37.80 7x
NO NUMBER	R + R REAR AXLE CARRIER	20.0*	84.00 7x
1481	LEFT FRONT DOOR REPAIR	20.0*	84.00 7x
1482	RIGHT FRONT DOOR REPAIR	30.0*	126.00 7x
1782	R/R DOOR REPAIR	15.0*	63.00 7x
2581	REAR BUMPER REPAIR		
Labour Cost Panel / Mechanical Labour Alignment Measuring Work Total of Labour } <i>check consistency</i>			
		Hrs	WU
		62.20	622.0
			2,612.40
		1.20	12.0
			50.40
			2,662.80

Paint

Paint Work

SYSTEM AZT

Time Basis 10 WU/h

Code	Description - TWO COAT METALLIC	WU	Price SGD
	BONNET NEW PART PAINTING	18.0	
	L/F WING NEW PART PAINTING	12.0	
	R/F WING NEW PART PAINTING	12.0	
	FRT LWR RAD SUPPORT SURFACE PAINT	4.0	
	FRT LOCK CARRIER SURFACE PAINT	4.0	
	CTR PNL CARRIER BAR SURFACE PAINT	4.0	
	L/RADIATOR BRACKET SURFACE PAINT	4.0	
	R/RADIATOR BRACKET SURFACE PAINT	4.0	
	R/F SIDE MEMBER CPL SURFACE PAINT	5.0	
	L/R DOOR NEW PART PAINTING	19.0	7x
	L/R LOWER SIDE PANEL NEW PART PAINTING	32.0	7x
	FRONT BUMPER NEW PART PAINT K1G	23.0	7x
	LEFT FRONT DOOR REPAIR PAINTING <50%	18.0	7x
	RIGHT FRONT DOOR REPAIR PAINTING <50%	18.0	7x
	R/R DOOR REPAIR PAINTING <50%	20.0	7x
	REAR BUMPER REPAIR PAINT PLASTIC	13.0	7x

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	52.63
0741	L/F WING NEW PART PAINTING	26.32
0742	R/F WING NEW PART PAINTING	26.32
1016	FRT LWR RAD SUPPORT SURFACE PAINT	2.99
1017	FRT LOCK CARRIER SURFACE PAINT	2.99
1187	CTR PNL CARRIER BAR SURFACE PAINT	2.99
1189	L/RADIATOR BRACKET SURFACE PAINT	2.99
1190	R/RADIATOR BRACKET SURFACE PAINT	2.99
1202	R/F SIDE MEMBER CPL SURFACE PAINT	4.98
1781	L/R DOOR NEW PART PAINTING	59.86
3481	L/R LOWER SIDE PANEL NEW PART PAINTING	45.10
0281	FRONT BUMPER NEW PART PAINT K1G	74.84
1481	LEFT FRONT DOOR REPAIR PAINTING <50%	32.95 7x
1482	RIGHT FRONT DOOR REPAIR PAINTING <50%	32.95 7x
1782	R/R DOOR REPAIR PAINTING <50%	37.47 7x
2581	REAR BUMPER REPAIR PAINT PLASTIC	31.59 7x

Labour Cost - Paint

Factor	42.00 SGD/h	Hrs	WU	Price SGD
Time Paint			210.0	
Preparation Main Work Metal		2.50	25.0	105.00
Preparation Comp. Work Plastic		0.80	8.0	33.60
Total	10 WU/h	24.30	243.0	1,020.60

Material Cost - Paint

New Part Painting	
New Part Painting - Plastic K1G	
Repair Painting	
Repair Painting Plastic	
Surface-/Blend Paint	
Material-constant Metal Preparation	
Material-constant Plastic	
Total	

Price SGD
210.23
74.84
103.37
31.59
19.93
28.60
12.70
481.26

Spare Parts

				prices as at 2015-06-01/01	Price SGD	
Code	Description	Part Number	Part Source			
0281	FRONT BUMPER	52119 58983	Original		350.00	✓
0293	L/F BUMPER COVER	52128 58170	Original	130	60.00	✓
0294	R/F BUMPER COVER	52127 58300	Original	130	60.00	✓
0317	L/F BUMPER BRACKET	52116 58090	Original	CM	70.00	✓
0318	R/F BUMPER BRACKET	52115 58090	Original	CM	70.00	✓
0327	FRT BUMPER ABSORBER	52611 58050	Original	CM	70.00	✓
0340	BUMPER SUPPORT	52021 58030	Original	R	190.00	✓
0347	L/FOG LAMP COVER	52040 58170	Original	SM	130.00	X
0348	R/FOG LAMP COVER	52030 58170	Original	SM	130.00	X
0375	LWR RADIATOR GRILLE	53112 58180	Original	CM	130.00	✓
0410	GRILLE	53101 58410	Original	CM	580.00	✓
0423	BUMPER MOULDING	53105 58050	Original	CM	330.00	✓
0431	BADGE TOYOTA	75301 58260	Original	MY	75.00	✓
0471	BONNET	53301 58060	Original	R	280.00	✓
0473	BONNET MOULDING	75770 58140	Original	CM	230.00	✓
0475	L/F HINGE	53420 58080	Original	DI	65.00	✓
0476	R/F HINGE	53410 58060	Original	DI	65.00	✓
0493	BONNET LOCK	53510 58080	Original	R	90.00	✓
0500	BONNET CABLE	53630 58050	Original	SM	60.00	7X
0561	LEFT HEADLAMP ASSY	81185 58570	Original	MY	1,600.00	✓
0562	RIGHT HEADLAMP ASSY	81145 58570	Original	MY	1,600.00	✓
0637	L/F FOG LAMP CPL	81220 48051	Original	SM	150.00	X
0638	R/F FOG LAMP CPL	81210 48051	Original	SM	150.00	X
0741	L/F WING	53802 58160	Original	R	380.00	✓
0742	R/F WING	53801 58070	Original	R	380.00	✓
0743	L/F WING RR MOULDING	53883 58010	Original	SM	180.00	7X
0744	R/F WING RR MOULDING	53882 58030	Original	SM	180.00	5X
0841	L/F WHEELHOUSE COVER	53806 58110	Original	CM	160.00	✓
0842	R/F WHEELHOUSE COVER	53805 58090	Original	CM	160.00	✓
1016	FRT LWR RAD SUPPORT	53028 28050	Original	330	130.00	✓
1017	FRT LOCK CARRIER	53205 58080	Original	350	190.00	✓
1027	L/AIR FUNNEL	52546 58070	Original	CM	60.00	✓
1028	R/AIR FUNNEL	52545 58070	Original	CM	60.00	✓
1029	UPPER AIR GUIDE	53106 58111	Original	CM	150.00	7X
1187	CTR PNL CARRIER BAR	53209 58040	Original	R	50.00	✓
1189	L/RADIATOR BRACKET	53203 58060	Original	R	220.00	✓
1190	R/RADIATOR BRACKET	53202 58050	Original	R	220.00	✓
1202	R/F SIDE MEMBER CPL	57101 58040	Original	R	1,300.00	7X
1331	BATTERY HOLDER	74431 42090	Original	SM	75.00	7X
1335	UPP BATTERY BRACKET	74404 58050	Original	BT	60.00	7X
1401	WINDSCREEN	56101 58440	Original	CM	750.00	✓

Code	Description	Part Number	Part Source	Price SGD	
1411	WINDSCREEN BOND KIT	PZ49I 00C1131		0.00	
1414	FRONT SCREEN PIPING	56115 30120		0.00	
1415	FRONT SCREEN PIPING	56116 22050		0.00	
1419	LWR W-SCREEN MLDG	56117 50130		0.00	
1436	WASHER CONTAINER	85315 58030	Original	180.00	✓
1781	L/R DOOR	67004 58080	Original	150.00	✓
1847	L/R WINDOW	69802 30280	Original	(A1) 1,300.00	7X
	REGULATOR		Original	230.00	7X
1851	L/R WINDOW MOTOR	85720 58050	Original	N/C	
3481	L/R LOWER SIDE PANEL	61602 58110	Original	350.00	7X
3807	L/SIDE WINDOW	62720 58260	Original	A1 480.00	7X
3861	L/SIDE WDW SEAL KIT	PZ49I 00C1131		0.00	
4325	PASSENGER AIRBAG	73960 58030	Original	0.00	
4331	INSTRUMENT PANEL	55400 58030C0	Original	1,450.00	✓
4341	KNEE AIRBAG	73900 58030C0	Original	Tn 1,500.00	✓
4465	CONDENSER CPL	88460 58040	Original	1,200.00	✓
4481	COMPR OUTL LINE	88711 58130	Original	550.00	✓
4482	CONDENS OUTL LINE	88710 58180	Original	A1 360.00	✓
4589	L/F BACKREST COVER	71074 58681C2	Original	160.00	✓
4590	R/F BACKREST COVER	71073 58711C4	Original	Tn 320.00	✓
4607	L/F SIDE AIRBAG	73920 42060	Original	Tn 320.00	✓
4608	R/F SIDE AIRBAG	73910 58040	Original	450.00	✓
4611	L/F SIDE AIRBAG SENS	89831 58010	Original	450.00	✓
4612	R/F SIDE AIRBAG SENS	89831 58010	Original	N/C 200.00	✓
4621	L/ITS HEAD AIRBAG	62180 58030	Original	200.00	✓
4622	R/ITS HEAD AIRBAG	62170 58030	Original	1,300.00	✓
4661	L/F SEAT BELT	73220 58071C0	Original	1,700.00	✓
4662	R/F SEAT BELT	73210 58061C1	Original	Tn 1,150.00	✓
4957	HEADLINING	63304 58720A1	Original	Tn 1,150.00	✓
7054	R/F TRACK CONT ARM	48068 28140	Original	Reform 3,800.00	✓
7066	R/CARRIER JOINT	43330 59155	Original	Sm 190.00	X
7082	R/F STEERING KNUCKLE	43211 78010	Original	Sm 80.00	X
7132	R/F WHEEL HUB	43550 28030	Original	Sm 250.00	X
7202	R/FR WHEEL	42611 58340	Original	Sm 290.00	X
7405	AIRBAG	45130 58040C0	Original	N/C (N/C) 950.00	X
7435	SLIP RING	84307 58030	Original	1,300.00	✓
7440	AIRBAG CONTROL UNIT	89170 58120	Original	350.00	✓
7761	RADIATOR CPL	16400 28711	Original	1,380.00	✓
7767	RADIATOR SHROUD	16711 28420	Original	650.00	7X
7773	RADIATOR OUTLET HOSE	16572 36180	Original	CM 140.00	7X
7775	L/UPP RADIATOR HOSE	16571 36190	Original	70.00	7X
7787	EXPANSION TANK	16470 28152	Original	Sm 65.00	7X
7793	L/BLOWER FAN	16361 28370	Original	140.00	✓
7794	R/BLOWER FAN	16361 28380	Original	CM 120.00	7X
7797	L/FAN MOTOR	16363 36200	Original	CM 120.00	7X
7798	R/FAN MOTOR	16363 36210	Original	Tn 280.00	7X
8373	LOWER INTAKE	17896 36030	Original	Tn 280.00	7X
	HOUSING			Sm 75.00	X
8375	AIR INTAKE HOSE	17751 36130	Original	N/C 95.00	X
8376	AIR HOSE ADAPTER	17752 36040	Original	N/C 80.00	7X
8411	ALTERNATOR	27060 0V280	Original	Sm 1,150.00	7X
8433	ALTERNATOR BELT	90916 02732	Original	Sm 95.00	7X
8781	FRT ENG COMP PROTECT	51440 58030	Original	CM 140.00	✓
8804	UPPER HEAT SHIELD	17168 36010	Original	R 130.00	7X
9121	L/R STABILIZER ARM	48790 58010	Original	Sm & 250.00	7X
9127	L/R STRG KNUCKLE	42305 58010	Original	Sm 350.00	7X

Code	Description	Part Number	Part Source	Price SGD	
9128	R/R STRG KNUCKLE	42304 58010	Original	350.00	7X
9181	L/R WHEEL HUB	42450 28030	Original	250.00	7X
9182	R/R WHEEL HUB	42450 28030	Original	250.00	7X
9201	L/R SHOCK ABSORBER	48530 58110	Original	110.00	7X
9551	L/RR WHEEL	42611 58340	Original	950.00	7X
9552	R/RR WHEEL	42611 58340	Original	95.00	7X
9645	LOW TONE HORN	86520 30670	Original	90.00	7X
9646	HIGH TONE HORN	86510 48190	Original	90.00	7X
1000	LH HEADLAMP ECU	LH HEAD LAMP	Original	350.00	7X
1001	RH HEADLAMP ECU	RH HEAD LAMP	Original	350.00	7X
1002	L/R DOOR LWR MLDING	LH REAR DOOR	Original	290.00	7X
1003	L/R FENDER LWR TRIM	LH REAR FENDER	Original	180.00	7X
8374	RH HORN BRACKET	HORN	Original	55.00	7X
8375	LH HORN BRACKET	HORN	Original	55.00	7X
f: OEM Parts				0.00	
n: Non-OEM Parts				42,675.00	
u: Used parts				100.00	
Savings					
Subtotal					
Fixed Sundry Parts Price					
Total				42,775.00	

Extras

Code	Description	Price SGD
0293	[S]: L/F BUMPER COVE R: TOW COVER	0.00*
0294	[S]: R/F BUMPER COVE R: TOW COVER	0.00*
1004	AIRBAG ECU PROGRAM A/B ECU	380.00* 250
1005	Electrical work Electrical work	25.00*
1006	Engine coolant Engine coolant	30.00*
1007	FNT W/S INNER SEAL FRNT WINDSCREEN	35.00*
1008	Air con coolant Air con	50.00*
1009	FRONT W/S SEALANT FRNT WINDSCREEN	20.00*
1010	Front number plate Number Plate	35.00*
1011	Wheel alignment Wheel alignment	60.00*
1187	[S]: CTR PNL CARRIER BAR: FRONT SUP	0.00*
1187	PORT PANEL LOWER	0.00*
1189	[S]: L/RADIATOR BRAC KET: FRONT SUPP	0.00*
1189	ORT PANEL LH	0.00*
1190	[S]: R/RADIATOR BRAC KET: FRONT SUPP	0.00*
1190	ORT PANEL RH	0.00*
4607	[S]: L/F SIDE AIRBAG : SEAT AIRBAG	0.00*
4608	[S]: R/F SIDE AIRBAG : SEAT AIRBAG	0.00*
7405	[S]: AIRBAG: STEERIN G WHEEL	0.00*
7435	[S]: SLIP RING: CLOC KSPRING	0.00*
8373	[S]: LOWER INTAKE HO USING: AIR RESO	0.00*
8373	NATOR BOX	0.00*
8376	BATTERY BATTERY	220.00* 7X
8377	L/R QTR GLAS SEALANT L/R QTR GLASS	35.00* 7X
8378	L/R QR GLAS INN SEAL L/R QTR GLASS	35.00* 7X
Total Extras		925.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Final Calculation

	SGD	SGD
Parts		
Fixed Sundry Parts Price	42,675.00	
Total Parts	100.00	42,775.00
Labour Time Base 10 WU/h		
Total 622.0 WU X 42.00 SGD/h	2,612.40	1428
Alignment		
Measuring Work	50.40	✓
Total of Labour		2,662.80
Total Of Extras		925.00
Paint Work Time Base 10 WU/h		
Labour Cost 243.0 WU X 42.00 SGD/h	1,020.60	550.20
Material Cost	481.26	243.64
Total Paint Including Material		1,501.86
Repair Cost Excludes GST		47,864.66
GST (+7.0%)		3,350.53
Repair Cost Included GST		51,215.19

Comments

- * - USER SUPPLIED DATA
- NN - NO MANUFACTURERS CODE EXISTS
-) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.



The Motor Claims Department
M/s China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

File No : SH/2022/167/07/100/OD
Date : 31-August-2022

Supplementary estimated cost of repair for vehicle no: SLV 1888 R Toyota
Policy No: DMPCSNW00097322100 Accident Date: 02.07.2022

Description	Quantity	Cost Price
Front cross member	1	\$ 950.00
Rear cross member front bush	1	\$ 120.00
Front cross member front bush	1	\$ 220.00

705/706
703/704

The Motor Claims Department
M/s China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

File No: SH/2022/167/07/100/OD
Date: 11-August-2022

Supplementary estimated cost of repair for vehicle no: SLV 1888 R Toyota
Policy No: DMPCSNW00097322100 Accident Date: 02.07.2022

Description	Quantity	Cost Price
7876 Thermostat <i>Me-</i>	1	840 ✓
7880 Thermostat housing <i>CM-</i>	1	861 ✓
8780 Front bumper lower dust cover <i>CM-</i>	1	8320 ✓
8391 Air cond pipe stage 1 (Cooling coil to compressor) <i>Not -</i>	1	8380 ✓
4453 Air cond pipe stage 2 (Cooling coil to compressor) <i>Not -</i>	1	8390 ✓
8376 Air cond pipe bracket (AC condensor to Cooling coil) <i>CM-</i>	1	8130 ✓
4484 Engine air cleaner <i>CM-</i>	1	380 ✓
1001 Front lower corss member (5710412270) <i>Rs-</i>	1	8310 ✓
1003 Front lower cross reinforcement (5110728020) <i>Rs-</i>	1	8180 ✓
1366 Front right wiper corner garnish <i>017 -</i>	1	835 ✓
7788 Front radiator top bracket <i>CM-</i>	1	885 ✓
8375 Front radiator spare tank pipe <i>CM-</i>	1	855 ✓