

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: JANICE KOH

Date: 15 Jul 2022

Preliminary Advice

Vehicle No	: SMF9862J	Accident Date	: 05/07/2022
Make	: SUBARU FORESTER	Policy No.	: SP2000035725
Assignment Date	: 14/07/2022	Excess	: S\$600.00
Date of Inspection	: 15/07/2022	Est. Duration of Repair	: 18
Inspection At	: SHU FATT AUTO WORKS		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	19,447.40
Revised Amount	:S\$	11,315.00
Check Items (Estimated)	:S\$	4,349.90
Total	:S\$	15,664.90

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	93,000.00
COE / PARF Rebate	:S\$	29,992.00
Salvage Value	:S\$	
Margin for Repair	:S\$	63,008.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Part by Part repair. According to the repairer, there is no secondhand parts available. Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost.