



樹發汽車修理廠
SHU FATT AUTO WORKS

BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065
Co. Reg. No. 09062400M GST Reg. No. 09-062400-M

(SUPPLEMENTARY)

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	WSK/JW/SF-SMF9862J
Policy No:	SP2000035725	Date of Loss:	05/07/2022
Vehicle Reg. No.:	SMF9862J	Driveable?	
Driver Age/Info:	64 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	WOO CHEE WAI	Contact No:	+6596646608
Driver:	WEE CHEE WAI		

Make/Model:	SUBARU FORESTER, 2.0 I-L CVT AWD SR (A)	Vehicle Reg. Date:	30/11/2018
Vehicle Colour:	BROWN	Chassis No:	JF1SJ5KC5JG112420
Engine No:	FB20YE45561		
Odometer:	43097 KM		

Paint Type:
Total Loss? **NO**
Est. Duration of Repair (day) 20

Present Location: SHU FATT AUTO WORKS (HQ)

COST OF CLAIMS

	Amount
Parts	1,822.20
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	1,822.20
+ GST 7.00% (\$\$)	127.55
Nett Amount (\$\$)	1,949.75
+ Previous Estimates (\$\$)	20,166.72
Claim Total (\$\$)	22,116.47

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 04 Aug 2022)
Parts: M1-SUV SUBARU FORESTER 2.0 I-L CVT AWD SR (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SMF9862J)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Cross member / BT	0.00	0.00	*540.00 F
2	1		*Washer tank / BR	0.00	0.00	*120.00 F
3	1		*Horn / BR	0.00	0.00	*30.00 F
4	1		*Anti roll bar bracket (stabilizer bracket) / BT	0.00	0.00	*10.00 F
5	1		*Right front wheel apron bracket / BT	0.00	0.00	*204.00 F
6	1		*Right front fender bracket (top) / BT	0.00	0.00	*18.00 F
7	1		*Right fog lamp bracket / BR	0.00	0.00	*20.00 F
8	1		*Condenser side sponge / BR	0.00	0.00	*18.00 F
9	1		*Right frt fender top cover / CRN	0.00	0.00	*20.00 F
10	1		*Left front headlamp washer nozzle / BR	0.00	0.00	*60.00 F
11	1		*Front bumper tow cover / MJ	0.00	0.00	*12.00 F
12	1		*MAF Sensor (Intake Air Sensor) / Shaded	0.00	0.00	*280.00 F
13	1		*Right front tyre / Tn (80% of \$18230 = \$184)	0	0.00	*230.00 FS
14	1		*Gear oil / BR	0	0.00	*70.00 FS
15	1		*Auto Transmission Fluid / BR	0	0.00	*57.00 FS

F=Franchise part. S=SpcNett.

Sub Total (S\$)	1,689.00
+ Margin on L,N Items 10.00% (S\$)	133.20
Total Parts (S\$)	1,822.20

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Steve (LKK)
4/8/22, 3:00pm