



樹發汽車修理廠  
SHU FATT AUTO WORKS

BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065  
Co. Reg. No. 09062400M GST Reg. No. 09-062400-M

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)

**PARTICULARS OF CLAIM**

|                     |                 |                       |                    |
|---------------------|-----------------|-----------------------|--------------------|
| Claim Type:         | OD (OWN DAMAGE) | Ref. No:              | WSK/JW/SF-SMF9862J |
| Policy No:          | SP2000035725-01 | Date of Loss:         | 05/07/2022         |
| Vehicle Reg. No.:   | SMF9862J        | Driveable?            |                    |
| Driver Age/Info:    | 64 / MALE       | Party At Fault:       | UNKNOWN            |
| TP Injury Involved? | NO              | Third Party Involved? | YES                |
| Insured/Claimant:   | WEE CHEE WAI    | Contact No:           | +6596646608        |
| Driver:             | WEE CHEE WAI    |                       |                    |

|                 |                                         |                    |                   |
|-----------------|-----------------------------------------|--------------------|-------------------|
| Make/Model:     | SUBARU FORESTER, 2.0 I-L CVT AWD SR (A) | Vehicle Reg. Date: | 30/11/2018        |
| Vehicle Colour: | BROWN                                   | Chassis No:        | JF1SJ5KC5JG112420 |
| Engine No:      | FB20YE45561                             |                    |                   |
| Odometer:       | 43097 KM                                |                    |                   |

|                               |    |
|-------------------------------|----|
| Paint Type:                   |    |
| Total Loss?                   | NO |
| Est. Duration of Repair (day) | 20 |

Remarks: VEHICLE IS IN.

Present Location: SHU FATT AUTO WORKS (HQ)

**COST OF CLAIMS**

|                              | Amount    |
|------------------------------|-----------|
| Parts                        | 13,067.40 |
| Miscellaneous Items          | 1,380.00  |
| Labour                       | 3,200.00  |
| Paintwork Labour             | 1,800.00  |
| Towing                       | 0.00      |
| Calculated Gross Total (S\$) | 19,447.40 |
| - Excess (S\$)               | 600.00    |
| (S\$)                        | 18,847.40 |
| + GST 7.00% (S\$)            | 1,319.32  |
| Nett Amount (S\$)            | 20,166.72 |

This claim is handled by: PATRICIA KOH

Generated using Merimen e-Claims Internet Estimation & Adjusting System

L/K/K to survey on 15/7/22

14/7/22

# REPAIR DETAILS

## Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 14 Jul 2022)

Parts: M1-SUV SUBARU FORESTER 2.0 I-L CVT AWD SR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Shu Fatt Auto Works/SMF9862J/14/07/2022 13:39

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

| No. | Qty | Part No. | Particulars                                      | %Disc | %Depr | Amount      |
|-----|-----|----------|--------------------------------------------------|-------|-------|-------------|
| 1   | 1   |          | *Front bonnet X R                                | 0.00  | 0.00  | *600.00 F   |
| 2   | 1   |          | *Front bonnet chrome / CAT                       | 0.00  | 0.00  | *100.00 F   |
| 3   | 8   |          | *Front bonnet chrome clips X nn                  | 0.00  | 0.00  | *20.00 F    |
| 4   | 1   |          | *Front bonnet insulator X nn                     | 0.00  | 0.00  | *60.00 F    |
| 5   | 12  |          | *Front bonnet insulator clips X nn               | 0.00  | 0.00  | *30.00 F    |
| 6   | 2   |          | *Front bonnet hinges X nn                        | 0.00  | 0.00  | *60.00 F    |
| 7   | 1   |          | *Front bonnet lock X nn                          | 0.00  | 0.00  | *75.00 F    |
| 8   | 1   |          | *Left front headlight ? X nn                     | 0.00  | 0.00  | *1,650.00 F |
| 9   | 1   |          | *Right front headlight / BR                      | 0.00  | 0.00  | *1,650.00 F |
| 10  | 1   |          | *Left front headlight holder ? X nn              | 0.00  | 0.00  | *35.00 F    |
| 11  | 1   |          | *Right front headlight holder / MIS              | 0.00  | 0.00  | *35.00 F    |
| 12  | 1   |          | *Front top grille / BR                           | 0.00  | 0.00  | *130.00 F   |
| 13  | 6   |          | *Front top grille clips X nn                     | 0.00  | 0.00  | *15.00 F    |
| 14  | 1   |          | *Front lower grille / CAT                        | 0.00  | 0.00  | *230.00 F   |
| 15  | 12  |          | *Front grille clips X nn                         | 0.00  | 0.00  | *30.00 F    |
| 16  | 1   |          | *Front grille emblem X nn                        | 0.00  | 0.00  | *55.00 F    |
| 17  | 1   |          | *Front bumper / BR                               | 0.00  | 0.00  | *340.00 F   |
| 18  | 1   |          | *Front bumper reinforcement / ON                 | 0.00  | 0.00  | *220.00 F   |
| 19  | 1   |          | *Left front bumper bracket / BR                  | 0.00  | 0.00  | *18.00 F    |
| 20  | 1   |          | *Right front bumper bracket / BR                 | 0.00  | 0.00  | *18.00 F    |
| 21  | 1   |          | *Front bumper foam ? / BT                        | 0.00  | 0.00  | *90.00 F    |
| 22  | 16  |          | *Front bumper clips X nn                         | 0.00  | 0.00  | *40.00 F    |
| 23  | 1   |          | *Left front bumper retainers X nn                | 0.00  | 0.00  | *12.00 F    |
| 24  | 1   |          | *Right front bumper retainer X nn                | 0.00  | 0.00  | *12.00 F    |
| 25  | 1   |          | *Right front headlight washer nozzle / BR        | 0.00  | 0.00  | *60.00 F    |
| 26  | 1   |          | *Right front headlight washer nozzle cover / MIS | 0.00  | 0.00  | *40.00 F    |
| 27  | 1   |          | *Right front headlight washer pipes / X nn       | 0.00  | 0.00  | *55.00 F    |
| 28  | 1   |          | *Right front fog light / BR                      | 0.00  | 0.00  | *180.00 F   |
| 29  | 1   |          | *Right front fog light chrome garnish / MIS      | 0.00  | 0.00  | *40.00 F    |
| 30  | 1   |          | *Right front fender / ON                         | 0.00  | 0.00  | *170.00 F   |
| 31  | 1   |          | *Right front fender cowlings / TN                | 0.00  | 0.00  | *96.00 F    |
| 32  | 12  |          | *Right front fender cowlings clips X nn          | 0.00  | 0.00  | *30.00 F    |
| 33  | 1   |          | *Front air resonator / MIS                       | 0.00  | 0.00  | *40.00 F    |
| 34  | 1   |          | *Front lower engine cover / BR X nn ✓ BRO        | 0.00  | 0.00  | *120.00 F   |
| 35  | 12  |          | *Front lower engine cover clips X nn             | 0.00  | 0.00  | *30.00 F    |
| 36  | 1   |          | *Right air bag sensor ? X nn                     | 0.00  | 0.00  | *135.00 F   |
| 37  | 1   |          | *Front support panel / ON                        | 0.00  | 0.00  | *280.00 F   |
| 38  | 1   |          | *Front support lower member / X nn               | 0.00  | 0.00  | *120.00 F   |
| 39  | 1   |          | *Front mud flap / MIS                            | 0.00  | 0.00  | *180.00 F   |
| 40  | 1   |          | *Front air intake hose / X nn                    | 0.00  | 0.00  | *281.00 F   |
| 41  | 4   |          | *Front air intake hose clips X nn                | 0.00  | 0.00  | *14.00 F    |
| 42  | 1   |          | *Front top air box / BR (fm)                     | 0.00  | 0.00  | *60.00 F    |
| 43  | 1   |          | *Front lower air box / BR (R)                    | 0.00  | 0.00  | *120.00 F   |
| 44  | 1   |          | *Front radiator ? / BR                           | 0.00  | 0.00  | *900.00 F   |
| 45  | 1   |          | *Front aircon condenser ? / BT                   | 0.00  | 0.00  | *400.00 F   |

Shu Fatt Auto Works/SMF9862J/14/07/2022 13:39. Not valid without Reference section.

Generated using Merimen e-Claims IEAS



| Qty | Part No. | Particulars                                       | %Disc | %Depr | Amount        |
|-----|----------|---------------------------------------------------|-------|-------|---------------|
| 46  | 1        | *Right front shock absorber / BT                  | 0.00  | 0.00  | *210.00 F     |
| 47  | 1        | *Right front shock absorber top mounting - PR     | 0.00  | 0.00  | *95.00 F 90   |
| 48  | 1        | *Right front shock absorber top bearing - PR X nn | 0.00  | 0.00  | *95.00 F      |
| 49  | 1        | *Right front shock absorber bush - PR             | 0.00  | 0.00  | *18.00 F      |
| 50  | 1        | *Right front lower arm - BT                       | 0.00  | 0.00  | *310.00 F     |
| 51  | 1        | *Right front knuckle arm - BT                     | 0.00  | 0.00  | *160.00 F     |
| 52  | 1        | *Right front lower arm bush (1) - PR X nn         | 0.00  | 0.00  | *35.00 F      |
| 53  | 1        | *Right front lower arm bush (2) - PR X nn         | 0.00  | 0.00  | *45.00 F      |
| 54  | 1        | *Right front wheel hub - PR                       | 0.00  | 0.00  | *105.00 F     |
| 55  | 1        | *Right front wheel bearing - PR X nn              | 0.00  | 0.00  | *90.00 F      |
| 56  | 1        | *Front anti roll bar - BT                         | 0.00  | 0.00  | *190.00 F 165 |
| 57  | 2        | *Front anti roll bar bushes - PR CR4              | 0.00  | 0.00  | *20.00 F      |
| 58  | 1        | *Right front drive shaft ? / BT                   | 0.00  | 0.00  | *600.00 F     |
| 59  | 1        | *Right tie rod - BT                               | 0.00  | 0.00  | *45.00 F 66   |
| 60  | 1        | *Right front rack end - BT                        | 0.00  | 0.00  | *50.00 F      |
| 61  | 1        | *Right front linkage - BT ? / BT                  | 0.00  | 0.00  | *50.00 F      |
| 62  | 1        | *Right front brake disc cover - BT                | 0.00  | 0.00  | *65.00 F 30   |
| 63  | 1        | *Right front brake sensor - PR X nn               | 0.00  | 0.00  | *145.00 F     |
| 64  | 1        | *Right frt rim - CR4                              | 0.00  | 0.00  | *600.00 F     |
| 65  | 1        | *Front number plate X nn                          | 0     | 0.00  | *55.00 FS     |
| 66  | 1        | *Coolant ? / PR                                   | 0     | 0.00  | *28.00 FS net |

F=Franchise part. S=SpcNett.

|                                     |                  |
|-------------------------------------|------------------|
| Sub Total (\$\$)                    | 11,887.00        |
| + Margin on L,N Items 10.00% (\$\$) | 1,180.40         |
| <b>Total Parts (\$\$)</b>           | <b>13,067.40</b> |

Shu Fatt Auto Works/SMF9862J/14/07/2022 13:39. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

No Qty Particulars

Amount

### Miscellaneous Items

- | No | Qty | Particulars                                                     | Amount       |
|----|-----|-----------------------------------------------------------------|--------------|
| 1  | 1   | To check & repair wiring.                                       | 50 80 120.00 |
| 2  | 1   | To check under carriage, replace damage parts & assembly.       | 200 680.00   |
| 3  | 1   | To check, adjust 4 wheel alignment.                             | 80 120.00    |
| 4  | 1   | To remove, radiator, condenser, fill coolant, air con freon.    | 100 250.00   |
| 5  | 1   | To remove, replace rt frt tyre rim, tyre, balance and assembly. | 30 60.00     |
| 6  | 1   | To reset ECU.                                                   | 100 150.00   |

Sub Total (S\$) 1,380.00

## Estimates on Labour

No Particulars

Lab.Type

Amount

### Paintwork Labour

- | No | Particulars               | Lab.Type | Amount        |
|----|---------------------------|----------|---------------|
| 1  | To respray damaged parts. | New      | 1200 1,800.00 |

### Labour Items

- |   |                                                                                                                                                                                                                                                                |     |               |
|---|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|---------------|
| 2 | To knock, straighten frt inner, lower, side panels, rt frt wheel hse, rt frt inner wheel hse, rt frt chassis, frt lower member, left frt wheel hse, rt frt dr, renew frt bonnet, frt support panel, frt lights, frt fender, frt grille, frt bumper & assembly. | New | 1800 3,200.00 |
|---|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|---------------|

Gross Labour Cost (S\$) 5,000.00

Shu Fatt Auto Works/SMF9862J/14/07/2022 13:39. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Steve (LKK)  
15/7/22, 19.00

10- M HL  
EX(11) - ?  
P/P  
L7 BL Y  
18 BL Y

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



# 樹發汽車修理廠 SHU FATT AUTO WORKS

BLOCK 1008 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065  
Co. Reg. No. 09062400M GST Reg. No. 09-062400-M

## (SUPPLEMENTARY) - 1

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)

### PARTICULARS OF CLAIM

|                               |                                         |                       |                    |
|-------------------------------|-----------------------------------------|-----------------------|--------------------|
| Claim Type:                   | OD (OWN DAMAGE)                         | Ref. No:              | WSK/JW/SF-SMF9862J |
| Policy No:                    | SP2000035725                            | Date of Loss:         | 05/07/2022         |
| Vehicle Reg. No.:             | SMF9862J                                | Driveable?            |                    |
| Driver Age/Info:              | 64 / MALE                               | Party At Fault:       | UNKNOWN            |
| TP Injury Involved?           | NO                                      | Third Party Involved? | YES                |
| Insured/Claimant:             | WOO CHEE WAI                            | Contact No:           | +6596646608        |
| Driver:                       | WEE CHEE WAI                            |                       |                    |
| Make/Model:                   | SUBARU FORESTER, 2.0 I-L CVT AWD SR (A) | Vehicle Reg. Date:    | 30/11/2018         |
| Vehicle Colour:               | BROWN                                   | Chassis No:           | JF1S15KC5JG112420  |
| Engine No:                    | FB20YE45561                             |                       |                    |
| Odometer:                     | 43097 KM                                |                       |                    |
| Paint Type:                   |                                         |                       |                    |
| Total Loss?                   | NO                                      |                       |                    |
| Est. Duration of Repair (day) | 20                                      |                       |                    |
| Present Location:             | SHU FATT AUTO WORKS (HQ)                |                       |                    |

### COST OF CLAIMS

|                                   | Amount           |
|-----------------------------------|------------------|
| Parts                             | 1,822.20         |
| Miscellaneous Items               | 0.00             |
| Labour                            | 0.00             |
| Paintwork Labour                  | 0.00             |
| Towing                            | 0.00             |
| <b>Gross Total (S\$)</b>          | <b>1,822.20</b>  |
| <b>+ GST 7.00% (S\$)</b>          | <b>127.55</b>    |
| <b>Nett Amount (S\$)</b>          | <b>1,949.75</b>  |
| <b>+ Previous Estimates (S\$)</b> | <b>20,166.72</b> |
| <b>Claim Total (S\$)</b>          | <b>22,116.47</b> |

Generated using Merimen e-Claims Internet Estimation & Adjusting System



# REPAIR DETAILS

## Reference

**Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 04 Aug 2022)  
**Parts:** M1-SUV SUBARU FORESTER 2.0 I-L CVT AWD SR (A) (Catalogue:Merimen Singapore 1.0)  
**Labour:** Repairer's (Price-denominated Standard List)  
**Print Code:** (Unsubmitted, no print-code for SMF9862J)  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

| No.                               | Qty | Part No. | Particulars                                      | %Disc | %Depr | Amount           |
|-----------------------------------|-----|----------|--------------------------------------------------|-------|-------|------------------|
| 1                                 | 1   |          | *Cross member / BT                               | 0.00  | 0.00  | *540.00 F        |
| 2                                 | 1   |          | *Washer tank / BT                                | 0.00  | 0.00  | *120.00 F        |
| 3                                 | 1   |          | *Horn / BT                                       | 0.00  | 0.00  | *30.00 F         |
| 4                                 | 1   |          | *Anti roll bar bracket (stabilizer bracket) / BT | 0.00  | 0.00  | *10.00 F         |
| 5                                 | 1   |          | *Right front wheel apron bracket / BT            | 0.00  | 0.00  | *204.00 F        |
| 6                                 | 1   |          | *Right front fender bracket (top) / BT           | 0.00  | 0.00  | *18.00 F         |
| 7                                 | 1   |          | *Right fog lamp bracket / BT                     | 0.00  | 0.00  | *20.00 F         |
| 8                                 | 1   |          | *Condenser side sponge / BT                      | 0.00  | 0.00  | *18.00 F         |
| 9                                 | 1   |          | *Right frt fender top cover / CRN                | 0.00  | 0.00  | *20.00 F         |
| 10                                | 1   |          | *Left front headlamp washer nozzle / BT          | 0.00  | 0.00  | *60.00 F         |
| 11                                | 1   |          | *Front bumper tow cover / MJ                     | 0.00  | 0.00  | *12.00 F         |
| 12                                | 1   |          | *MAF Sensor (Intake Air Sensor) - Shrink         | 0.00  | 0.00  | *280.00 F        |
| 13                                | 1   |          | *Right front tyre - Tn (80% of \$1830 = \$184)   | 0     | 0.00  | 184 / *230.00 FS |
| 14                                | 1   |          | *Gear oil / BT                                   | 0     | 0.00  | *70.00 FS        |
| 15                                | 1   |          | *Auto Transmission Fluid / BT                    | 0     | 0.00  | *57.00 FS        |
| Sub Total (\$)                    |     |          |                                                  |       |       | 1,689.00         |
| + Margin on L,N Items 10.00% (\$) |     |          |                                                  |       |       | 133.20           |
| Total Parts (\$)                  |     |          |                                                  |       |       | 1,822.20         |

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.  
Generated using Merimen e-Claims IEAS

Steve (LKK)  
4/8/22, 3:22pm