



樹發汽車修理廠
SHU FATT AUTO WORKS

BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065
Co. Reg. No. 09062400M GST Reg. No. 09-062400-M

(SUPPLEMENTARY)

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	WSK/JW/SF-SMF9862
Policy No:	SP2000035725	Date of Loss:	05/07/2022
Vehicle Reg. No.:	SMF9862J	Driveable?	
Driver Age/Info:	64 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	WOO CHEE WAI	Contact No:	+6596646608
Driver:	WEE CHEE WAI		

Make/Model:	SUBARU FORESTER, 2.0 I-L CVT AWD SR (A)	Vehicle Reg. Date:	30/11/2018
Vehicle Colour:	Brown		
Engine No:	FB20YE45561	Chassis No:	JF1SJ5KC5JG112420
Odometer:	43097 KM		

Paint Type:

Total Loss? **NO**

Est. Duration of Repair (day) 20

Remarks: STEVE SURVEYED ON 11 AUGUST 2022.

Present Location: SHU FATT AUTO WORKS (HQ)

COST OF CLAIMS

Parts	1,373.00
Miscellaneous Items	0.00
Labour	150.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	1,523.00
+ GST 7.00% (S\$)	106.61
Nett Amount (S\$)	1,629.61
+ Previous Estimates (S\$)	22,116.47
Claim Total (S\$)	23,746.08

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 Aug 2022)

Parts: M1-SUV SUBARU FORESTER 2.0 I-L CVT AWD SR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Shu Fatt Auto Works/SMF9862J/15/08/2022 11:21

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front windscreen CRA (hit by gemstone is accessories hanging in the car)	0.00	0.00	*1,050.00 F ✓
2	1		*Front windscreen moulding NEC	0.00	0.00	*100.00 F ✓
3	1		*Front windscreen sealant NEC	0	0.00	Nett *42.00 FS ✓
4	1		*Front windscreen inner seal NEC	0	0.00	Nett *40.00 FS ✓
5	1		*Front windscreen ERP holder NEC	0	0.00	Nett *26.00 FS ✓

F=Franchise part. S=SpcNett.

Sub Total (\$\$) **1,258.00**
+ Margin on L,N Items 10.00% (\$\$) **115.00**

Total Parts (\$\$) **1,373.00**

Shu Fatt Auto Works/SMF9862J/15/08/2022 11:21. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Steve (LKK)
 15/08/22

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	To remove, replace front windscreen.	New	100 ✓ 150.00
Gross Labour Cost (\$\$)			150.00

Shu Fatt Auto Works/SMF9862J/15/08/2022 11:21. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >