

J.E.W Motor Pte Ltd

ADDRESS: 60 JALAN LAM HUAT #03-72, CARROS CENTRE SINGAPORE 737869

VEHICLE NUMBER: SMD1762C

THIRD PARTY CLAIM

MAKE & MODEL: Toyota Corolla Altis

REPAIR ESTIMATE

CHASSIS NUMBER: MR052ZEE106124635

QTY	PARTS PARTICULARS	CONIDTION	AMOUNT S\$
1	Bootlid 839.40	\$	839.90 <i>bt</i>
1	Bootlid "1.6" emblem	\$	45.80 <i>nei</i>
1	Bootlid centre emblem	\$	45.89 <i>nei</i>
1	Bootlid "Corolla" emblem	\$	66.40 <i>ue</i>
1	Bootlid "Altis" emblem	\$	55.20 <i>nei</i>
1	Bootlid "LX" emblem	\$	39.80 <i>ue</i>
1	Bootlid lock	\$	134.50 <i>x nn</i>
1	Bootlid lock catch	\$	45.00 <i>x nn</i>
1	Bootlid RH lamp 228.90	\$	255.55 <i>cut</i>
1set	Bootlid inner trim clips	\$	45.00 <i>x nn</i>
1	Bootlid weatherstrip	\$	198.50 <i>aut</i>
1	Rear bumper 571.20	\$	548.90 <i>de</i>
1set	Rear bumper clips	\$	70.00 <i>zone</i>
1	Rear bumper RH reflector	\$	55.30 <i>as</i>
1	Rear bumper RH side retainer (long)	\$	67.80 <i>de</i>
1	Rear bumper RH side retainer (small)	\$	46.97 <i>de</i>
1	Rear bumper LH side retainer (long)	\$	67.80 <i>x nn</i>
1	Rear bumper LH side retainer (small)	\$	46.97 <i>x nn</i>
1	Rear bumper inner sponge	\$	178.90 <i>asa</i>
1	Rear bumper RH bracket	\$	97.90 <i>x nn</i>
1	End panel 681.90	\$	590.70 <i>bt</i>
1	End panel garnish	\$	202.80 <i>de</i>
1set	End panel garnish clips	\$	60.00 <i>zone</i>
1	RH taillamp assy 410.95	\$	455.67 <i>asa</i>
1set	RH taillamp lock clips	\$	28.00 <i>nei</i>
1	RH taillamp gasket	\$	23.00 <i>x nn</i>
1	RH taillamp lower bracket	\$	55.94 <i>de</i>
1	RH taillamp panel	\$	178.93 <i>buc</i>
1	Rear windscreen glass rubber moulding	\$	78.40 <i>ue</i>

1	Rear RH fender	1082.25	\$	1,086.90	buc
1	Rear RH fender inner trim		\$	332.45	X
1set	Rear RH fender inner trim clips		\$	50.00	X
1	Rear RH fender splash shield		\$	71.20	X
1set	Rear RH fender splash shield clips		\$	35.00	X
1	Spare tyre panel top board		\$	278.40	X
1	Exhaust silencer		\$	723.10	X
1	Exhaust silencer gasket		\$	55.00	X
1	Rear RH wheel bearing		\$	425.70	X
1	Rear RH shock absorber		\$	211.20	X
1	Rear axle beam		\$	1,284.30	X
1	Rear RH door		\$	1,321.00	X
1	Rear RH door protector		\$	83.22	X
1	Rear RH door protector chrome insert		\$	32.80	X
			\$	10,615.79	
			25% \$	2,653.95	
			\$	7,961.84	

QTY	PARTS PARTICULARS	CONDITION	SPECIAL NETT AMOUNT	
				S\$
1	Rear windscreen glass sealant		\$	80.00 6000 ✓
1	Rear windscreen glass inner seal		\$	50.00 nei ✓
1	RH taillamp panel seal		\$	40.00 2000 ✓
1	End panel seal		\$	70.00 3000 ✓
1	Rear RH fender seal		\$	75.00 3000 ✓
1	Rear reverse sensor		\$	450.00 x nm
1	Rear RH door edge rubber protector		\$	180.00 x nm
1	Rear RH sport rim		\$	1,200.00 x nm
1	Rear RH tyre		\$	550.00 x nm

LABOUR/ PAINTING AND ETC		AMOUNT \$S	
		\$	1,800.00 800
1	Labour charges	\$	1,500.00 800
2	Spray painting	\$	120.00 3000
3	Check wiring and lightng system		

4	Apply rust coating on affected areas	\$	150.00 30
5	To remove and refit rear windscreen glass to carry repair	\$	250.00 120
6	To remove and replace rear inner trims, roof lining, seat and board to carry repair	\$	400.00 60
7	To remove and replace rear reverse sensors to carry repair	\$	100.00 30
8	To do wheel alignment system	\$	100.00 X nn
9	To remove and replace rear undercarriage parts to carry repair	\$	550.00 X nn
10	To remove and refit rear RH door inner parts to new door	\$	120.00 X nn
11	To balance rear RH sport rim with tyre	\$	50.00 X nn

FINAL AMOUNT S\$: \$ 15,796.84

Tanfu 97495749

wp' 18/7/22 @ 5:15pm

c/s Resurvey after repair

tanfu @ lkhauto.com

07 days

LS \$4700

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: