

ELITE AUTOMOTIVE PTE LTD

280 Woodlands Industrial Park E5, #01-17,

Harvest @ Woodlands Singapore 757322

Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SMX6618Z

Vehicle Model : MERCEDES GB200

Chassis Number : W1N2476872W050017

Estimated Repair Cost

S/N	Parts Description	Qty	List Price
1	FRONT LHS DOOR	1	\$ 1964.82
2	REAR LHS DOOR	1	\$ 2844.63
3	REAR LHS DOOR OUTER HANDLE	1	\$ 142.92
4	REAR LHS DOOR LOWER CHROME MOULDING	1	\$ 55.61
5	REAR LHS DOOR INNER TRIM BOARD	1	\$ 1081.98
6	REAR LHS DOOR INNER TRIM BOARD CLIPS	10	\$ 80.00
7	REAR LHS DOOR HINGES	2	\$ 187.16
8	REAR LHS DOOR WEATHERSTRIP	1	\$ 317.05
9	REAR LHS DOOR WHEEL ARCH	1	\$ 220.42
10	REAR LHS DOOR WHEEL ARCH CLIPS	10	\$ 80.00
11	REAR LHS DOOR WINDOW OUTER CHROME MOULDING	1	\$ 242.80
12	REAR LHS DOOR POWER WINDOW MOTOR	1	\$ 491.45
13	REAR LHS DOOR REGULATOR	1	\$ 976.05
14	REAR LHS DOOR SOUND PROOFING	1	\$ 80.00
			\$ 8764.89
Discount Less 10%			
List Prices Total			\$ 876.48
			7,888.41

ELITE AUTOMOTIVE PTE LTD

280 Woodlands Industrial Park E5, #01-17,

Harvest @ Woodlands Singapore 757322

Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SMX6618Z

Vehicle Model : MERCEDES GB200

Chassis Number : W1N2476872W050017

S/N	Labour Descriptions	Charges	
1	LABOUR CHARGES TO REMOVE & INSTALL LHS FRONT & REAR END ATTACHMENTS & FITTINGS TO ENABLE REPAIRS; TO REPLACE DAMAGED PARTS AS LISTED ABOVE.	\$	1200.00
2	TO SPRAY PAINTING ON: FRONT LHS DOOR, REAR LHS DOOR, REAR LHS FENDER.	\$	1200.00
3	TO CHECK DIAGNOSE & REMOVE FAULT CODES AFTER ACCIDENT REPAIRS.	\$	280.00
4	TO REMOVE & TRANSFER LHS FRONT & REAR DOOR TRIM BOARD, DOOR SCREEN, POWER WINDOW & ELECTRICAL WIRINGS & SERVICEABLE FITTINGS TO NEW DOOR & TEST FUNCTION.	\$	500.00

Labour Total \$ 3180.00

Parts & Labour Total \$ 11068.41